



MEMORANDUM FOR RECORD

Heidi Kemner
Air Safety Investigator
Eastern Region Aviation

Subject: ERA17FA190 – Electronic Engine Control Units

The Electronic Engine Control Units from the left and right engine were sent off to UTC Aerospace Systems in Windsor Locks, Connecticut. The units were examined July 24, 2018.

Unit 1 – Testing was not possible due to the condition of the unit. An attempt was made at retrieving the nonvolatile memory data from the memory chip via a Data I/O device. However, the memory chip would not communicate with the Data I/O device. No NVM data was retrieved.

Unit 2 – Testing was not possible due to the condition of the unit. Because of the missing pins on the memory chip, data retrieval was not possible.