

Liedler Courtney

From: McAtee Nancy
Sent: Monday, March 02, 2015 8:21 AM
To: Liedler Courtney
Cc: Budinski Michael
Subject: CEN14FA467 Email report (Annunciator Panel)

Courtney,

The annunciator panel from this accident aircraft was examined for the presence of any stretched light bulb filaments. Each annunciator light was x-rayed to determine the status of the two bulb inside. No stretched filaments were found in any of the annunciator lights.

If you have any questions or need anything else, please let me know

Nancy McAtee
Chemist
RE-30