AIRCRAFT





ENGINEERING RECORD

INSPECTION, REPAIRS & REPLACEMENT ENTRIES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.	SIGNATURE	LICENCE NUMBER
Aircraft: N419FP Tach: 4347.9 Date:12/15/2015 TTAF: 4347.9 Installed new bonding strap & terminal ends on flap motor, installed new seal trim on intake, installed new run/leak check, operational check good. All work done in accordance with Diamond Main aircraft has been inspected in accordance with a 100 Hour inspection and determined to be airwort. David Hicks A&P	tenance Manual. I certify the	er kit.
12/30/2015 COMPLIED WITH FAR 91.207(D) WEXT DUE 12	116	
INSTALLED NEW BATTERIES IN PLMOTS, SWITCHE	4	
primer nozzles pressure tested oil cooler to 250 psi new oil filter bypass valve seat an o-rings new oil drain valve new throttle, mixture and carbheat control cables new incomplete firewall fwd Aeroduct hoses new left brake pads and disc new mixture return spring run leak ops good. All work completed in accordance with Diamond maintenance mainspected in accordance with an Annual inspection and determined airworthy this date. AP	duction air filter lubed runew hobbs oil pressure sunual. I certify this aircra	dder pedals ne witch I Ground
Aircraft: N419FP Tach:4500.5 Date: 3/30/16 TTAF:4500.5 Installed new Garmin fuses, next due 3/2018. Installed new standby battery, next due 3/2018. Installed new ELT battery and complied with FAR91.207D, next due 1/2021. Ground run/leak work done in accordance with Diamond Maintenance Manual. I certify this aircraft has been installed new inspection and determined airworthy this date.	abaals assessing 1 1 1	4 4 4 4
Aircraft: 419FP Tach: 4599.9 Date: 5/16/16 TTAF: 4599.9 Installed new induction air filter new upper rudder mount bearing new pilot rudder adjust ca mount bushings and repaired vertical lower control rod ground strap repaired carb heat air be cracks new left brake pads Ground run leak ops good. All work completed in accordance with certify this aircraft has been inspected in accordance with an Annual inspection and determine the control of the contro	ox aft mounts by weldin	44

AIR TIME AND

Aircraft: N419FP

Tach:4699.3

6/23/16 Date:

TTAF:4699.3

Installed new induction filter. Re-attached bonding strap on rudder. Installed new bonding strap on LH flap bellcrank. Installed new bonding strap on LH aileron bellcrank. Installed new rudder pedal adjustment cable on RH pedal assy. Ground run/leak check, operational check good. All work done in accordance with Diamond Maintenance Manual. I certify this aircraft has been inspected in accordance with a 100 Hour inspection and determined airworthy this date.

Kevin Landgren A&P CARRIED FORWARD