LIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Recility. (See back pages for other specific entries.)
	engine acc MSB-533B, Lycoming Magnaflux sump with Engine Serv guides, grin ground & i repaired co inspected ar	2013, Tach Time 3399.87 ETT 5298.53 TSMOH 0.0 Disassembled ordance with AD 04-10-14C1 and Lycoming. Service Instructions SAIB-NE-06-32R1, SB-475C cleaned and inspected. Using Direct Drive Engine Overhaul Manual P# 60294-7 R 7-10D. all steel parts. Check oil pump. Divco recondition crankcase, oil induction tubes, accessory case and vernatherm seat. Harrison vices recondition Cylinders replacing exhaust valves, exhaust d seats, & hone for ring finish. Aircraft Specialties services reinitiated, 0.006U Per Lycoming Service Instruction #1111, bunterweights per Lycoming Service instruction #1143-B. ad/or repaired per Lycoming S.B. 475C excluding paragraph 6 unterweight blade.

Description of Inspections, Tests, Repairs and Alterations

ODAY'S

TOTAL

Flight Standards Service Organizational Online

