

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Research and Engineering
Materials Laboratory Division
Washington, D.C. 20594



May 5, 2011

FIRE FACTUAL REPORT ERRATA

Report No. 11-002

A. ACCIDENT INFORMATION

Date of Accident: September 9, 2010
Time of Accident: 6:11 pm (PDT)
Location: San Bruno, California
NTSB No.: DCA10MP008
Vehicle: Natural gas transmission pipeline

B. ERRATA

1. On Page 3, Line 13, the sentence that reads:

“The crater, prior to excavation, was approximately 59 feet (north to south) by 26 feet (east to west).”

Should read:

“The crater, prior to excavation, was approximately 72 feet (north to south) by 26 feet (east to west).”

2. On Page 5, Lines 1-3 the sentence that reads:

“Damage to the surrounding houses, vehicles and land extended approximately 600 feet from the blast center with most of the damage radiating out in a northwest direction away from the center of the crater.”

Should read:

“Damage to the surrounding houses, vehicles and land extended approximately 600 feet from the blast center with most of the damage radiating out in a northeast direction away from the center of the crater.”

3. On Page 5, Line 10, change “46 sustained minor damage” to “53 sustained minor damage.”

4. The following addresses should be added to the "Minor Damaged" section starting on Page 9.
 1. 120 Daley Ct.; Replace fire damaged roof.
 2. 250 Estates Dr.; Replace fire damaged roof, skylight, windows, and patio doors.
 3. 1285 Claremont Dr.; Replace fire damaged windows.
 4. 2761 Plymouth Way; Repair fire damaged chimney
 5. 1127 Vermont Way; Replace fire damaged roof and gutters.
 6. 2721 Concord Way; Replace fire damaged windows, window framing and stucco.
 7. 1770 Claremont Dr; Replace fire damaged windows

Nancy B. McAtee
Fire and Explosion Specialist