

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility (See back pages for other specific entries.)
				replacement by 12/2015. Installed replacement horizontal oil pressure sender. Run-up and leak check OK. [REDACTED] [REDACTED]
21 JUN 2015				
21 JUN 2015	74.7 hours		74.7	Flushed & refilled coolant system. Replaced NGK-DCPR8E spark plugs & Annual Inspection. I certify this aircraft has been inspected I.A.W. manufacturer's maintenance & inspection procedures and was found to be in condition for safe operation. Inspection was performed @ (OI-NC) after issuance of ferry permit from (OAS) on 19 JUN 2015 by Tim Hakey. Run-up and leak check okay. Thomas Dawson LSRM-A# [REDACTED] [REDACTED]