

**Aircraft Record** General Information

Manufacturer Piper Pawnee Model PA-25-235  
Serial 25-8156005 Registration Number N-90866

Date of Manufacture \_\_\_\_\_

Engine(s) currently installed:

Manufacturer Lycoming Model O-540-B2C5 Serial RL-23067-40A  
Serial L-23067-40A

Manufacturer Lycoming Model \_\_\_\_\_ Serial \_\_\_\_\_

Propeller(s) currently installed:

Manufacturer McCully Model 1A200/FA845Z Serial \_\_\_\_\_

UB Model \_\_\_\_\_ Serial \_\_\_\_\_ Serial \_\_\_\_\_

Side Model \_\_\_\_\_ Serial \_\_\_\_\_ Serial \_\_\_\_\_

Side Model \_\_\_\_\_ Serial \_\_\_\_\_ Serial \_\_\_\_\_

ENGINE  
ICE

YEAR:	TOTAL TIME IN SERVICE	Equipment Addition, Removal or Exchange	
DATE		Item	Manufacturer's Name
FEB 2, 2017	8265.4		

Recovered fuselage, horizontal stabilizers, elevators and rudder - See 337 dated 02/02/2017. Painted all cowlings, canopy and fairings. Rejuvenated and repainted wings. Installed new 1250HD bungee chords and painted shock absorbers. Installed new bolts in shock absorbers. Fabricated and installed new right seat belt cable. Installed new bushings for landing gear attach bolts where needed and installed new gear bolts. Installed new fuel quick drain in left wing tank. Installed new tires on mains - Airhawk 8.00X6 6 ply. Installed new jettison cables on both doors. Welded crack in fuel header tank, tested, painted and reinstalled. Repaired frame for winch access door. Welded new brace wires inside elevators, primed and painted. C/W AD 95-12-01 by dye penetrant inspecting IAW STC SA01073AT, attachment A, Paragraph F. Next due in Feb. 2023. C/W AD 2007-08-07 Horizontal stab. Supports IAW SB 25/53/03. C/W AD 77-21-06 Rear wing attach tubing cluster IAW SB 551A. AD 2015/08/04 Wing lift struts PCW. Ads checked through 2017-02.

**AIRCRAFT**

I certify that this engine has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

George F. Taylor

*[Signature]*

6A

# ENGINE MAINTENANCE RECORDS

Log No. \_\_\_\_\_

Aircraft Registration No. N90866Engine Manufacturer LYCOMINGModel O540-B2C5Serial No. RL-2306740ADate installed on aircraft 2-22-2015

Time Between Overhauls (TBO) \_\_\_\_\_ Hours

If used on multi-engine aircraft:

- |                                |                               |
|--------------------------------|-------------------------------|
| <input type="checkbox"/> Right | <input type="checkbox"/> Left |
| <input type="checkbox"/> Front | <input type="checkbox"/> Rear |

