DATE	AIRFRAME TIME IN SERVICE		d Aviation		i, inc. FO Box 1720 Alberrari Bair Striffon No. ZAG 183M	e, 190 (80 <del>0)</del> 2 =	
		Date: 03-02-2020			4005.5 Hobbs Time: N/A	_	
		Make PIPER	<b>Model</b> PA-23-250	<b>Serial No</b> 27-3017	Reg. No N335W	-	
		AIRCRAFT TOT LEFT ENGINE LEFT ENGINE RIGHT ENGINE RIGHT ENGINE RIGHT PROP T 16-2020 LEFT PROP TT 2020. HEATER HM =	TT LOG BOOK ENTRY N335W  TT TOTAL TIME IN SERVICE				
		ANNUAL INSPE 250 AMM. REM COVERS, INTE COMPARTMEM LUBED PULLE CLEANED ANI BRAKE DISC. BRAKE RESO WITH A SERVI AND PITTED OF FILTER. PERI EXTENSION V MULE AND EM BOTTLE AND TOP SERVICE BOTH NOSE V REMOVED BA BATTERY PAS BATTERY BO ACID PROOF DRAIN AND V NUMERIOUS A CLAMPS MISS INDICATION F FIREWALL. P LINE. CAW AD AND RIGHT E 21-07R1 FUEL AND NO OBS BY INSPECTIC AD APPLIES O	CABLES. WHEELS GS AND ERVICED UATOR JAS RUSTY ITH NEW JCY RALILIC DWN CO2 KAGE. EPLACED 3-000. AND DO WITH JCED TO RESSURE NES TO T FLEX ON LEFT JW AD 88- ARE OPEN JD 68-07-04 UND. THIS	Pa 1 of 2			
						OVER	
		,					
							44.

STYLE MOUNT. MOUNT AD RECURRING DUE 100HRS / ANNUAL AT 4127.5 OR 3-31-2021. C/W AD 72-11-01 POSSIBLE FIRE FROM FUEL VAPORS BY INSPECTION OF FUEL CELLS FOR LEAKAGE AND NO LEAKAGE FOUND FROM INTERIOR INSPECTION OF WINGS AND UNDER FLOORS IN FUSELAGE, AD RECURRING DUE 50 HOURS @ 4077.5 LE TACH. C/W AD 72-14-05 100 HOUR INSPECTION OF LEFT AND RIGHT ENGINE EXHAUST SYSTEMS. REPLACED RIGHT ENGINE AFT EXHAUST STACK HANGAR BRACKET WITH A SERVICABLE BRACKET. NO OTHER DISCREPANCIES FOUND. AD RECURRING DUE @ 4127.5. REPLACED SCAT DUCTS BETWEEN FILTER HOUSINGS AND INJECTOR SERVO AIR BOX, P/N 05-29916. C/W AD 2009-13-06R1 100 HOUR NOSE BAGGAGE DOOR LUBE AND LATCH INSPECTION AND NO DISCREPANCIES FOUND. 1000 HOUR HARDWARE CHANGE DUE @ 4837.7 A/C TT. CLEANED FUEL SCREENS AND DRAINED FUEL FROM ALL TANK SUMPS. CHECKED REGUIRED PLACARDS LISTED IN POH. CHECKED FOR COMPLIANCE OF AD 2015-24-05 PER SB 1266 AND CORRECT PLACARDS ARE IN POH AND ON INSTRUMENT PANEL, PREVIOUS C/W. REPLACED MISC STRIPPED NUT PLATES AND RIVNUTS THAT HELD AFT TOP COWLINGS, NACELLE FAIRINGS ETC. REINSTALLED PLATES COVERS AND FAIRINGS. ADJUSTED CABIN HEAT VALVE CABLE UNDER AFT SEATS TO OBTAIN FULL TRAVEL, LUBED VALVE POINTS. REPLACED NOSE DOOR OPEN SPRING WITH SERVICABLE SPRING AND NEW HARDWARE. RECHECKED NOSE GEAR DOOR ADJUSTMENTS BEFORE AIRCRAFT DOWN JACKED. C/W AD 88-21-07 R1 FUEL SYSTEM 100 HR INSPECTION PER SB 340 PART B AND SB 507 TO CHECK SWIVELS AND TRAVEL OF FUEL SELECTOR VALVE TRAVELS. LUBED CABLES AND SWIVELS WERE FREE AND VALVES TRAVELED STOPS TO STOPS. AD RECURRING DUE 100 HRS AT 4127.5 REMOVED ELT AND FUNCTIONAL TESTED ELT PER 91.207(d) AND NO ELT DISCREPANCIES FOUND. ELT BATTERY DUE REPLACEMENT ON OR BEFORE APRIL 30, 2022. REPLACED CRACKED T FITTING UNDER HEATER FUEL SELECTOR VALVE AND REPLACED O RING IN CROSSFEED SUMP DRAIN VALVE AND OPERATIONAL CHECKED AND NO DISCREPANCIES FOUND. INSPECTED HEATER SHUT OFF VALVE AND FUEL REGULATOR VALVE AND NO FUEL LEAKS OR EVIDENCE OF FUEL LEAKS FOUND. GROUND OPERATIONAL CHECKED HEATER AND OPERATED HEATER THRU SEVERAL CYCLES AND HEATER OPERATIONS WERE NORMAL. REINSTALLED INTERIOR FLOOR PANELS, CARPETS, SEATS ETC. VACUUMED INTERIOR CARPETS. WASHED EXTERIOR AND LUBED EXTERIOR HINGES. CHECKED ALL EXTERIOR AND INTERIOR LIGHTS. AD COMPLIANCE REVIEWED THRU ISSUE 2-15-2020. I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND THE AIRCRAFT IS APPROVED FOR RETURN TO SERVICE THIS DATE. PERTINENT DETAILS OF THE INSPECTION AND MAINTENANCE COMPLETED ARE ON FILE AT THIS REPAIR STATION UNDER WO 4434R-A DATED 3-02-2020. \*\*\*END\*\*\*

Signed:
For: Inglewood Aviation Maintenance Services, Inc.
\*CRS ZA4R693M Date: 3 - 02 - 2020

Paz of Z

DATE	TIME IN SERVICE	Inglewood Maintenance	l Aviation Services, Inc.	inglewood Aviation F.A.A. Cartified to	i, înc. 110 desi 1730 Albemade, NO 20002 - male Christian Me. II246 (CSSM)	
	021,4102	Date: 03-02-2020		Tach: LE 4027.5	Hobbs Time: N/A	
		Make LYCOMING	Model IO-540-C4B5	<b>Serial No</b> L-2347-48	Reg. No N335W	
		LEFT ENGINE LEFT ENGINE	LOG BOOK ENT TOTAL TIME IN : TOTAL TIME SM	SERVICE	= 4027.5 = 273.6	
		100 HOUR / AN COMPRESSIO 70/8, #2 74/80, PLUGS WITH NIGNITION LEAR CHANGED OIL FILTER AND IN NONE WAS FO AVIATION LAB BRACKETT BA COVER MOUN CLAMPS. C/W INSPECTION FC/W AD 72-14-WASHED ENG NO LEAKS FOI ADJUSTMENT THRU ISSUE 2 ACCORDANCE RETURN TO SI MAINTENANCE 4434R-A DATE Signed:	INUAL INSPECT N TEST PERFOR #3 74/80, #4 74/8 IEW UREM40E S DS. CLEANED F AND FILTER. C ISPECTED FOR DUND. OIL SAMF ORATORIES. SI 110 OIL FILTER115 FILTER ELE T SCREWS AND WITH AD 2015- PER LYCOMING S DE ENGINE EXH, INE AND GROUN JND ON A POST TO IDLE SPEED -15-2020. I CER E WITH A ANNUA ERVICE THIS DA	ION COMPLETED THEMED. CYLINDER COORD. CYLINDER COORD. WE TO THE STATE OF THE STATE	IN DATE. ENGINE CYLINDER OMPRESSIONS ARE: CYL #1 D. REPLACED ALL SPARK ECKED IGNITION TIMING AND IDRAINED FUEL TANK SUMPS. ENS AND CUT OPEN OLD OIL AL OR EXCESS CARBON AND ILED FOR PROCESSING BY ITH 12 QTS AEROSHELL W100 I BRACKETT AIR FILTER, TORQUE ON ALL ROCKER I'URN CONNECTOR HOSE I'EL INJECTOR LINES BY SCREPANCIES FOUND. NO DISCREPANCIES FOUND. REFORMANCE WAS NORMAL AND ECTION. MADE MINOR E. AD COMPLIANCE REVIEWED GINE HAS BEEN INSPECTED IN I'THE ENGINE IS APPROVED FOR ETAILS OF THE INSPECTION AND REPAIR STATION UNDER WO	
			<u>,</u>			
					•	
		SUB-	TOTALS this pa	ae		
				ard to next page		

	TIME IN SERVICE	Inglewood Maintenance	d Aviation e Services, Inc.		, Inc. PO Box 1720 Albemarle, NC 28002 pair Station No ZA4R693M	
		Date: 03-02-2020		Tach: RE 4027.5	Hobbs Time: N/A	
		Make LYCOMING	Model 10-540-C4B5	Serial No L-2374-48	Reg. No N335W	
		RIGHT ENGI	NE LOG BOOK ENT NE TOTAL TIME IN NE TOTAL TIME SM	SERVICE	= 4027.5 = 273.6	
		PLUGS WITH IGNITION LE CHANGED O FILTER AND NONE WAS I AVIATION LA OIL AND CHA BRACKETT E COVER MOU CLAMPS. C/ INSPECTION C/W AD 72-1 WASHED EN AND NO LEA ADJUSTMEN THRU ISSUE ACCORDANI RETURN TO MAINTENAN 4434R-A DAT Signed For: Inglewore	I NEW UREM40E SI ADS. CLEANED FU INSPECTED FOR E FOUND. OIL SAMPI BORATORIES. SE 48110 OIL FILTER. BA-115 FILTER ELEI JINT SCREWS AND W WITH AD 2015-19 I PER LYCOMING S 4-05 ENGINE EXHA IGINE AND GROUN JIKS FOUND ON A P JIT TO IDLE SPEED JIT TO JIT SERVICE THIS DAT	PARK PLUGS. CHE JEL SCREENS AND JEANED OIL SCREE VIDENCE OF META LE TAKEN AND MAI REVICED ENGINE W INSTALLED A NEW MENT. CHECKED 1 CYLINDER OIL RET P-07 LYCOMING FU B 342G AND NO DI UST SYSTEM AND D RUN UP. ENGINE OST ENGINE RUN I AND IDLE MIXTURE IFY THAT THIS ENG L INSPECTION AND TE. PERTINENT DE ON FILE AT THIS F IND***  E SENCES, Inc.	D. REPLACED ALL SPARK CKED IGNITION TIMING AND DRAINED FUEL TANK SUMPS. ENS AND CUT OPEN OLD OIL AL OR EXCESS CARBON AND ILED FOR PROCESSING BY ITH 12 QTS AEROSHELL W100 BRACKETT AIR FILTER, FORQUE ON ALL ROCKER FURN CONNECTOR HOSE EL INJECTOR LINES BY SCREPANCIES FOUND. NO DISCREPANCIES FOUND. E PERFORMANCE WAS NORMAL INSPECTION. MADE MINOR E. AD COMPLIANCE REVIEWED GINE HAS BEEN INSPECTED IN THE ENGINE IS APPROVED FOR ETAILS OF THE INSPECTION AND REPAIR STATION UNDER WO	
	brs.				· · · · · · · · · · · · · · · · · · ·	
. ,					· · · · · · · · · · · · · · · · · · ·	
-					,	
,				`		

Date	Total Propeller Time	Time Since Overhaul	Description of Work		Authorized Signatures
	Ingl	ewood Aviation tenance Services, Inc.		on and once they Albertain, No In Citylen the United States	1994°,
	Date: 3-0	02-2020	Tach: LE=4027.5, RE=4005.5 Hobbs Time: N/A		
	Make HART	Model HC-E2YR- 2RBFS/F8465-7F			-
	PROF	PROPELLER LOG BOOK PELLER TT= 4027.5, PROF 16-2020.		2.1 AND 16 CALENDAR YF	es
	REIN GRO PROI THAT ANNU DATE	STALLED SPINNER AND I UND RUN OF ENGINES. ( PELLER. AD COMPLIANC THIS PROPELLER HAS E JAL INSPECTION AND WA E. PERTINENT DETAILS O PLETED IS ON FILE AT TH 120. ***END*** Signed	NO LEAKS OR DISCRI COMPLETED GOVERI E REVIEWED THRU IS BEEN INSPECTED IN A AS APPROVED FOR R OF THE INSPECTION A HIS REPAIR STATION	ETURN TO SERVICE THIS IND MAINTENANCE UNDER 4434R-A DATED 0 Secures, Inc.	G OF Y
		1	1	1	

## **SERVICE HISTORY**

Date	Total Propeller Time	Time Since Overhaul	Description of Work		Authorized Signatures
	Maint	ewood Aviation tenance Services, Inc.	P.A.Carilla Had	ine, PO For 1729 Albemaño, i di Sadion H., 1744 0006	h(1964 as -
	Date: 3-0	Model HC-E2VP	Tach: LE=4027.5, RE=40 Serial No 4955	Reg. No N335W	
	PROI	IT PROPELLER LOG BOOP PELLER TT= 4027.5, PROP -16-2020.	YRS		
,	REM MM V BLAE REIN GRO PRO	PLETED A ANNUAL INSPE OVED SPINNER AND INSP MITH AEROSHELL #6. DR DES. SERVICED ACCUMU ISTALLED SPINNER AND I UND RUN OF ENGINES. ( PELLER. AD COMPLIANC	PECTED HUB AND BI ESSED SMALL NICK ILATOR WITH NITRO NO LEAKS OR DISCR COMPLETED GOVER E REVIEWED THRU	ADES. LUBED PROPS P S AND PRIMED AND PAIN GEN TO SPEC / TEMP CH REPANCIES FOUND DURI NOR AND CYCLE CHECK ISSUE 2-15-2020. I CERT	ER ITED HART. NG (S OF
•	ANNI DATE COM	T THIS PROPELLER HAS EVAL INSPECTION AND WAS PERTINENT DETAILS OF PLETED IS ON FILE AT THE COLUMN SIGNED STATE OF THE PROPERTY	AS APPROVED FOR I	RETURN TO SERVICE TH AND MAINTENANCE I UNDER 4434R-A DATED	
		*CRS ZA4F		2-2020	