

Inspections, Tests, Repairs and Alterations
 performed with Name, Rating and Certificate Number of
 Repair Facility. (See back pages for other specific entries.)

| | | |
|------------|--|-------------------------------------|
| Model: | Aircraft S/N: 602-1192 | Acraft. Reg. No: N-6007N |
| Propeller: | Model; Ser. Hartz. HC-B5MP-3C EVA 3070 | Propeller TSMOH / TT T.T. 1621.2 |

Replaced all rudder and elevator hinge bearings and bolts.
 Replaced tail wheel bearings and races. Replaced tail gear
 walk as needed. Cleaned and painted horizontal stabilizer
 sealed floor board to hopper. Cleaned and painted aft fuselage
 horizontal stab. eyebolts as per S/L 129 and AD 2005-13-12.
 Tightened fuel tank access plates on r/h wing.

Visual inspection and was determined to be in an airworthy

| YEAR 20 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|--------------------|---------------------------|-------------------|-----------------------------|---|
|--------------------|---------------------------|-------------------|-----------------------------|---|

FROST FLYING MAINTENANCE, INC.
 Marianna, AR 72360 Phone: [REDACTED]

Date: 12/12/14 **N#** N6007N **Hobbs:** 2195.6
Model: AT602 **S/N#** 602-1192 **TTAF:** 2195.6
 C-W ANNUAL INSPECTION I-A-W FAR 43app D & THE AT602 M-M p/n 10017-OM AS A GUIDE. REMOVE ALL
 INSPECTION PANELS. REPLACE & PACK ALL WHEEL BEARINGS . INSTALLED NEW p/n B100-06 FLAP
 TRANSMISSION DRIVE COUPLER. REMOVE TAIL GEAR ASSY. PREP -PAINT& REINSTALL WITH ALL
 NEW HARDWARE. INSTALLED ALL NEW ELEVATOR & RUDDER BEARINGS WITH NEW
 BEARINGS p/n14104-4 & REINSTALLED WITH NEW HARDWAR. LUBED & SERVICED AIRCRAFT &
 RE INSTALLED ALL INSPECTION PANELS. C-W AD2009-11-05 BY INSPECTION PER S-L 253 Rev;C. NO
 CRACKS NOTED AT THIS TIME. NEXT DUE HOBBS TIME 2295.6. INSTALLED NEW TAIL NAV LIGHT
 ASSY. C-W 1000HR AFT WING BOLT REPLACEMENT.NEXT DUE HOBBS TIME 3195.6
 C-W AD2005-13-12 BY INSPECTING I-A-W SL#129A & FOUND OK FOR SERVICE NEXT DUE 12/2015.
 .C-W AMSAFE RESTRANT INSPECTION I-A-W AMSAFE DOCUMENT#E509129 & FOUND OK FOR
 SERVICE. INSTALLED 2eaNEW TAX-LANDING LIGHTS& OPS CK OK. INSTALLED NEW INLET AIR
 FILTER.INSTALLED NEW WING WALK AS NEEDED. ALL WORK DONE IN ACCORDANCE WITH
 THE AT602 MAINTENANCE MANUALS AND DATA. SEE AIRWORTHINESS DIRECTIVE
 COMPLIANCE RECORD THIS DATE FOR DETAILS.

I certify this aircraft has been inspected in accordance with an Annual Inspection and is
 found to be in an airworthy condition.

Signature: [REDACTED] **PATRICK WILLIAMS** [REDACTED]

FROST FLYING MAINTENANCE, INC.

Marianna, AR 72360

Phone: [REDACTED]

Date

Date: 12-12-14

N6007N

Hobbs:2195.6

Model:HC-B5MP-3C

S/N#:EVA3070

TTIS; 2195.6

C/W 100 HOUR INSPECTION ON PROPELLER, GREASE, AND INSPECTED. INSTALLED NEW BATA BLOCK ASSY. ALL WORK DONE I/A/W WITH HARTZELL MANUAL SECTION 61-00-39 Rev.11
GROUND RUN & OPS CK. NO LEAKS NOTED AT THIS TIME.

I Certify this propeller is found to be in air worthy for work performed.

Signature:

[REDACTED]

PATRICK WILLIAMS

[REDACTED]

| | | | | |
|--|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |