



U.S. Department
of Transportation
**Federal Aviation
Administration**

Cincinnati Flight Standards District Office
4358 Ferguson Drive
Cincinnati, OH 45245
Phone: 513-842-9600
Fax: 513-842-9620

May 20, 2011


Timothy W. Monville
NTSB
8240 NW 52 Terrace, Suite 418
Doral, FL 33166

Dear Mr. Monville:

On May 13, 2011 I witnessed the teardown of the two propellers identified in the report dated May 19, 2011 submitted to you by Tom McCreary of Hartzell Propeller, Inc.

I have read the report and concur with the observations as stated by Mr. McCreary.

Sincerely,


Robert W. Craig
Aviation Safety Inspector
FAA CVG-FSDO
4358 Ferguson Drive
Cincinnati, OH 45245