

# INSPECTION REPORT

Inspector's Name Tyrrell, Raymond J.		Inspector's Signature RAYMOND J TYRRELL <small>Digitally signed by RAYMOND J TYRRELL DN: cn=US, o=U.S. Government, ou=FRA Volpe, ou=DOT Volpe, email=RAYMOND.J.TYRRELL Date: 2017.06.13 11:01:15 -0400</small>			Inspector's ID No. [REDACTED]	Report No. 53	Date yy mm dd 2017 06 10		
Railroad/Company Name & Address LONG ISLAND RAIL ROAD Hillside Maintenance Complex [REDACTED] t NY 11423				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Brad Jenkins Title Email bjenkins@lirr.org Signature _____			
RR/Co. Code LI		Subdivision MAIN LINE							

From: City NEW YORK -QUEENS	Codes 4170	Destination City & County	Codes	From Latitude						
State NY	36	City		From Longitude						
County QUEENS	C081	County		To Latitude						
Mile Post: From	To	Inspection Point HILLDSIDE YARD		To Longitude						
Activity Code:	238	229M	223	231	MREC	238X				
Units:	12	12	12	12	1	1				
Sub Units:	0	0	0	0	12	0				

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	LI	7695	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	LI	7696	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?

Source Code C	File Number FE-2017-12	ID's of Accompanying Inspector(s)
------------------	---------------------------	-----------------------------------

# INSPECTION REPORT

(Continuation)

Inspector's ID No. <div style="background-color: black; width: 100px; height: 15px;"></div>	Report No. 53	Report Date 6/10/2017
--	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	LI	7403	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	LI	7403	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	LI	7417	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Source Code C	File Number FE-2017-12	ID's of Accompanying Inspector(s)
------------------	---------------------------	-----------------------------------

# INSPECTION REPORT

(Continuation)

Inspector's ID No. <div style="background-color: black; width: 100px; height: 15px;"></div>	Report No. 53	Report Date 6/10/2017
--	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	LI	7418	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	LI	7625	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	LI	7626	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Source Code	File Number	ID's of Accompanying Inspector(s)
C	FE-2017-12	

# INSPECTION REPORT

(Continuation)

Inspector's ID No. <div style="background-color: black; width: 100px; height: 15px;"></div>	Report No. 53	Report Date 6/10/2017
--	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	LI	7049	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	LI	7050	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	LI	7743	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Source Code	File Number	ID's of Accompanying Inspector(s)
C	FE-2017-12	

# INSPECTION REPORT

(Continuation)

Inspector's ID No. <div style="background-color: black; width: 100px; height: 15px;"></div>	Report No. 53	Report Date 6/10/2017
--	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	LI	7744	MU	238						N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 CONDUCTED MP&E INSPECTION IN ACCORDANCE WITH 49 CFR PARTS 238, 229,223 AND 231 NO EXCEPTION TAKEN ON TRAIN NUMBER 7623 EQUIPMENT THAT WAS INVOLVED IN AN EMPLOYEE FATALITY EAST OF QUEENS VILLAGE STATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	<input type="text"/>	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Source Code C	File Number FE-2017-12	ID's of Accompanying Inspector(s)
------------------	---------------------------	-----------------------------------