

INSPECTION REPORT

Inspector's Name Allen, Zach			Inspector's Signature				Inspector's ID No PII		Report No 135		Date yy mm dd 2017 09 28		
Railroad/Company Name & Address UNION PACIFIC RR CO. 5701 W Vickery Blvd Fort Worth TX 76107						R/C R	Division SYSTEM		RR/Co Representative (Receipt Acknowledged) Name Danny Torres Title General Superintendent Email PII Signature _____				
From: City ARLINGTON		Codes 0260		Destination City & County				Codes	From Latitude				
State TX		48		City					From Longitude				
County TARRANT		C439		County					To Latitude				
Mile Post: From To			Inspection Point GREAT SOUTHWEST YARD						To Longitude				
Activity Code:	2170	2180	CERT										
Units:	1	1	1										
Sub Units:	2	2	2										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	Y	0	
Description - [** Comment to Railroad/Company **] The purpose of this inspection on Union Pacific Railway at the Great Southwest yard was to ensure compliance of the 49 CFR and ROR/RSR for an accident that occurred on 9/22/2017 to the crew of the YGW51R-22.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code			Date(mm/dd/yyyy):			Comments on back?			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
2										N	N	0	2170
Description - [** Comment to Railroad/Company **] The crew proper followed the following ROR/RSR rules;6.5.1: Remote Control Movements; 35.4.3: "Pitch and Catch" Operations, 35.3.1: Operator Equipment, 35.4.1: Man-down Transmission, and 8.2: Position of Switches													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code			Date(mm/dd/yyyy):			Comments on back?			

INSPECTION REPORT

(Continuation)

Inspector's ID No PJ	Report No 135	Report Date 9/28/2017
--------------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
3										N	N	0	218O

Description - [** Comment to Railroad/Company **]
The crew members of the YGW51R-22 and the Great Southwest yard correctly followed CFR 218 Subpart F: §218.99 Shoving or pushing movements, §218.101 Leaving rolling and on-track maintenance-of-way equipment in the clear, and §218.103 Hand-operated switches, including crossover switches.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
4										N	N	0	CERT

Description - [** Comment to Railroad/Company **]
Crew members on the YGW51R-22 had current RCO certifications and found the crew members to be compliance with 49 CFR Part 240 and 242. The helpers conductor and RCO certification were valid until 7/26/2018, and the Foremans conductor and RCO certification are valid until 12/17/2019.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	-----------------------------------	--	----------------------	----------------------	-------------------	----------------------	-------------------