DEPARTMENT OF TRANSPORTATION

FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

In martiale Name						Inspector's Signature						In	antaria ID Na	D ())			Date		
Inspector's Name				In		1			pector's ID No.	Report No	• -	уу	mm	dd					
Clarke, Craig C.														9		2017	01	19	
Railroad/Company Name & Address								R/C	Divi	sion	1	RR/Co. Re	presentative (Recei	pt Acknow	ledged)			
BNSF RAILWAY COMPANY									R	POV	WDER		Name	e John Bainter					
107 West Gillette Ave.								RR/Co. Code	Subc	livision		Title	Division Engineer						
						00716					ACK HI	ILLS	Email						
Gillette WY				Y 82716															
													Signature						
From: City EDGEMONT					Codes 0850	odes 0850 Destination City &				ounty				From Latitude					
State SD					46		City SD/WY STATE LINE						9956	From Longitude					
County FALL RIVER					C04	7	County CUSTER						C033	To Latitude					
Mile Post: From 0477.00 To 0476.50						Inspection Point MAIN								To Longitude					
Activity Code: TOM				0.50															
Code:																			
Units:		1																	
Sub Units:		0																	
Item Initials/Milep		ost	Equip	ment/Track #	Type/Kind		/ Defe	ct Subr	ule		Speed	Class	Train #/Site	SI	NFR*	RCL**	# of	Activity	
1 0476.99		MT #1		#1	T 213		0139 D			3:		3	W. LEG W		J	N	Occ.*** 1	Code TOM	
				1	215				55 5		5	SWIT			1	1	10101		
Descri			FOOL			DW					п (a .	••	1.0	• • •		
INSUFFICIENT COMPRESSION IN SPRING TO HOLD WING RAIL AGAINST POINT RAIL. (snow and/or ice between the wing rail and frog point does not allow the wing rail to close creating a 3/8 inch gap)														es not					
Seal Ap	plied	Se			al Removed			Hazard	Hazard Class			U	N/NA ID						
Violation Recommended					atitude:	tude:				ongitude:									
										ue:				Longitude:					
Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Coo								ode		Date(n	nm/dd/y	ууу):			Comme	nts on ba	ck?		
Item Initials/Milepost Equipment/Track # T					21	ype/Kind 49 CFR/ Defect Subrule				Speed Class Tr			Train #/Site	ain #/Site SNFR			# of	Activity	
2						USC									Ň	N	Occ.*** 0	Code	
2														1	N	IN	0		
Description - [** Comment to Railroad/Company **] This inspection report was sent to BNSF Division Engineer John Bainter as an attachment to an email on 1-19-2017. A read receipt was requested to act as his																			
	spection rep are of accept				U	eer Joh	n Baint	er as an a	attachment	to an e	email or	1 1-19-2	2017. A read	l receipt was	s requ	uested to	act as hi	S	
Seal Applied Seal Removed										Hazard Class UN/NA ID									
Violation Recommended								IT	atitude:	٥.				Longitude:					
				Yes	✔ No								LOI	Bitude.					
	Notification t f Remedial A		is:	Required	l 🖌 Option	nal	Railroad	Action Co	ode		Date(m	nm/dd/y	ууу):			Comme	nts on ba	ck?	