



MEMORANDUM FOR THE RECORD

To: Dennis Diaz
ASI, ERA Ashburn, VA

From: Tom Little
ASI, WPR Seattle, WA

Subject: Fuel Servo examination: Precision Airmotive, Marysville, WA
Technician – Peter Neilson

Date/time: February 5, 2009 0800 – 1100

Dennis,

The following is a brief summary of the fuel servo examination conducted this morning at the facilities of Precision Airmotive, Marysville, WA:

1. External examination of components
 - no impact or thermal damage observed
 - all components intact
 - nozzles clear – no damage noted
2. Bench/flow testing
 - all parameters checked
 - no significant anomalies notes
3. Fuel nozzles (4)
 - nozzles do not appear to be Precisions
 - all nozzles flow tested
 - 3 in spec
 - 1 3/10th of a pound under spec
4. Disassembly of fuel servo and examination
 - disassembly and examination of components failed to reveal any anomalies which would have precluded normal operation of the fuel servo.

Thomas M. Little
ASI
NTSB/WPR
Seattle, WA
424 745-1960