

HIGHWAY FACTORS GROUP CHAIRMAN'S FACTUAL REPORT

Highway Attachment – CSX "Trouble Tickets" for the Main Street Grade Crossing, March 2012 – March 2017

Biloxi, Mississippi

HWY17MH010

(19 pages)

Incident Detail

From 03/01/2012 To 03/07/2017 Total Incidents 28

Status All AssetType All RootAssetType All Department Signals AssetNum 340185W

Log# 8029709 **Status Closed Entered** 03-07-2017 15:26:44 **by** Kondy, Rick **Type** Train-vehicle collision (Signals)

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762/2763
Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 15:44

Description 03/07/2017 15:26:44 by Richard Kondy Dept Signals IT+ Unknown

Updated 03/07/2017 15:27:44 **by** Richard Kondy **Dept** Signals **IT+** Train-vehicle collision (Signals) Incident Type: TRK Dispatch incident Number: 94977 Incident Date: 07-MAR-17 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: Q60607 HIT A PASSENGER BUS AT MP 000726.6 MAIN ST. BUS HAD PASSENGERS. disp protecting crossing with activation failure # 12212 . Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/07/2017 15:27:44

Updated 03/07/2017 15:31:50 **by** Richard Kondy noc mgr notified . **Dept** Signals **IT+** Train-vehicle collision (Signals)

noc mgi notillea .

Updated 03/07/2017 15:43:05 **by** Richard Kondy **Dept** Signals **IT+** Train-vehicle collision (Signals) Status changed to Dispatched for Michael Stanfill ETA of: 15:44

Updated 03/07/2017 15:45:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Train-vehicle collision (Signals)

ETA time reached Status changed to Active

Updated 03/07/2017 21:54:57 **by** John Williams **Dept** Signals **IT+** Train-vehicle collision (Signals)

Waiting on update from maintainer

Updated 03/08/2017 00:00:40 **by** Zacchaeus Wood **Dept** Signals **IT+** Train-vehicle collision (Signals)

Left msg for mtr to update.

Updated 03/08/2017 01:36:12 **by** Trent Burnham **Dept** -C and S **IT+** Train-vehicle collision (Signals)

Updated 03/08/2017 06:16:34 **by** Trent Burnham **Dept** -C and S **IT+** Train-vehicle collision (Signals) Gate Mech and foundation to be replaced on the east side. ETR 12:00 3/8.

Closed 03/10/2017 07:57:56 by Bruce McVey Dept Signals IT+ Train-vehicle collision (Signals) Incident Resolved: 03/10/2017 07:56:00 Equipment Type: Cantilever/Mast Action Taken: Repaired/Replaced cantilever/mast

Employee: Sig Mgr James

- replaced gate mech with doll arm and kight, foundation...

Did ALL OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/10/2017 07:57:56

Log# 7949382 Status Closed Entered 01-05-2017 11:04:10 by McVey, Bruce Type Train-vehicle collision (Signals)

Supv James Jr, G HReg SODiv ATSub NMIRI 0Milepost 000 726.6Block 2762/2763Section 3090-7M16Asset MAIN STAssetNum 340185WMaintainer Stanfill, M O - ETA: 11:35

Description 01/05/2017 11:04:10 **by** Bruce McVey **Dept** Signals **IT+** Unknown

Updated 01/05/2017 11:04:33 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

COPIED FROM DIRT Notification

Incident Type: TRK Dispatch incident Number: 78802 Incident Date: 05-JAN-17 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident

Description: TRAIN HIT VEHICLE AT MAIN ST MP 000726.1. GATES DAMAGED ON WEST SIDE AND LOCAL POWER COMPANY NEEDED ON SITE

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 01/05/2017 11:04:33

Updated 01/05/2017 11:05:34 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

Status changed to Dispatched for Michael Stanfill ETA of: 11:35

Updated 01/05/2017 11:06:09 by Bruce McVey Dept Signals IT+ Train-vehicle collision (Signals)

The AA is protecting the Crossing with a **Type 1 Activation Failure Message# 35609**.

Updated 01/05/2017 11:06:42 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

South bound Q619-03

Updated 01/05/2017 11:14:45 by Waltina Edwards Dept PSCC IT+

Contacted On 01-05-2017 11:11:00 Agency . Police Department Contact Name 2922 Phone 228-392-0641

Updated 01/05/2017 11:40:00 by TCIS AUTOMATION Dept Signals IT+ Train-vehicle collision (Signals)

ETA time reached Status changed to Active

Updated 01/05/2017 13:14:05 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

South bound Q619-03 still on site

Updated 01/05/2017 14:12:35 by Bruce McVey Dept Signals IT+ Train-vehicle collision (Signals)

disp reports that vehicle was not occupied at time of incident.

Updated 01/05/2017 14:39:08 by Bruce McVey Dept Signals IT+ Train-vehicle collision (Signals)

WAITING ON PARTS, ARRIVE IN AM

Updated 01/05/2017 14:42:42 by Bruce McVey Dept Signals IT+ Train-vehicle collision (Signals)

applied Jumper Log # 7949670

Updated 01/05/2017 14:49:19by Michael StanfillDept SignalsIT+ Train-vehicle collision (Signals)

Q619-03 hit Pepsi truck that got stuck on crossing. Truck was pushed into west gate mech. Gate mech and all associated parts are destroyed. Parts have been ordered and should arrive 1-6-17 in the am. Maintainer applied jumper from gp1 to gp to stop lights from flashing continuously with jumper log# 7949670. East gate and lights will work as designed. Maintainer will leave activation failure message# 35609 on crossing till repairs are completed. Maintainer attached Hawk recorder logs to this file. Field report shows 33 seconds from crossing activation to Island drop.

Thora report offewer de decertae from crossing activation to folding drop.

Updated 01/05/2017 14:52:16 **by** Don Skidmore Jr **Dept** -C and S **IT+** Train-vehicle collision (Signals)

WAITING ON PARTS, ARRIVE IN AM

Updated 01/06/2017 19:12:18 **by** Michael Stanfill **Dept** Signals **IT+** Train-vehicle collision (Signals) Incident Resolved: 01/06/2017 19:11:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s) Replaced west gate mast, mech, foundation and all lights. Tested with a 360 day test with no exceptions. Gate decent time is 14 seconds. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 01/06/2017

19:12:18

Closed 01/06/2017 19:16:12 by Sean Gaspar Dept Signals IT+ Train-vehicle collision (Signals)

Incident Resolved: 01/06/2017 19:11:00 Equipment Type: Gate Mechanism Action Taken: Replaced component(s).

Operational Checks Performed

Updated 01/06/2017 20:36:53 **by** Shari Baron **Dept** PSCC **IT+**

Contacted On 01-06-2017 20:36:00 Agency Biloxi Police Department Contact Name Eric Phone 228-392-0641

Log# 7945208 Status Closed Entered 01-02-2017 17:05:07 by Knotts, Patrick Type Vehicle on Track

IRI 0

Milepost 000 726.6

Contact Name NA Phone NA

Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer McCardle, B - ETA: 19:36

Description 01/02/2017 17:05:07 by Patrick Knotts Dept Signals IT+ Unknown

Sub NM

Updated 01/02/2017 17:05:40 **by** Patrick Knotts **Dept** Signals **IT+** Vehicle on Track MAIN ST MP 000726.6. PSCC REPORTED SEMI TRUCK STUCK ON TRACKS. PROTECTED WITH MSG 32182-SIGNALS AND 32183-MOW. Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 01/02/2017 17:05:40

Updated 01/02/2017 17:24:07 **by** Byron Tinsley **Dept** PSCC **IT+**

PSCC Incident Report - #7945200

Supv James Jr, G H

Updated 01/02/2017 17:36:10 by Patrick Knotts Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Brent McCardle ETA of: 19:36

Reg SO

Div AT

Updated 01/02/2017 19:40:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track

ETA time reached Status changed to Active

Contacted On 01-02-2017 17:24:00 Agency NA

Closed 01/02/2017 20:31:31 by Carlos Betancourt Dept Signals IT+ Vehicle on Track Incident Resolved: 01/02/2017 20:30:00 Equipment Type: N/A Action Taken: NTF - UTD No Signal equipment damage, all op checks and wai. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 01/02/2017 20:31:31

Updated 01/02/2017 20:49:12 **by** Byron Tinsley **Dept** PSCC **IT+**

Contacted On 01-02-2017 20:48:00 Agency Biloxi Police Department Contact Name Eric Phone 228-392-0641

Log# 7853208 Status Closed Entered 10-21-2016 14:18:13 by Tyo, Mark Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.125 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 15:06

Description 10/21/2016 14:18:13 **by** Mark Tyo **Dept** Signals **IT+** Unknown

Updated 10/21/2016 14:18:56 **by** Mark Tyo **Dept** Signals **IT+** Vehicle on Track Incident Type: TRK Dispatch incident Number: 59747 Incident Date: 21-OCT-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident Description: SEMI STUCK ON TRACK AT MAIN ST 000726.6 Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 10/21/2016 14:18:56

Updated 10/21/2016 14:18:57 by Mark Tyo Dept Signals IT+ Vehicle on Track

An email notification for (IRI) asset MAIN ST (1) has been sent to the following:

George James Jr

Updated 10/21/2016 14:21:23 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 15:06

Updated 10/21/2016 15:10:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track

ETA time reached Status changed to Active

Updated 10/21/2016 15:36:05 **by** Jerome Shepard **Dept** PSCC **IT+**

Contacted On 10-21-2016 15:36:00 Agency Biloxi Police Department Contact Name Operator Angie Phone 228-392-0641

PSCC Incident 7853190

Closed 10/21/2016 15:48:36 by Jake Carter Dept Signals IT+ Vehicle on Track Incident Resolved: 10/21/2016 15:48:00 Equipment Type: N/A Action Taken: Track Occupied no signal damage,gft 13 sec;returned to disp Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent

10/21/2016 15:48:36

Updated 10/21/2016 15:53:45 by Byron Tinsley Dept PSCC

Contacted On 10-21-2016 15:53:00Agency Biloxi Police Department Contact Name 911 Phone 228-392-0641

IT+

PSCC Incident 7853190

Log# 7847406 Status Closed Entered 10-17-2016 18:23:52 by Oglesby, Brad Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 20:57

Description 10/17/2016 18:23:52 **by** Brad Oglesby **Dept** Signals **IT+** Unknown

Updated 10/17/2016 18:25:33 by Brad Oglesby Dept Signals IT+ Vehicle on Track Last Update 10-17-2016 18:19 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch incident Number: 58858 Incident Date: 17-OCT-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident Description: TRUCK STUCK ON THE TRACKS AT 000726.6 MAIN STREET, NEED MAINTAINER AND TRACK INSPECTOR 1824 ESS CONFIRMED THE AA DISPATCHER IS PROVIDING PROTECTION ON THE CROSSING AS PER ACTIVATION FAILURE STANDARD. Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 10/17/2016 18:25:33

Updated 10/17/2016 18:26:55 by Brad Oglesby Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 19:56

Updated 10/17/2016 18:53:56 by Byron Tinsley Dept PSCC IT+
Contacted On 10-17-2016 18:53:00 Agency NA Contact Name NA Phone NA

PSCC Incident Report - #7847395 Biloxi Police Department 228-392-0641

Updated 10/17/2016 20:00:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Updated 10/17/2016 21:55:52 **by** Michael Stanfill **Dept** Signals **IT+** Vehicle on Track Incident Resolved: 10/17/2016 21:55:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung original gate Rehang east gate. No other damage. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 10/17/2016 21:55:52

Closed 10/17/2016 21:56:24 by Brad Oglesby Dept Signals IT+ Vehicle on Track Incident Resolved: 10/17/2016 21:55:00 Equipment Type: Gate Action Taken: Replaced shear pin/rehung

original gate . Operational Checks Performed

 Updated 10/17/2016 21:56:43
 by Kiwana Tompkins
 Dept PSCC
 IT+

 Operation 1.02 to 1

Contacted On 10-17-2016 21:56:00 Agency N/A Contact Name N/A Phone N/A

Log# 7810240 Status Closed Entered 09-21-2016 10:11:23 by McVey, Bruce Type Train-vehicle collision (Signals)

Supv James Jr, G H **Reg** SO **Div** AT **Sub** NM **IRI** 0 **Milepost** 000 726.6 **Block** 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 10:58

Description 09/21/2016 10:11:23 by Bruce McVey Dept Signals IT+ Unknown

Updated 09/21/2016 10:11:51 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

COPIED FROM DIRT Notification

Incident Type: TRK Dispatch incident Number: 52348 Incident Date: 21-SEP-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident

Description: Q61421 HIT CAR AT MP 000726.6, MAIN ST

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 09/21/2016 10:11:51

Updated 09/21/2016 10:12:27 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

The AA is protecting the Crossing with a Type 1 Activation Failure Message# 35759.

Updated 09/21/2016 10:13:40 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

Status changed to Dispatched for Michael Stanfill ETA of: 10:58

Updated 09/21/2016 10:53:31 **by** Bruce McVey **Dept** Signals **IT+** Train-vehicle collision (Signals)

mtr reports that incident happened at 340187K - DELAUNEY ST xing (cross buck xing....)

Updated 09/21/2016 11:34:06 **by** Michael Stanfill **Dept** Signals **IT+** Train-vehicle collision (Signals) Incident Resolved: 09/21/2016 11:30:00 Equipment Type: N/A Action Taken: NTF - UTD Collision occurred 2 crossings south of Main st, at 340187K - DELAUNEY ST. which is a cross-buck only crossing. Maintainer checked Main St. with no exceptions to operation of crossing. Remove crossing protection with message number 35850. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 09/21/2016 11:34:06

Updated 09/21/2016 11:42:23 by Waltina Edwards Dept PSCC IT+

Contacted On 09-21-2016 11:40:00 Agency [Police Department] Contact Name 352 Phone 228-392-0641

Esters Boulevard

Closed 09/21/2016 11:53:48 by Bruce McVey Dept Signals IT+ Train-vehicle collision (Signals)

Incident Resolved: 09/21/2016 11:30:00 Equipment Type: N/A Action Taken: NTF - UTD

Incident Resolved. Operational Checks Performed

Log# 7687076 Status Closed Entered 06-21-2016 13:32:04 by McVey, Bruce Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 14:05

Description 06/21/2016 13:32:04 **by** Bruce McVey **Dept** Signals **IT+** Unknown

Updated 06/21/2016 13:32:26 by Bruce McVey Dept Signals IT+ Vehicle on Track

COPIED FROM DIRT Notification

Incident Type: TRK Dispatch incident Number: 28769 Incident Date: 21-JUN-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: N Incident Description: ACTIVATION FAILURE TRACTOR TRAILER STUCK ON TRACKS 000726.6 MAIN STREET Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 06/21/2016 13:32:26

Updated 06/21/2016 13:32:55 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

The AA is protecting the Crossing with a Type 1 Activation Failure Message# 27090.

Updated 06/21/2016 13:35:39 by Bruce McVey Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 14:05

Updated 06/21/2016 13:47:24 **by** Jackie McGuirt **Dept** PSCC **IT+**

Contacted On 06-21-2016 13:47:00 Agency Biloxi Police Department Contact Name Oper: 308 Phone 228-392-0641

PSCC Incident Report - Edit #7687054

Updated 06/21/2016 14:10:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 06/21/2016 14:27:45 by Bruce McVey Dept Signals IT+ Vehicle on Track

Incident Resolved: 06/21/2016 14:27:00 Equipment Type: N/A Action Taken: NTF - UTD

Employee: M. Stanfill

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 06/21/2016 14:27:45

Updated 06/21/2016 14:56:28 by Roland Knagge Dept PSCC IT+

Contacted On 06-21-2016 14:54:00 Agency Biloxi Police Department Contact Name 3501 Phone 228-392-0641

Log# 7633152 Status Closed Entered 05-10-2016 13:58:37 by McVey, Bruce Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.5 Milepost 000 726.6 Block 2762/2763 Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill. M O - ETA: 15:02

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - *ETA:* 15:02

Description 05/10/2016 13:58:37 by Bruce McVey Dept Signals IT+ Unknown

Updated 05/10/2016 13:59:07 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

COPIED FROM DIRT Notification

Incident Type: TRK Dispatch incident Number: 19563 Incident Date: 10-MAY-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC

Flag: N Incident Description: VEHIVLE STUCK ON TRACKS AT MAIN ST MP 000726.6

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 05/10/2016 13:59:07

Updated 05/10/2016 13:59:09 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

An email notification for (IRI) asset MAIN ST (3) has been sent to the following:

George James Jr Danny McKenzie

Updated 05/10/2016 13:59:39 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

The AA is protecting the Crossing with a Type 1 Activation Failure Message# 34645.

Updated 05/10/2016 14:03:00 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 15:02

Updated 05/10/2016 14:19:35 **by** Byron Tinsley **Dept** PSCC **IT+**

Contacted On 05-10-2016 14:19:00 Agency NA Contact Name NA Phone NA

PSCC Incident Report - Edit #7633121 Biloxi Police Department 228-392-0641

Updated 05/10/2016 15:05:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 05/10/2016 16:15:15 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Incident Resolved: 05/10/2016 16:14:00 Equipment Type: N/A Action Taken: NTF - UTD

The Signal Maintainer reported that there was no signal damage. Gate Descent time is 13 Seconds. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 05/10/2016 16:15:15

Updated 05/10/2016 16:25:42 **by** Byron Tinsley **Dept** PSCC **IT+**

Contacted On 05-10-2016 16:24:00 Agency Biloxi Police Department Contact Name 3501 Phone 228-392-0641

Log# 7622945 Status Closed Entered 05-02-2016 15:36:22 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.25 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 16:01

Description 05/02/2016 15:36:22 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

Updated 05/02/2016 15:38:25 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

The AA Dispatcher received a report that a Tanker Truck is stuck on the tracks at Main Street, MP 000 726.61,

DOT# 340185W, NM Sub.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 20431**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 05/02/2016 15:38:25

Updated 05/02/2016 15:38:27 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

An email notification for (IRI) asset MAIN ST (2) has been sent to the following:

George James Jr

Updated 05/02/2016 15:41:27 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 16:01

Updated 05/02/2016 16:05:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track

ETA time reached Status changed to Active

Updated 05/02/2016 16:07:56 by Byron Tinsley Dept PSCC IT+

Contacted On 05-02-2016 16:06:00 Agency Biloxi Police Department Contact Name 911 Phone 228-392-0641

@ Easter Blvd.

Closed 05/02/2016 16:19:42 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Incident Resolved: 05/02/2016 16:19:00 Equipment Type: N/A Action Taken: NTF - UTD

The Signal Maintainer reported that there was no signal damage. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 05/02/2016 16:19:42

Updated 05/02/2016 16:29:57 by Byron Tinsley Dept PSCC IT+

Contacted On 05-02-2016 16:28:00 Agency Biloxi Police Department Contact Name Eric Phone 228-392-0641 @ Easter Blvd.

Log# 7611665 Status Closed Entered 04-23-2016 22:20:27 by Kite, Matt Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.125 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Broadway, J L - ETA: 00:43

Description 04/23/2016 22:20:27 by Matthew Kite Dept Signals IT+ Unknown

Updated 04/23/2016 22:21:21 by Matthew Kite Dept Signals IT+ Vehicle on Track

Incident Type: TRK Dispatch incident Number: 16104 Incident Date: 23-APR-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0727.0000 Right Mile Post: 000, 0730.2851 Asset: 2763 003, Asset Name: MAIN PTC Flag: Y Incident Description: SEMI STUCK ON MAIN ST XING - 000 726.6 - NEED TRACK INSPECTION Copied frm DIRT. Disp prot with A/F #45854.

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 04/23/2016 22:21:21

Updated 04/23/2016 22:21:22 by Matthew Kite Dept Signals IT+ Vehicle on Track

An email notification for (IRI) asset MAIN ST (1) has been sent to the following:

George James Jr

Updated 04/23/2016 22:24:19 by Kiwana Tompkins Dept PSCC IT+

Contacted On 04-23-2016 22:23:00 Agency Biloxi Police Department Contact Name Brady Phone 228*392*0641

PSCC #7611589

Updated 04/23/2016 23:13:07 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Joshua Broadway ETA of: 00:43

Updated 04/24/2016 00:05:40 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track Last Update 04-23-2016 23:33 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK Dispatch

incident Number: 16119 Incident Date: 23-APR-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000,

0723.1305 Right Mile Post: 000, 0727.0000 Asset: 2762 001, Asset Name: MAIN PTC Flag: N Incident Description: SEMI STUCK ON TRACK, NEED SIGNALS AND TRACK INSPECTORsecond notification sent by aa disp is a duplicate notification 6236521 is a duplicate comfirmed by aa disp 3rd shift...

Updated 04/24/2016 00:45:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Updated 04/24/2016 02:06:08 **by** Joshua Broadway **Dept** Signals **IT+** Vehicle on Track Incident Resolved: 04/24/2016 02:05:00 Equipment Type: Track Action Taken: Removed debris Vehicle removed. no signal damage. 12 seconds gate descent time. Returned to service with anullment number 45917. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 04/24/2016 02:06:08

Closed 04/24/2016 02:07:29 by Jerry Rockhill Dept Signals IT+ Vehicle on Track Incident Resolved: 04/24/2016 02:05:00 Equipment Type: Track Action Taken: Removed debris . Operational Checks Performed

Updated 04/24/2016 02:09:13 by Kiwana Tompkins Dept PSCC IT+

Contacted On 04-24-2016 02:09:00 Agency Biloxi Police Department Contact Name 1955 Phone 228*392*0641

Log# 7604659 Status Closed Entered 04-18-2016 16:32:31 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Mannion, R - *ETA*: 18:20

Description 04/18/2016 16:32:31 by Louis Rosenblatt Dept Signals IT+ Unknown

Updated 04/18/2016 16:33:11 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

The AA Dispatcher received a report from the PSCC that a Semi Truck is stuck on the track at Main Street, MP 000 726.61. DOT# 340185W. NM Sub.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 36059**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 04/18/2016 16:33:11

Updated 04/18/2016 17:05:59 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Roger Mannion ETA of: 18:20

Updated 04/18/2016 18:25:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Updated 04/18/2016 20:09:58 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track Incident Resolved: 04/18/2016 20:09:00 Equipment Type: N/A Action Taken: Track Occupied Truck removed, no signal damage Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 04/18/2016 20:09:58

Closed 04/18/2016 20:11:43 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track Incident Resolved: 04/18/2016 20:09:00 Equipment Type: N/A Action Taken: Track Occupied Operational

Checks Performed

 Log# 7556283
 Status Closed
 Entered 03-12-2016 15:55:50
 by Kite, Matt
 Type Vehicle on Track

 Supv James Jr, G H
 Reg SO
 Div AT
 Sub NM
 IRI 0
 Milepost 000 726.6
 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Broadway, J L - ETA: 17:59

Description 03/12/2016 15:55:50 **by** Matthew Kite **Dept** Signals **IT+** Unknown

Updated 03/12/2016 15:56:40 by Matthew Kite Dept Signals IT+ Vehicle on Track

Incident Type: TRK Dispatch incident Number: 06489 Incident Date: 12-MAR-16 Pri.Train ID: SubDivision Code: NM Left Mile Post: 000, 0726.0000 Right Mile Post: 000, 0730.3000 Asset: 2763 003, Asset Name: MAIN PTC

Flag: N Incident Description: CAR STUCK ON THE TRACKS AT 000726.6 MAIN STREET, NEED MAINTAINER

AND TRACK INSPECTOR Copied frm DIRT. Disp prot with A/F #15725.

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/12/2016 15:56:40

Updated 03/12/2016 16:29:02 by Matthew Kite Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Joshua Broadway ETA of: 17:59

Updated 03/12/2016 18:00:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 03/12/2016 18:13:51 by Matthew Kite Dept Signals IT+ Vehicle on Track

Incident Resolved: 03/12/2016 18:13:00 Equipment Type: N/A Action Taken: NTF - UTD

Mntr reports bus removed frm trks. No damage to sig equip. Performed op checks, no exceptions noted to sig

equip. Turned crossing back over to disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent

03/12/2016 18:13:51

Log# 7457210 Status Closed Entered 12-29-2015 14:12:16 by Williams, Joseph Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.125 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 15:18

Description 12/29/2015 14:12:16 **by** Joseph Williams **Dept** Signals **IT+** Unknown

Updated 12/29/2015 14:14:39 **by** Joseph Williams **Dept** Signals **IT+** Vehicle on Track

1413:Hr outside party reported that there is a semi truck stuck on the tracks. 1413:Hr dispatcher was already protecting the crossing with an activation failure message. Notification Sent to -Signal Control Center - Atlanta at 12/29/2015 14:14:39

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 12/29/2015 14:14:39

Updated 12/29/2015 14:14:40 by Joseph Williams Dept Signals IT+ Vehicle on Track

An email notification for (IRI) asset MAIN ST (.125) has been sent to the following:

George James Jr

Updated 12/29/2015 14:18:44 by Matthew Kite Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 15:18

Updated 12/29/2015 14:25:56 by Deborah Anderson Dept PSCC IT+

Contacted On 12-29-2015 14:23:00 Agency Biloxi Police Department Contact Name 376 Phone 228-392-0641

TCIS # 7457207

Updated 12/29/2015 15:20:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 12/29/2015 16:11:02 by Jake Carter Dept Signals IT+ Vehicle on Track

Incident Resolved: 12/29/2015 16:10:00 Equipment Type: N/A Action Taken: NTF - UTD No damage to sig equipment; returned to disp Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC

Notification Sent 12/29/2015 16:11:02

Updated 12/29/2015 16:32:27 by Waltina Edwards Dept PSCC IT+

Contacted On 12-29-2015 16:31:00 Agency Police Department Contact Name 2901 Phone Phone# 228-392-0641

Log# 7421701 Status Closed Entered 11-30-2015 06:06:40 by Rockhill, Jerry Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762/2763

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 07:40

Description 11/30/2015 06:06:40 **by** Jerry Rockhill **Dept** Signals **IT+** Unknown

Updated 11/30/2015 06:08:40 by Jerry Rockhill Dept Signals IT+ Vehicle on Track

0607 Last Update 11-30-2015 05:59 By DRT Type General Business Impact 3 Priority 3 Incident Type: TRK

Updated 11/30/2015 06:10:11 **by** Jerry Rockhill **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 07:40

Updated 11/30/2015 07:45:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Updated 11/30/2015 09:48:48 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

Update - The ESS texted a message requesting an update on the Signal Maintainers cell phone.

Closed 11/30/2015 09:51:09 by Bruce McVey Dept Signals IT+ Vehicle on Track

Incident Resolved: 11/30/2015 08:50:00 Equipment Type: N/A Action Taken: NTF - UTD

Employee: M. Stanfill

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 11/30/2015 09:51:09

Log# 7188341 Status Closed Entered 06-15-2015 15:12:04 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.125 Milepost 000 726.6 Block 2762

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 16:49

Description 06/15/2015 15:12:04 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

Updated 06/15/2015 15:12:41 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher reported that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 24259**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 06/15/2015 15:12:41

Updated 06/15/2015 15:34:25 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 16:49

Updated 06/15/2015 16:50:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 06/15/2015 17:32:50 by Robert Gibson Dept Signals IT+ Vehicle on Track Incident Resolved: 06/15/2015 17:22:00 Equipment Type: N/A Action Taken: NTF - UTD MTR REPORTED COA, NO DAMAGE TO THE XING, EZ/EX 100/85 Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 06/15/2015 17:32:50

Log# 7158402 Status Closed Entered 05-26-2015 11:27:21 by McVey, Bruce Type Vehicle on Track

Supv James Jr, G HReg SODiv ATSub NMIRI 0Milepost 000 726.6Block 2762Section 3090-7M16Asset MAIN STAssetNum 340185WMaintainer Stanfill, M O - ETA: 13:07

Description 05/26/2015 11:27:21 **by** Bruce McVey **Dept** Signals **IT+** Unknown

Updated 05/26/2015 11:27:44 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher reported that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a truck stuck on the track.

The Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 26906**. BLM Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 05/26/2015 11:27:44

Updated 05/26/2015 11:28:42 **by** Bruce McVey **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 13:07

Updated 05/26/2015 11:44:06 by Waltina Edwards Dept PSCC IT+

Contacted On 05-26-2015 11:42:00 Agency Biloxi Police Department Contact Name 347 Phone 228-392-0641

esters Boulevard

Updated 05/26/2015 13:10:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 05/26/2015 15:01:54 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Incident Resolved: 05/26/2015 15:00:00 Equipment Type: N/A Action Taken: NTF - UTD

The Signal Maintainer reported that there was no signal damage. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 05/26/2015 15:01:54

Updated 05/26/2015 15:11:03 **by** Byron Tinsley **Dept** PSCC **IT+**

Contacted On 05-26-2015 15:07:00 Agency Biloxi Police Department Contact Name 2901 Phone 228-392-0641 esters Boulevard

Log# 7078439 Status Closed Entered 03-31-2015 18:42:08 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.125 Milepost 000 726.6 Block 2762

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Mannion, R - ETA: 21:29

Description 03/31/2015 18:42:08 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

Updated 03/31/2015 18:44:19 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 49296**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/31/2015 18:44:19

Updated 03/31/2015 19:29:44 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Roger Mannion ETA of: 21:29

Updated 03/31/2015 21:30:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Updated 03/31/2015 21:57:04 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track Incident Resolved: 03/31/2015 21:57:00 Equipment Type: N/A Action Taken: Track Occupied Truck removed from track, no signal damage, watched SB train through crossing with no exceptions. Returned to dispatcher @ 2156. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/31/2015 21:57:04

Closed 03/31/2015 22:01:23 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Incident Resolved: 03/31/2015 22:01:00 Equipment Type: N/A Action Taken: Track Occupied Resolved to close.

Operational Checks Performed

Updated 03/31/2015 23:42:55 **by** Misty Hunter **Dept** PSCC **IT+**

Log# 7076463 Status Closed Entered 03-30-2015 15:49:29 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Mannion, R - ETA: 19:15

Description 03/30/2015 15:49:29 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

Updated 03/30/2015 15:49:57 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, NM Sub. has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 45827**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/30/2015 15:49:57

Updated 03/30/2015 16:15:46 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Roger Mannion ETA of: 19:15

Updated 03/30/2015 18:11:12 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track Incident Resolved: 03/30/2015 18:11:00 Equipment Type: N/A Action Taken: Track Occupied Truck removed prior to arrival, no signal damages, verified full operation of crossing with no exceptions. returned to dispatcher at 1806, WCJ. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/30/2015 18:11:12

Closed 03/30/2015 18:12:54 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track Incident Resolved: 03/30/2015 18:12:00 Equipment Type: N/A Action Taken: Track Occupied Resolved to close. Operational Checks Performed

Log# 6860473 Status Closed Entered 10-31-2014 10:45:13 by Kite, Matt Type Vehicle on Track Supv James Jr, G H Reg SO Div AT Sub NM **IRI** 0.125 Milepost 000 726.6 **Block** 2762 **Section** 3090-7M16 **Asset MAIN ST** AssetNum 340185W Maintainer Mannion, R - ETA: 12:50 **Description** 10/31/2014 10:45:13 **by** Matthew Kite **Dept** Signals IT+ Unknown

Updated 10/31/2014 10:46:07 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

Disp reports truck on the trks at crossing. Disp prot with A/F #16860.

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 10/31/2014 10:46:07

Updated 10/31/2014 10:50:13 by Matthew Kite Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Roger Mannion ETA of: 12:50

Updated 10/31/2014 10:57:24 by Robert Clendening Dept PSCC IT+
Contacted On 10-31-2014 10:56:00 Agency Biloxi Police Department Contact Name John Phone 228-392-06

Contacted On 10-31-2014 10:56:00 Agency Biloxi Police Department Contact Name John Phone 228-392-0641 @ Esters Boulevard

S 2010:0 200:010:0

Updated 10/31/2014 11:07:30 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

ATL ACD, AA Disp, NM Sub, Loc 2762; PSCC reported vehicle stuck on tracks at mp 000726.6, Main Street - COPIED.

Updated 10/31/2014 12:55:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track ETA time reached Status changed to Active

Updated 10/31/2014 12:55:24 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track Incident Resolved: 10/31/2014 12:55:00 Equipment Type: N/A Action Taken: Track Occupied truck removed no signal damage. back to dispatcher @ 1254 with message number 16966 Operational Checks Performed Asset:

MAIN ST Status Changed To: In Service PCC Notification Sent 10/31/2014 12:55:24

Closed 10/31/2014 12:58:05 by Matthew Kite Dept Signals IT+ Vehicle on Track

Incident Resolved: 10/31/2014 12:57:00 Equipment Type: N/A Action Taken: NTF - UTD

Operational Checks Performed

Log# 6848453 Status Closed Entered 10-22-2014 17:34:32 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Mannion, R - ETA: 19:49

Description 10/22/2014 17:34:32 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

Updated 10/22/2014 17:35:19 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

The AA Dispatcher reported that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a tractor trailer stuck on the tracks.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 39632**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 10/22/2014 17:35:19

Updated 10/22/2014 17:49:10 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Roger Mannion ETA of: 19:49

Updated 10/22/2014 19:50:00 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Updated 10/22/2014 20:08:52 **by** Roger Mannion **Dept** Signals **IT+** Vehicle on Track Incident Resolved: 10/22/2014 20:08:00 Equipment Type: N/A Action Taken: Track Occupied vehicle removed, no signal damages. Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 10/22/2014 20:08:52

Closed 10/22/2014 20:13:43 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track Incident Resolved: 10/22/2014 20:13:00 Equipment Type: N/A Action Taken: Track Occupied Resolved to close.

Operational Checks Performed

Log# 6772574 Status Closed Entered 08-28-2014 22:29:53 by Rosenblatt, Louis Type Train-vehicle collision

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762

Section 3090-7M16 Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 01:11 & Watson, T G - ETA: 05:30

Description 08/28/2014 22:29:53 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

Updated 08/28/2014 22:30:34 **by** Louis Rosenblatt **Dept** Signals **IT+** Train-vehicle collision

The AA Dispatcher received a report from Q18028 Northbound that they struck a Tractor Trailer at Main Street, MP 000 726.61, DOT# 340185W, NM Sub.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 20224**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 08/28/2014 22:30:34

Updated 08/28/2014 22:30:47 by Louis Rosenblatt Dept Signals IT+ Train-vehicle collision

Notification has been sent to the following: George James Jr Danny McKenzie Jody Cox C Manager

Updated 08/28/2014 22:39:49 **by** Louis Rosenblatt **Dept** Signals **IT+** Train-vehicle collision

Train involved: Q18028
 Direction of travel: North
 Estimated speed: unknown

4. Subdivision: NM - NO&M **5. Timetable speed**: 45 MPH

6. Number of occupants/injuries: 0/0

7. Number of fatalities: 0

8. Milepost: 000 726.61 DOT: 340185W Name: Main Street

9. Crossing protection (gates, flashers, bells, cantilevers, etc.): Flashers/Bell/Gates

10. Crossing controller equipment (PMD3, GCP 4000, etc.): GCP-3000

11. Damage to crossing, if any: unknown

12. Date last inspected (can be pulled from Raildocs): 08/08/2014

Updated 08/28/2014 22:41:34 **by** Louis Rosenblatt **Dept** Signals **IT+** Train-vehicle collision

C&S Manager Briefed.

Updated 08/28/2014 22:43:12 **by** Louis Rosenblatt **Dept** Signals **IT+** Train-vehicle collision

Update - The AA Dispatcher reported that the train crew said they were going 40 mph and they are checking for signal damage. LVR

Updated 08/28/2014 23:11:59 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision

Status changed to Dispatched for Michael Stanfill ETA of: 01:11

Updated 08/29/2014 01:15:00 by TCIS AUTOMATION Dept Signals IT+ Train-vehicle collision

ETA time reached Status changed to Active

Updated 08/29/2014 01:20:34 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision

0114 mtr reports east gate and signal at crossing is on the ground....mtr onsite

Updated 08/29/2014 03:08:17 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision 0300 mtr needs for crossing repairs: gate mech with 2 arms and gate keeper mast with double junction box base 18 ft gate with lights bell for top of mast doll arm 2 sets of back to back lights (8 lights)....led inserts are reusable onsite...xbucks and dot sign reusable...

Updated 08/29/2014 05:29:38 **by** Jerry Rockhill **Dept** Signals **IT+** Train-vehicle collision

Status changed to Escalated, Tommy Watson ETA of: 05:30

Closed 08/29/2014 21:42:07 by Louis Rosenblatt Dept Signals IT+ Train-vehicle collision

Incident Resolved: 08/29/2014 21:39:00 Equipment Type: Gate Mechanism Action Taken: Replaced

component(s)

The Signal Maintainer reported that East Gate Mechanism Assembly was replaced. Operational Checks were performed. He watched a Southbound train operate through the crossing with no exceptions taken. The Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/29/2014 21:42:07

Log# 6740944 Status Closed Entered 08-07-2014 08:23:35 by Gothard, Jason Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762

Section 3090-Ocean Springs Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 09:24

Description 08/07/2014 08:23:35 **by** Jason Gothard **Dept** Signals **IT+** Unknown

Updated 08/07/2014 08:24:05 by Jason Gothard Dept Signals IT+ Vehicle on Track

atl acd, aa disp, nm sub, loc 2781" PSCC reported a tractor trailer stuck on the track at Main St, MP 000 726.61...Please send MOW and Signals to check Asset: MAIN ST Status Changed To: Out Of Service PCC

Notification Sent 08/07/2014 08:24:05

Updated 08/07/2014 08:24:49 **by** Jason Gothard **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 09:24

Updated 08/07/2014 08:40:16 by Brooks Clayton Dept PSCC IT+

Contacted On 08-07-2014 08:40:00 Agency Biloxi Police Department Contact Name Tiffany Phone 228-392-0641

Closed 08/07/2014 09:20:44 by Jason Gothard Dept Signals IT+ Vehicle on Track Incident Resolved: 08/07/2014 09:20:00 Equipment Type: N/A Action Taken: Track Occupied truck cleared and no signal damage. made op checks and ret to disp Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/07/2014 09:20:44

Updated 08/07/2014 09:23:47 by Christina Martorano Dept PSCC IT+

Contacted On 08-07-2014 09:22:00 Agency Biloxi Police Contact Name Tiffany Phone 228-392-0641

Log# 6646699 Status Closed Entered 06-03-2014 08:32:07 by Kite, Matt Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762

Section 3090-Ocean Springs Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 09:34

Description 06/03/2014 08:32:07 **by** Matthew Kite **Dept** Signals **IT+** Unknown

Updated 06/03/2014 08:33:03 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

ATLANTA CHIEF, AA DISPATCHER, MM SUB, LOCATION 2762-001, PSCC REPORTS TRUCK ON TRACKS

AT MAIN ST MP 000726.6 - Copied. Disp prot with A/F #47506.

Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 06/03/2014 08:33:03

Updated 06/03/2014 08:34:18 **by** Matthew Kite **Dept** Signals **IT+** Vehicle on Track

Status changed to Dispatched for Michael Stanfill ETA of: 09:34

Updated 06/03/2014 08:45:31 by Christina Martorano Dept PSCC IT+

Contacted On 06-03-2014 08:35:00 Agency Biloxi Police Contact Name 347 Phone 228-392-0641

PSCC incident #6646688

Updated 06/03/2014 09:39:04 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 06/03/2014 10:13:00 by Bruce McVey Dept Signals IT+ Vehicle on Track

Incident Resolved: 06/03/2014 10:12:00 Equipment Type: N/A Action Taken: NTF - UTD

Employee: M. Stanfill

- Vehicle removed, No signal damage.

Did OP Checks, Back/released to AA disp. Gate down time 14

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 06/03/2014 10:13:00

Updated 06/03/2014 10:42:40 **by** Alexis Romine **Dept** PSCC **IT+**

Contacted On 06-03-2014 10:42:00 Agency Biloxi Police Contact Name Angie Phone 228-392-0641

PSCC incident #6646688

Log# 6534225 Status Closed Entered 03-14-2014 17:29:57 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 Milepost 000 726.6 Block 2762

Section 3090-Ocean Springs Asset MAIN ST AssetNum 340185W Maintainer Richardson, G L - ETA: 19:48

Description 03/14/2014 17:29:57 **by** Louis Rosenblatt **Dept** Signals **IT+** Unknown

Updated 03/14/2014 17:31:25 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, NM Sub, has a vehicle on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 16663**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 03/14/2014 17:31:25

Updated 03/14/2014 17:49:37 **by** Sean Reid **Dept** PSCC **IT+**

Contacted On 03-14-2014 17:49:00 Agency Biloxi Police Department Contact Name Disp # Hamet Phone 228-392-0641

@ Esters Blvd

Updated 03/14/2014 19:03:21 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Status changed to Dispatched for Gregory Richardson ETA of: 19:48

Updated 03/14/2014 19:50:00 **by** TCIS AUTOMATION **Dept** Signals **IT+** Vehicle on Track

ETA time reached Status changed to Active

Updated 03/14/2014 19:50:10 by TCIS AUTOMATION Dept Signals IT+ Vehicle on Track

ETA time reached Status changed to Active

Closed 03/14/2014 20:59:15 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track

Incident Resolved: 03/14/2014 20:56:00 Equipment Type: N/A Action Taken: NTF - UTD

The Signal Maintainer reported that there was no signal damage. The vehicle has been removed. Operational Checks were performed. The Crossing was placed Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 03/14/2014 20:59:15

Updated 03/14/2014 21:05:59 **by** Avie Saunders **Dept** PSCC **IT+**

Contacted On 03-14-2014 21:05:00 Agency n/a Contact Name n/a Phone n/a

PSCC Incident Report #6534196

Log# 6254591 Status Closed Entered 08-18-2013 07:52:45 by Kondy, Rick Type .False or partial activation reported

Supv James Jr, G H Reg SO Div AT Sub NM IRI 0.125 Milepost 000 726.6 Block 2762

Section 3090-Ocean Springs Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 09:31

Description 08/18/2013 07:52:45 **by** Richard Kondy **Dept** Signals **IT+** Unknown

Updated 08/18/2013 07:55:00 **by** Richard Kondy **Dept** Signals **IT+** .False or partial activation reported gates down , no trains . disp protecting crossing with false activation # 29673 . Notification Sent to -Signal Control Center - Atlanta at 08/18/2013 07:55:00 Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 08/18/2013 07:55:00

Updated 08/18/2013 08:01:50 by Bruce McVey Dept Signals IT+ .False or partial activation reported

Status changed to Dispatched for Michael Stanfill ETA of: 09:31

Updated 08/18/2013 08:03:30 by Deborah Anderson Dept PSCC IT+

Contacted On Agency // Contact Name biloxi police Phone 228-392-0641

Reporting party has been verified as the responsible law enforcement agency.

Updated 08/18/2013 09:35:00 by TCIS AUTOMATION Dept Signals IT+ .False or partial activation reported

ETA time reached Status changed to Active

Updated 08/18/2013 10:00:49 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

• Mtr/employee is on-site.

Updated 08/18/2013 11:21:55 **by** Bruce McVey **Dept** Signals **IT+** .False or partial activation reported

SB Q579-17 in block

Closed 08/18/2013 11:46:44 by Bruce McVey Dept Signals IT+ .False or partial activation reported

Incident Resolved: 08/18/2013 11:46:00 Equipment Type: Power/batteries Action Taken: Lightning protectors/arrestors replaced

Employee: M. Stanfill

- replaced 6 lighting arrestors at Lamse...

Did OP Checks, Back/released to AA disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/18/2013 11:46:44

Dept PSCC **Updated** 08/18/2013 12:19:54 **by** Deborah Anderson

Contact Name 376 Contacted On 08-18-2013 12:19:00 Agency biloxi police Phone 228-392-0641

Status Closed **Entered** 08-17-2013 14:55:47 **by** Williams, Joseph Log# 6254121 Type .False or partial activation reported

Milepost 000 726.6 Supv James Jr, G H Reg SO Div AT Sub NM IRI 0 **Block** 2762

Section 3090-Ocean Springs **Asset MAIN ST** AssetNum 340185W Maintainer Houck, B - ETA: 16:30

Description 08/17/2013 14:55:47 by Joseph Williams **Dept** Signals IT+ Unknown

Updated 08/17/2013 14:59:17 by Joseph Williams **Dept** Signals IT+ .False or partial activation reported 1456:HR Biloxi Police reported that the gates are down with lights flashing and no trains in sight. 1458:Hr dispatcher WJS notified. Notification Sent to -Signal Control Center - Atlanta at 08/17/2013 14:59:17 Asset: MAIN ST Status Changed To: Out Of Service PCC

Updated 08/17/2013 15:07:44 **by** Sean Reid **Dept PSCC** IT+

Contacted On 08-17-2013 15:07:00 Agency Biloxi Police Department Contact Name Disp # Eric Phone 228-392-0641

Updated 08/17/2013 15:30:56 by Matthew Kite **Dept** Signals IT+ .False or partial activation reported

Status changed to Dispatched for Bradley Houck ETA of: 16:30

Updated 08/17/2013 16:35:00 by TCIS AUTOMATION **Dept** Signals IT+ .False or partial activation reported

ETA time reached Status changed to Active

Notification Sent 08/17/2013 14:59:17

Dept Signals Closed 08/17/2013 17:56:48 **by** Matthew Kite IT+ .False or partial activation reported

Incident Resolved: 08/17/2013 17:45:00 Equipment Type: Crossing case equipment Action Taken: Replaced card(s)

Mntr found relay drive cd on nor side was bad, transferred to stand-by side, tested crossing. Operational checks were good, turned crossing backover to disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 08/17/2013 17:56:48

Updated 08/17/2013 18:37:57 **by** Kihron Bristol **Dept PSCC** IT+

Phone 228-392-0641 Contacted On 08-17-2013 18:37:00 Agency Biloxi Police Department Contact Name operator

Log# 5884366 Status Closed **Entered** 12-01-2012 17:13:28 **by** Kite, Matt Type Vehicle on Track

Div AT Sub NM Supv James Jr, G H Reg SO IRI Milepost 000 726.6 **Block** 2762

Section 3090-Ocean Springs Asset MAIN ST AssetNum 340185W Maintainer Broadway, J L - ETA: 18:41

Description 12/01/2012 17:14:56 **by** Matthew Kite **Dept** Signals IT+ Vehicle on Track

atl acd, aa disp, nm sub, loca: 000726.6 horse trailer bottomed out on the tracks, need mow and signals to inspect - COPIED. Train crew reports trailer is stuck on trks. Disp prot crossing with A/F #40581. Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 12/01/2012 17:14:56

Closed 12/01/2012 19:22:55 **Dept** Signals **by** Matthew Kite IT+ Vehicle on Track

Incident Resolved: 12/01/2012 19:18:00 Equipment Type: N/A Action Taken: Eqpt tested & fnd working as

intended Suspected Reason: Outside party or vandalism

Mntr reports trailer removed frm trk. No damage to sig equipment at crossing. Performed op checks, gate des

time 13 sec. Turned crossing backover to disp.

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent

12/01/2012 19:22:55

Log# 5789068 Status Closed Entered 09-19-2012 15:39:54 by Rosenblatt, Louis Type Vehicle on Track

Supv James Jr, G H Reg SO Div AT Sub NM IRI Milepost 000 726.6 Block 2762

Section 3090-Ocean Springs Asset MAIN ST AssetNum 340185W Maintainer Stanfill, M O - ETA: 16:54

Description 09/19/2012 15:43:19 **by** Louis Rosenblatt **Dept** Signals **IT+** Vehicle on Track

The AA Dispatcher received a report from the PSCC that Main Street, MP 000 726.61, DOT# 340185W, has a vehicle stuck on the track.

The AA Dispatcher is protecting the Crossing with a **Type 1 Activation Failure Message# 33399**. LVR Asset: MAIN ST Status Changed To: Out Of Service PCC Notification Sent 09/19/2012 15:43:19

Updated 09/19/2012 15:44:53 by Raheem Roberts Dept PSCC IT+

Contacted On 09-19-2012 15:44:00 Agency n/a Contact Name n/a Phone n/a

Ref PSCC Incident Report #5788977

Closed 09/19/2012 17:49:10 by Louis Rosenblatt Dept Signals IT+ Vehicle on Track Incident Resolved: 09/19/2012 17:47:00 Equipment Type: N/A Action Taken: Issue cleared before cause

identified Suspected Reason: Equipment failure

The Signal Maintainer tested the crossings with no issues found. The Crossing is Back In Service with the Dispatcher. LVR

Operational Checks Performed Asset: MAIN ST Status Changed To: In Service PCC Notification Sent 09/19/2012 17:49:10

Updated 09/19/2012 18:15:21 **by** Sean Reid **Dept** PSCC **IT+**

Contacted On 09-19-2012 18:15:00 Agency n/a Contact Name n/a Phone n/a

Ref PSCC Incident Report #5788977

Page Execution Time: 003.00 seconds