

Human Factors Summary Report on 07/16/2013 as of 07:56

Search Criteria	
Employee Name/ID	NOTHERN, D. W - [REDACTED] Crew Position Engineer
Human Factor Summary - NOTHERN, D. W - NOTHERN, D. W - 07/16/2013 as of 07 56	
Employee Name	NOTHERN, D. W
Crew Position	Engineer
Original Hire Date	10/10/1974
Certification Date	03/12/2011
Last Rules Exam	GCOR(03/09/2011 - OR4A - 90), Air Brake(03/09/2011 - RXABE - 90), Haz Mat(03/09/2011 - ORHM - 93)
Last Ride	05/28/2013 (49-Days) on ENG position. Count of Rides in 365 Days- ENG-3, RCO-0, TRN-0
Last Event Recorder	05/31/2013 (46-Days) on ENG position. Count of Event Recorders in 365 Days- ENG-3, RCO-0, TRN-0
EQMS Score	847
FTX	Total FTX = 24 PASS = 21 COACH = 3 HEAR = 0
Discipline	09/10/2012 - WHILE WORKING AS AN ENGINEER ON TRAIN LDG89-10, AT HAYS, KANSAS, IN THE VICINITY OF M LEPOST 289, ON THE SHARON SPRINGS SUBDIVISION, AT APPROXIMATELY 1930 HOURS, ON SEPTEMBER 10, 2012, EMPLOYEE FAILED TO USE SAFE SWITCHING PRACTICES AND TRAIN HANDLING, RESULTING IN SEVERE DAMAGE TO CAR AIGX470042 WHEN MAKING A TRAIN JOINT WITH A TWO LOCOMOTIVE CONSIST. RULE 7.1 L0+L3=L3 (5 DAY SUSPENSION)

Search Criteria	
Employee Name/ID	IVERSON, JOSHUA R - [REDACTED] Crew Position Conductor
Human Factor Summary - IVERSON, JOSHUA R - IVERSON, JOSHUA R - 07/16/2013 as of 07 56	
Employee Name	IVERSON, JOSHUA R
Crew Position	Conductor
Original Hire Date	02/20/2007
Certification Date	07/11/2012
Last Rules Exam	GCOR(12/13/2012 - OR4A - 88), Air Brake(12/13/2012 - RXABE - 95), Haz Mat(12/13/2012 - ORHM - 100)
Last Ride	03/06/2013 (132-Days) on ENG position. Count of Rides in 365 Days- ENG-2, RCO-0, TRN-1
Last Event Recorder	06/02/2013 (43-Days) on ENG position. Count of Event Recorders in 365 Days- ENG-1, RCO-0, TRN-0
EQMS Score	988
FTX	Total FTX = 17 PASS = 15 COACH = 2 HEAR = 0
Discipline	08/09/2008 - WHILE WORKING AS CONDUCTOR ON LMF43-08 AT HERINGTON, KANSAS, NEAR M LEPOST 171.3, TOPEKA SUBDIVISION, AT APPROXIMATELY 2:50 A.M., ON AUGUST 9, 2008, YOU FAILED TO SWITCH SAFELY AND EFFICIENTLY WHEN YOUR JOB ALLOWED A CUT OF LOADED CARS TO MAKE CONTACT WITH AN EMPTY CAR RESULTING IN DAMAGE TO EQUIPMENT.

Search Criteria	
Employee Name/ID	HOYT, DALE A - [REDACTED] Crew Position Conductor
Human Factor Summary - HOYT, DALE A - HOYT, DALE A - 07/16/2013 as of 07 56	
Employee Name	HOYT, DALE A
Crew Position	Conductor
Original Hire Date	02/07/2005
Certification Date	07/11/2012
Last Rules Exam	GCOR(02/08/2012 - OR1A - 95), Air Brake(02/08/2012 - RXABC - 95), Haz Mat(02/08/2012 - ORHM - 93)
Last Ride	05/02/2013 (75-Days) on TRN position. Count of Rides in 365 Days- ENG-0, RCO-0, TRN-1
Last Event Recorder	05/23/2013 (54-Days) on TRN position. Count of Event Recorders in 365 Days- ENG-0, RCO-0, TRN-1
EQMS Score	965
FTX	Total FTX = 14 PASS = 13 COACH = 1 HEAR = 0
Discipline	09/07/2007 - WHILE WORKING AS A CREWMEMBER ON THE YSN56-07 ON SEPTEMBER 7, 2007 AT APPROXIMATELY 1730 HOURS IN THE VICINITY OF MP 185.5 IN THE SALINA YARD IN SALINA, KANSAS, MR. HOYT FAILED TO PERFORM A PROPER JOB BRIEFING AND MADE AN UNPROTECTED SHOVING MOVEMENT OF CARS RESULTING IN THE DERAILMENT OF TWO CARS UP 912688 AND QTTX 131391. SSI ITEM APPLIES