

INSPECTION REPORT

Inspector's Name BECK, THOMAS G		Inspector's Signature 		Inspector's ID No. 	Report No. 4	Date yy mm dd 2017 01 06							
Railroad/Company Name & Address LONG ISLAND RAIL ROAD 93-29 183rd Street Hollis NY 11423				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Cue Ellis Title Track Engineer Sub 1 Email Signature _____							
From: City NEW YORK-KINGS	Codes 4170	Destination City & County			Codes	From Latitude							
State NY	36	City			From Longitude								
County KINGS	C047	County			To Latitude								
Mile Post: From To		Inspection Point ATLANTIC TERMINAL			To Longitude								
Activity Code:	RWP	LTT	MTW	TOM	2170								
Units:	1	1	1	6	1								
Sub Units:	8	4	0	0	7								
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] ACCIDENT SITE INVESTIGATION OF LI TRAIN # 2817 , HEADEND MU # 7553 , GOING THRU BUMPING POST ON STATION TRACK # 6 WITH 108 INJURIES. WALKED MAIN TRACK WITH NTSB AND LI MANAGEMENT , NO EXCEPTIONS TAKEN													
Seal Applied		Seal Removed		Hazard Class				UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					

Source Code C	File Number HQ-2017-1179	ID's of Accompanying Inspector(s)
------------------	-----------------------------	-----------------------------------