



Anup Sidhu  
Director NVM Marketing  
Atmel Corporation  
Tel: (408) 436-4136  
Fax: (408) 487-2538


July 20, 2001

Jeff Kennedy  
NTSB

Dear Mr. Kennedy,

We were unsuccessful at reading the data contained in the part. The reason for this is that some of the parts leads were very badly damaged. We also consulted our packaging group and used an outside consultant in an attempt to attach new leads on the device, and we were unsuccessful in this operation. If you have any questions, please feel free to give me a call at (408) 436-4136.

Sincerely,

  
Anup Sidhu

Director NVM Marketing