EQUIP ID	DATE SERVICE REPORTED REQUEST ID	WORK ORDER ID	SYMPTOM COMMENT	FAILURE COMMENT	CORRECTION COMMENT	WARRANTY COMPLAINT
SCAX206	02/23/2015 SCAX206-293166		606: BATTERY CHARGER FAILURE. NO DOORS/LIGHT/HVAC.	12: BROKEN	No Correction Entered	
SCAX206	11/05/2014 SCAX206-264307	No Work Order Assigned	1300: DESTINATION SIGNS BOTH SIDES NO DISPLAY	12: BROKEN	REPLACED LIGHT BULBS	DESTINATION SIGNS BOTH SIDES NO DISPLAY
SCAX206	10/31/2014 SCAX206-262619	No Work Order Assigned	900: PASSENGER FELL WHILE WALKING DOWN B END MID TO LOWER LEVEL	12: BROKEN	PERFORMED AFTER ACCIDENT INSPECTION	PASSENGER FELL WHILE WALKING DOWN B END MID TO LOWER LEVEL
SCAX206	09/26/2014 SCAX206-250046		1502: UPPER LEVEL B END FIRE EXTINGUISHER B/O. LOW PRESSURE	12: BROKEN	REPALCED	UPPER LEVEL B END FIRE EXTINGUISHER B/O. LOW PRESSURE
SCAX206			1502: VESTIBULE CURTAIN DOESN'T RETRACT ON THE B END	12: BROKEN	REPLACED No Correction Federal	VESTIBULE CURTAIN DOESN'T RETRACT ON THE B END
SCAX206 SCAX206	08/04/2014 SCAX206-234202 07/31/2014 SCAX206-233505	ECMS02-2014-748 ECMS02-2014-748	1300: R/S DESTINATION SIGN OUT 1502: A END VESTIBULE CURTAIN DEFECIVE. WILL NOT RETRACT	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	R/S DESTINATION SIGN OUT A END VESTIBULE CURTAIN DEFECIVE. WILL NOT RETRACT
SCAX206			1400: FOGGY WINDOW UPPER LEVEL	12: BROKEN	REPLACED WINDOW PER DDS	FOGGY WINDOW UPPER LEVEL
SCAX206			1502: A END UPPER AND LOWER LEVEL FIRE EXTINGUISHER EXPIRED	12: BROKEN	APPLIED FIRE EXTINGUISHER WITH CORRECT DATE.	A END UPPER AND LOWER LEVEL FIRE EXTINGUISHER EXPIRED
SCAX206 SCAX206	07/14/2014 SCAX206-227718		1400: FOGGY WINDOW UPPER LEVEL	12: RESTROOM-NO WATER	MACADI ADDED WATER REPLACED FOGGY WINDOW	RESTROOM-NO WATER FOGGY WINDOW UPPER LEVEL
SCAX206	06/19/2014 SCAX206-221776	-	1502: R/R DOOR MISSING RUBBER DOOR STOP		APPLIED RUBBER DOOR STOP, NO ISSUES REPORTED AT TIME OF RELEASE.	R/R DOOR MISSING RUBBER DOOR STOP
SCAX206 SCAX206	01/22/2014 SCAX206-180095 11/07/2013 SCAX206-160275		1300: DESTINATION SIGN B/O. NOT SHOWING 1502: LUMINESCENT STRIP COMING OFF A END STAIRS	12: DESTINATION SIGN B/O. NOT SHOWING 12: BROKEN	REBOOTED AND CHECKED, WORKING PROPERLY. No Correction Entered	DESTINATION SIGN B/O. NOT SHOWING LUMINESCENT STRIP COMING OFF A END STAIRS
SCAX206	11/06/2013 SCAX206-160273		1605: B/O WATER SEAL	12: BROKEN	No Correction Entered	B/O WATER SEAL
SCAX206	08/09/2013 SCAX206-134817		106: ALL ROTORS HAVE THERMAL CRACKS	12: BROKEN	No Correction Entered	ALL ROTORS HAVE THERMAL CRACKS
SCAX206 SCAX206	07/03/2013 SCAX206-123157 06/10/2013 SCAX206-115011			12: PAX	REPORT COMPLETED NO DEFECTS FOUND	PASSENGER INJURY
SCAX206	06/07/2013 SCAX206-115011 06/07/2013 SCAX206-114512				REPLACED KIT. DDSIGNOFF DOORS WORKING AS INTENDED. DDSIGNOFF.	OPEN FIRST AID KIT DOORS-JAMMED
SCAX206	05/29/2013 SCAX206-112019	ECMS02-2013-1279	1400: WINDOWS-WINDOWS CRACKED/BROKEN	No Failure/Cause Entered	No Correction Entered	WINDOWS-WINDOWS CRACKED/BROKEN
SCAX206	04/04/2013 SCAX206-91282	No Work Order Assigned		40 PROVEN	FILLED. DDSIGNOFF.	R/R NO BIOCIDE
SCAX206 SCAX206			915: B END MR ANGLE COCK HANDLE BROKE OFF 1605: R/R LOCKED OUT. FLUSH CONTROLLER B/O	12: BROKEN 12: BROKEN	REPLACED HANDLE. DDSIGNOFF. WATER ADDED. DDSIGNOFF.	B END MR ANGLE COCK HANDLE BROKE OFF R/R LOCKED OUT. FLUSH CONTROLLER B/O
SCAX206	01/03/2013 SCAX206-60139		1602: R/R HOLDING TANK FULL	12: BROKEN	TANK EMPTY BY LABORER. DDSIGNOFF.	R/R HOLDING TANK FULL
SCAX206		No Work Order Assigned	900: MISC-DEBRIS STRIKE/DAMAGE	12: BROKEN	REPLACED CUT OUT COCK. DDSIGNOFF.	MISC-DEBRIS STRIKE/DAMAGE
SCAX206 SCAX206	12/24/2012 SCAX206-58343 12/19/2012 SCAX206-56837		1600: RESTROOM-NO BIOCIDE 1400: WINDOWS-WINDOWS CRACKED/BROKEN	12: BROKEN 12: BROKEN	BIOCIDE CART NOT IN SERVICE. PER M99 DDSIGNOFF. REPLACED AT OLP. DDSIGNOFF.	RESTROOM-NO BIOCIDE WINDOWS-WINDOWS CRACKED/BROKEN
SCAX206	12/18/2012 SCAX206-56438		1005: LOST DOOR COMPLETE CIRCUIT DUE TO LVPS	12: BROKEN	ADJUSTED OUT PIT LUPS. DDSIGNOFF.	LOST DOOR COMPLETE CIRCUIT DUE TO LVPS
SCAX206	10/02/2012 SCAX206-32831		607: LOST EMERGENCY BATTERY POWER EN ROUTE	12: BROKEN	INSPECTED BATTERIES THEY ARE CHARGING. EMERGENCY LIGHT WORKING.	LOST EMERGENCY BATTERY POWER EN ROUTE
SCAX200	09/12/2012 SCAX206-26390	_		12: BROKEN	DDSS REPLACED PER DDSS	LIGHT OUT AT ST #110
SCAX206	09/06/2012 SCAX206-26390 09/06/2012 SCAX206-24498		1200: LIGHT OUT AT ST #110 1601: TOILET PAPER ROLL HOLDER MISSING	15: VANDALS	REPLACED DURING DAILY INSPECTION PROCESS	TOILET PAPER ROLL HOLDER MISSING
SCAX206	08/22/2012 SCAX206-20219	No Work Order Assigned	1605: R/R HOLDING TANK LEAKS WATER ON TOP WHEN REPLENESHING	12: FITTING LOOSE	ADJUSTED FITTING PER DDSS	R/R HOLDING TANK LEAKS WATER ON TOP WHEN REPLENESHING WATER
		_	WATER			TOTAL TOTAL TENES WATER ON TOP WHEN REPLETED WATER
SCAX206 SCAX206	08/09/2012 SCAX206-16185 07/11/2012 SCAX206-215		1600: RESTROOM-NO BIOCIDE 1200: BOTH DESTINATION SIGN LIGHTS B/O	12: BROKEN 12: BROKEN	MACADI ADDED BIOCIDE PER DDSS REPLACED DURING PM INSPECTION	BOTH DESTINATION SIGN LIGHTS B/O
SCAX206	05/25/2012 SCAX206-212		1141: PASSENGER INJURY. REFUSED MEDICAL ATTN.	12: NO DEFECTS NOTED	INSPECTION COMPLETED	PASSENGER INJURY. REFUSED MEDICAL ATTN.
SCAX206	05/16/2012 SCAX206-211		1009: DOORS-A END DOOR LATCH B/O	12: BROKEN	DOORLATCH REPAIRED PER DAILY DEFECT SIGN OFF SHEET	DOORS-A END DOOR LATCH B/O
SCAX206 SCAX206	05/07/2012 SCAX206-210 04/18/2011 SCAX206-193		917: RR - MISC-GRAFFITI DAMAGE 1200: LIGHTING-LIGHTS OUT/DEFECTIVE	12: BROKEN No Failure/Cause Entered	CLEANED OFF GRAFFITI PER SMP129 LIGHT BULB HAS BEEN REPLACED	RR - MISC-GRAFFITI DAMAGE RIGHT SIDE "DOOR OPEN" INDICATOR LIGHT IS BURNT OUT
					REBOOT BATTERY CHARGER CIRCUIT BREAKER AND RESTORED LVP. HVAC'S	RIGHT SIDE DOOR OF EN INDICATOR EIGHT IS BORNT OUT
SCAX206	02/14/2011 SCAX206-191		1121: SIDE DOOR DOES NOT OPEN	No Failure/Cause Entered	AND DOORS WORKING OR.	SIDE DOOR DOES NOT OPEN
SCAX206 SCAX211	08/26/2004 SCAX206-70	ECMS02-2004-1694		No Failure/Cause Entered	No Correction Entered CLEANED	TDACHLINDED CEAT 76
SCAX211	02/18/2015 SCAX211-292171 02/18/2015 SCAX211-292170		1141: MAUL MISSING FROM EMERGENCY TOOLS	No Failure/Cause Entered No Failure/Cause Entered	NOT IN STOCK	TRASH UNDER SEAT 76 MAUL MISSING FROM EMERGENCY TOOLS
SCAX211	08/08/2014 SCAX211-235769	No Work Order Assigned	1600: RESTROOM-NO WATER	12: BROKEN	WATER ADDED	RESTROOM-NO WATER
SCAX211	07/29/2014 SCAX211-232749	No Work Order Assigned	1602: R/R HOLDING TANK IS FULL	12: BROKEN	UNCLOGGED AND DUMPED TANK	R/R HOLDING TANK IS FULL
SCAX211	07/18/2014 SCAX211-229056	No Work Order Assigned	700: EXTERIOR WHITE INDICATOR CONTINUOUSLY ON	12: INSPECTED AND TESTED ALL DOORS, FOUND WHITE EXTERIOR INDICATOR LIGHT STAYS ON, ALL DOORS OPERATE AS INTENDED, UNABLE TO	INSPECTED AND TESTED ALL DOORS, FOUND WHITE EXTERIOR INDICATOR LIGHT STAYS ON, ALL DOORS OPERATE AS INTENDED, UNABLE TO IDENTIFY	EXTERIOR WHITE INDICATOR CONTINUOUSLY ON
00/01211	07,10,2011	The Trent Gradi Aldeigned	730. 271 2 1101 THE 113 107 11 01 TO 11 11 10 10 10 10 10 10 10 10 10 10 10	IDENTIFY SOURCE, CREW WILL BE NOTIFIED.	SOURCE, CREW WILL BE NOTIFIED.	
	06/09/2014 SCAX211-220339	ECMS02-2014-524	100: BRAKES-BRAKES WILL NOT APPLY-RELEASE-MAINTAIN	No Failure/Cause Entered	No Correction Entered	
	06/05/2014 SCAX211-219647 05/06/2014 SCAX211-209539	ECMS02-2014-524	1502: PEI SYSTEM ACTIVATED 1302: PA-IC INOPERATIVE	12: BROKEN No Failure/Cause Entered	No Correction Entered FURTHER INSPECTION AT CMF	PA-IC INOPERATIVE
			1602: R/R HOLDING TANK IS FULL	12: BROKEN	SANITIZED AND INSPECTED OK FOR SERVICE	R/R HOLDING TANK IS FULL
	04/04/2014 SCAX211-199117				ADDED WATER	RESTROOM-NO WATER
	03/12/2014 SCAX211-193968 02/28/2014 SCAX211-191093		1103: HVAC FAULTS ON BOTH ENDS 1500: SEATS-SEATS LOOSE-TORN-DIRTY	12: BROKEN No Failure/Cause Entered	No Correction Entered No Correction Entered	HVAC FAULTS ON BOTH ENDS SEATS-SEATS LOOSE-TORN-DIRTY
			1004: DOORS-DOOR CONTROL STATION DEFECTIVE	12: ACTIVATION KNOB ON DOOR STATION #3 NEEDS TO BE REPLACED	REPLACED DOOR STATION #3 KNOB. WORKING AS INTENDED.	DOORS-DOOR CONTROL STATION DEFECTIVE
SCAX211	02/06/2014 SCAX211-184369	No Work Order Assigned	1001: DOOR #8 WOULD NOT CLOSE	12: CONDUCTOR REPORTED TO CHIEF DISPATCHER THAT THEY HAD DOOR	PERFORM CONSIST DOOR CHECK, UNABLE TO DUPLICATE FAILURE. DOORS	DOOR #8 WOULD NOT CLOSE
	22.2.2.1.10.300			ISSUES AND IS ASKING FOR PERMISSION TO GO INTO DOOR OVERRIDE. 12: CONDUCTOR REPORTS OPERATING DOORS FROM CAR #1 (C #211)	WORKING AS INTENDED. TECH INSPECTED AND TESTED C#211 DOOR STATIONS, TECH REPORTS DOOR	
90 A VO44	02/04/2014 202700	No Work Order A:	4000- DOORS SIDE DOORS WILL NOT OREN	OPENED DOORS AND ONLY CARS #1-2 OPENED OK AND CARS #3-4-5-6 DIDN'T	STATION AT DOOR #4 OPEN AND CLOSE BUTTONS HAVE TO BE HELD FOR 3	
SUAX211	02/04/2014 SCAX211-183/92	IND WORK Order Assigned	1000: DOORS-SIDE DOORS WILL NOT OPEN	OPEN. CONDUCTOR HAD TO GO UP TO CAR #3 (C #103 TO GET DOORS TO	SECONDS TO OPEN AND CLOSE PROPERLY. TECH TESTED ALL OTHER DOOR	DOORS-SIDE DOORS WILL NOT OPEN
<u> </u>		-		OPEN. 12: THERE IS A BROKEN EMERGENCY WINDOW ON THE UPPER LEVEL NEAR	STATIONS AND VERIFIED OPEN AND CLOSE OK.	
SCAX211	01/17/2014 SCAX211-179505	No Work Order Assigned	1400: EMERGENCY WINDOW BROKEN UPPER LEVEL	ST #76.	REPLACED EMERGENCY WINDOW ON THE UPPER LEVEL NEAR ST #76.	EMERGENCY WINDOW BROKEN UPPER LEVEL
	01/14/2014 SCAX211-177717		907: MISC-PA/IC INOPERATIVE	No Failure/Cause Entered	No Correction Entered	MISC-PA/IC INOPERATIVE
SCAX211	01/08/2014 SCAX211-176420	No Work Order Assigned	1502: BIKE RESTRAINT WON'T UN-COUPLE	46: MISSING PIN	HARDWARE FOUND INSTALLED BACK IN. 01/09 VERIFIED THAT THE PULL RING CABLE WAS RESET AND WORKING AS	BIKE RESTRAINT WON'T UN-COUPLE
SCAX211	01/02/2014 SCAX211-174986	No Work Order Assigned	1008: DOORS-EMERGENCY DOOR PULL ACTIVATED	12: CONDUCTOR HAD TO RESET PULL RING CABLE ASSEMBLY.	VERIFIED THAT THE PULL RING CABLE WAS RESET AND WORKING AS INTENDED/	DOORS-EMERGENCY DOOR PULL ACTIVATED
SCAX211	12/17/2013 SCAX211-171125	ECMS04-2014-214	1001: DOOR GETS STUCK IN THE DOOR POCKET WHEN CLOSING	12: BROKEN	No Correction Entered	DOOR GETS STUCK IN THE DOOR POCKET WHEN CLOSING
			1304: RECONNECT PEI CONTROL BOXES LOCATED AT THE BOTTOM OF EACH			RECONNECT PEI CONTROL BOXES LOCATED AT THE BOTTOM OF EACH
SCAX211	12/16/2013 SCAX211-170776	No Work Order Assigned	STAIRCASE AND IN THE RESTROOM. VERIFY THE IC AND PA COMMUNICATIONS REMAIN UNAFFECTED. DO NOT REMOVE THE SYSTEM	No Failure/Cause Entered	BOXES CONNECTED - 12/18/2013	STAIRCASE AND IN THE RESTROOM. VERIFY THE IC AND PA COMMUNICATIONS REMAIN UNAFFECTED. DO NOT REMOVE THE SYSTEM
00/0/211	12/10/2010 00/01211 170770	140 Work Order Abbigned	INACTIVE LABELS OVER SELECTION BUTTON ON FRONT OF EACH CONTROL	No Fallato, oddoo Efficioa	BOALD COMMEDIES 12/10/2010	INACTIVE LABELS OVER SELECTION BUTTON ON FRONT OF EACH CONTROL
			BOX.			BOX.
	12/13/2013 SCAX211-170432 11/27/2013 SCAX211-166376		1502: BUGS SEEN NEAR BOTH HANDICAP SEATS 1103: HVAC-NOT OPERATIONAL	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	BUGS SEEN NEAR BOTH HANDICAP SEATS HVAC-NOT OPERATIONAL
	11/27/2013 SCAX211-166376 11/27/2013 SCAX211-166371	ECMS04-2014-214 ECMS04-2014-214	1605: RESTROOM-TOILET LEAKS/CONTINUOUSLY RUNNING	12: BROKEN	No Correction Entered No Correction Entered	RESTROOM-TOILET LEAKS/CONTINUOUSLY RUNNING
SCAX211	11/26/2013 SCAX211-165984	ECMS04-2014-214	1605: SEQUENCING VALVE B/O	12: BROKEN	No Correction Entered	SEQUENCING VALVE B/O
	11/22/2013 SCAX211-165925	ECMS04-2014-214	1605: RESTROOM-TOILET LEAKS	No Failure/Cause Entered	No Correction Entered	RESTROOM-TOILET LEAKS
	11/22/2013 SCAX211-165344 11/14/2013 SCAX211-162845	ECMS04-2014-214 ECMS04-2014-214	1600: RESTROOM-NO WATER 1600: RESTROOM-NO WATER	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	RESTROOM-NO WATER RESTROOM-NO WATER
SCAX211	11/11/2013 SCAX211-161895	ECMS04-2014-214	1605: R/R LOCKED OUT. B/O SYNC VALVE	12: BROKEN	No Correction Entered	R/R LOCKED OUT. B/O SYNC VALVE
SCAX211	10/29/2013 SCAX211-156898	ECMS02-2013-1622	1605: RESTROOM-TOILET LEAKS FROM BEHIND R/R WALL	12: BROKEN	REPAIRED AT S AND I	RESTROOM-TOILET LEAKS FROM BEHIND R/R WALL
SCAX211	10/28/2013 SCAX211-155857	ECMS02-2013-1622	1600: RESTROOM-NO WATER	12: BROKEN	PUSH BUTTON FOUND DEFECTIVE (MISSING HARDWARE) REPAIRED	RESTROOM-NO WATER
SCAX211	10/25/2013 SCAX211-154940	ECMS02-2013-1622	1009: B/O SPRING ON B END DOOR	12: BROKEN	REPAIRED	B/O SPRING ON B END DOOR
SCAX211	10/24/2013 SCAX211-154890	ECMS02-2013-1622	1602: RESTROOM-TOILET FULL/PLUGGED	No Failure/Cause Entered	PUSH BUTTON FOUND DEFECTIVE (MISSING HARDWARE)	RESTROOM-TOILET FULL/PLUGGED
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	. ,			REPAIRED	

March Control Contro	EQUIP	DATE SERVICE	WORK	SYMPTOM	FAILURE		
Section Control Cont							
Column C					-		
March Marc	SCAX211		ECMS02-2013-1622	1600: RESTROOM-NO WATER		PUSH BUTTON FOUND DEFECTIVE (MISSING HARDWARE)	RESTROOM-NO WATER
April Control Contro							
Control Cont							
April Control Contro	SCAX211	10/01/2013 SCAX211-148715	ECMS02-2013-1622	1600: RESTROOM-NO WATER	12: BROKEN		RESTROOM-NO WATER
Prop. Prop	SCAX211	09/24/2013 SCAX211-147367	No Work Order Assigned	1600: RESTROOM-NO WATER			RESTROOM-NO WATER
Column							
Color Colo	JUANZIII	09/13/2013 3CAX211-144923	LOWIS02-2013-1022	1003. STNOTINO VALVE BIO	12. DROKEN		STNOTING VALVE BIO
ACCUST CARDING CONTINUES CARDING CONTINU	SCAX211	09/13/2013 SCAX211-144924	ECMS02-2013-1622	1502: ROACH INFESTATION IN R/R	12: BROKEN		ROACH INFESTATION IN R/R
Company Comp						INSPECTED DURING PM NO ROACHES FOUND	
Section Control Cont							
The content of the							
		08/12/2013 SCAX211-135422			12: BROKEN	No Correction Entered	B END HVAC HAS A TAG AS LOCKED OUT TO BE CUT FOR REPAIRS
Control Cont							
Control Cont							
Proceedings							
Control Cont							
Control Cont							
		07/10/2013 SCAX211-125056	No Work Order Assigned	1600: RESTROOM-NO WATER	12: PAX USE	FILLED PER SMP129	
					12: PAX		
	SCAX211	05/10/2013 SCAX211-105015	No Work Order Assigned	1600: RESTROOM-NO WATER		ADDED WATER BY MACADI. DDSIGNOFF.	
					No Failure/Cause Entered		D/D LIGI DING TANK IS FULL
Mode		04/03/2013 SCAX211-89123	ECMS02-2013-757	1502: NO FIRST AID KIT		No Correction Entered	
Control Cont							
	SCAX211	03/20/2013 SCAX211-85091	No Work Order Assigned	1602: RESTROOM-TOILET FULL/PLUGGED			RESTROOM-TOILET FULL/PLUGGED
	SCAX211	03/19/2013 SCAX211-84895	No Work Order Assigned	0: CARD FILES REPROGRAMMED	12: CARD FILES REPROGRAMMED	CARD FILES REPROGRAMMED	CARD FILES REPROGRAMMED
PACKED GOLDAN PACKED SOUTH P							
Part							
CACAPT C					No Failure/Cause Entered		OT EN ELVEL EMERGENO TAMBON EXTERNOL BEOME INIOGNIC
DOCUMENT DOCUMENT DOCUMENT TOTAL TIME DOCUMENT DOCUMEN	00.4.7.044	00/45/0040 000 000	No Mode Order Assistant	ACCC. DECEDOOM TOURET LEAVO	40. 1547/10		DEGIT DOOM TON ET LEAVO
ECAST CREATING	SCAX211	02/15/2013 SCAX211-75224	No Work Order Assigned	1605: RESTROOM-TOILET LEAKS	18: LEAKING	DDSIGNOFF/MG	
DOUGHT D	SCAX211	02/08/2013 SCAX211-73081	No Work Order Assigned	1602: RESTROOM-TOILET FULL/PLUGGED	12: CLUGGED	FOUND CLUG AT TOILET TANK. REMOVED CLUG ADJUSTED SEQUENCE VALVE	RESTROOM-TOILET FULL/PLUGGED
AUGST SOUTH SOUT						DDSIGNOFF	
Control Cont	SCAX211	02/04/2013 SCAX211-70717	No Work Order Assigned	1602: HOLDING TANK FULL ; TOILET CLUGGED			HOLDING TANK FULL; TOILET CLUGGED
SACK111 100922033 SACK111-96629 Now Man Older Aleganger 1000 ST 655 SOLED 12 BROKEN REPLACED DURFO CA DISSIANCE*** SACK111-100721 SACK111-100	SCAX211	01/18/2013 SCAX211-64643	No Work Order Assigned	1605: RESTROOM-TOILET LEAKS	12: BROKEN		RESTROOM-TOILET LEAKS
SOACH 1927/2012 SOACH-19472 ECMBC 2019-2019 ECMBC 2019-2	SCAX211	01/02/2013 SCAX211-59629	No Work Order Assigned	1500: ST #53 SOILED	12: BROKEN		ST #53 SOILED
SACAPI 1247-01 50-021-1-1021 50-021-1-	SCAX211	01/02/2013 SCAX211-59628	No Work Order Assigned	1605: NO DUMP CAP	12: BROKEN		
SACATI 1924-0079 SACATI	SCAX211	12/27/2012 SCAX211-58712	ECMS02-2012-3867	1600: RESTROOM-TOILET PUMP NOT WORKING	12: BROKEN		
SCA2011 10240071 20A201-19300 100-RESTROOM FOUR FULL FULL FULGED 12-BROKEN INCLOGGED BY MINE G. DORS SCA21-19200 SCA21-19201 100-RESTROOM FOUR FULL MISSING COVER 12-BROKEN INCLOGGED BY MINE G. DORS SCA21-19201 100-RESTROOM FOUR FULL MISSING COVER 12-BROKEN INCLOGGED BY MINE G. DORS SCA21-19201 100-RESTROOM FOUR FULL MISSING COVER 12-BROKEN INCLOGGED BY MINE G. DORS SCA21-19201 100-RESTROOM FOUR FULL MISSING COVER 12-BROKEN INCLOGGED BY MINE G. DORS SCA21-19201 100-RESTROOM FOUR FULL MISSING COVER BY A SCA21-19201 100-RESTROOM FULL MISSING COVER BY A SCA21-1920	SCAX211	12/24/2012 SCAX211-58332	No Work Order Assigned	917: GRAFFITI ETCHED ON R/R MIRROR	12: BROKEN		GRAFFITI ETCHED ON R/R MIRROR
SCA2011 10002012 SCA2011-45888 No Vino Corear Assigned 500 SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS SEATS - ELECTRICAL CUTLET MISSING COVER 2. BROWEN LOWER WATER PROFESS 2. BROWEN LOWER WATER PROFE							
SCA2011 1020/2012 SCA2011-14872 ECMISO2-2012-3550 BOST RANSPORMER CREATING PER PREPRIATION DESSENSE ECMISOR CREATING PER PRESE TO DESS							SEATS- ELECTRICAL OUTLET MISSING COVER
SCA2211 1169/2012 SCA2211-4288 1600 RESTROOMHO WATER 12 BROKEN 12	SCAX211	11/20/2012 SCAX211-48721	ECMS02-2012-3553	1605: DRINKING FOUNTAIN LEAKING			
SCA2211 1195/2012 SCA2211-42845 NO Work Corder Assigned 1400 EMERGENCY ACCESS STICKER BIO OUTSIDE DOOR 3 12 BROKEN REPLACED DOSS EMERGENCY ACCESS STICKER BIO OUTSIDE DOOR 3 12 BROKEN CALLED ROTENT DIAGNOSE PROBLEM SIMP129 SCA2211-3099 EMERGENCY ACCESS STICKER BIO OUTSIDE DOOR 3 12 BROKEN CALLED ROTENT DIAGNOSE PROBLEM SIMP129 SCA2211-3299 EMERGENCY ACCESS STICKER BIO OUTSIDE DOOR 3 12 BROKEN CALLED ROTENT DIAGNOSE PROBLEM SIMP129 SCA2211-3297 EMERGENCY ACCESS STICKER BIO OUTSIDE DOOR 3 SCA2211-3297 EMBORING STICKER BIO OUTSIDE DOOR 3 EMB							
SCA2211 1019/2012 SCA2211-5906 ECMS02-2012-3002 300 P.A.P. A INDEPENDENT 12: BROKEN CALLED ROTEM TO DIAGNOSE PROBLEM. SMP1/29			No Work Order Assigned	1400: EMERGENCY ACCESS STICKER B/O OUTSIDE DOOR #3			EMERGENCY ACCESS STICKER B/O OUTSIDE DOOR #3
SCA2211 1090/2012 SCA2211-32987 EXBOSC 2012-2889 15022 END VESTIBULE CURTAIN TORN 12. BROKEN SERVICE AT CMP							
SCAZ211 1091/2012 SCAZ211-30330 ECMSQ-2012-2869 1602- RESTROOM-TOILET FULKPUIGED 12 BROKEN REPARED BY ROTEM PER DDSS							B END VESTIBULE CURTAIN TORN
SCAA211 0924/2012 SCAA211-39314 ECMS02-2012-2669 1905: RESTROOM-TOLIET LEAKS 12: HOSE BROKEN REPAIRED BY ROTES BY ROTE B	SCAX211	10/01/2012 SCAX211-32579	ECMS02-2012-2884	1602: RESTROOM-TOILET FULL/PLUGGED	12: BROKEN		
SCAX211 09/10/2012 SCAX211-2499 NO LEAN FROM BEHIND WALL NEXT TO DRINKING FOUNTAIN 12: NDF NO LEAN FROM BEHIND WALL NEXT TO DRINKING FOUNTAIN 12: NDF SCAX211 09/10/2012 SCAX211-2499 100: NDF ACKED MARKED 100: RESTROOM NO WATER 12: USE FILLED WATER TANK FER DDSS FILLED WATER T							
SCAX211 9907/2012 SCAX211-2996 No Work Order Assigned 1500: SEATS-SEATS LOOSE-TORN-DIRTY 12: PAX LITTER SCHEDURE OF RUMINGATION 09 12 2012 SCAX211-1277 SCAX211-1277 ECMS02.2012-2295 1600: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1600: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1600: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1610: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1610: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1610: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1610: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1610: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1277 ECMS02.2012-2295 1610: RESTROOM-NO WATER 12: USE FILLED WATER TANK PER DDSS SCAX211-1278 No Work Order Assigned 140: WATER TANK PER DDSS SCAX211-1278 No Work Order Assigned 140: WATER TANK PER DDSS SCAX211-1278 No Work Order Assigned 140: WATER TANK PER DDSS SCAX211-1278 SCAX211-1285 SCAX211-1285 No Work Order Assigned 140: WATER TANK PER DDSS SCAX211-1285 SCAX211-1285 No Work Order Assigned 140: WATER TANK PER DDSS 12: BROKEN No Correction Entered HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR SCAX211-1285 SCAX211-1285 No Work Order Assigned HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR SCAX211-1285 SCAX211-1285 No Work Order Assigned HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR SCAX211-1285							
SCA2211 089142012 SCA2211-147277 ECMS02-2012-2302 1000: DOOR 53 WOULD ONLY OPEN HALF WAY 12: ANTI RATTLE DEVICE FOUND LAYING IN BOTTOM DOOR TRACK FIXED BY ROTEM PER SMP129 SCA2211-18018 ECMS02-2012-2252 1111 E BEND VESTIBULE CURTAIN SECOND 12: BROKEN REPUACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN 12: BROKEN REPUACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN BROKEN / VESTIBULE CURTAIN 12: BROKEN REPUACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN BROKEN / VESTIBULE CURTAIN 12: BROKEN REPUACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN REPUACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN BROKEN REPUACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN BROKEN / SERVICE PER DDSS CANSC11-18353 CANS					12: PAX LITTER		SEATS-SEATS LOOSE-TORN-DIRTY
SCA2/11 08/09/2012 SCA2/211-16178 ECMS02-2012-2225 1411 B END VESTIBULE CURTAIN SO 12 BROKEN REPUACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN 12 BROKEN REPLACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN 12 BROKEN REPLACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN 12 BROKEN REPLACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN 12 BROKEN REPLACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN 13 BROKEN / VESTIBULE CURTAIN 1411 BROKEN / VESTIBULE CURTAIN 1411 BROKEN / VESTIBULE CURTAIN 15 BROKEN REPLACED DAILY INSPECTION REPLACED PER DAILY DEFECT SIGN OFF SHEET REPLACED PER DAILY DEFECT SIGN OFF S							
SCA2211 07/39/2012 SCA2211-11246 NO Work Order Assigned 1141: BROKEN / VESTIBULE CURTAIN 12: BROKEN REPLACED DURING DAILY INSPECTION BROKEN / VESTIBULE CURTAIN 12: BROKEN No Correction Entered HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8535 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-8259 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-224 ECMS02-2012-1078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-224 ECMS02-2012-1078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-224 ECMS02-2012-1030 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-224 ECMS02-2012-1030 ECMS02-2012-1030 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-224 ECMS02-2012-1030 ECMS02-2012-1030 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-224 ECMS02-2012-1030 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012 SCA2211-224 ECMS02-2012-1030 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS OF CAR 107/19/2012							
SCA2211 07/18/2012 SCA2211-8253 ECMS02-2012-2078 1103: HVAC-NOT OPERATIONAL ON BOTH ENDS 12: BROKEN No Correction Entered HVAC-TOO HOT No Correction Entered HVAC-TOO HOT HVAC-TOO	SCAX211	07/30/2012 SCAX211-11246	No Work Order Assigned	1141: BROKEN / VESTIBULE CURTAIN	12: BROKEN	REPLACED DURING DAILY INSPECTION	
SCA211 07/17/2012 SCA211-255 ECMS02-2012-2078 1100: HVAC-TOO HOT No Correction Entered HVAC-TOO HOT							
SCAX211 07/06/2012 SCAX211-235 No Work Order Assigned 1400: WINDOWS-WINDOWS CRACKED/BROKEN 12: BROKEN 12: BROKEN REPLACED PER DDS SCAX211-234 ECMS02-2012-1853 ECMS02-2012-1853 ECMS02-2012-1853 ECMS02-2012-1854 ECM					IZ: DRUKEN		
SCAX211 06/19/2012 SCAX211-233 ECMS02-2012-1711 1602: RESTROOM-TOILET FULL/PLUGGED 12: BROKEN UNCLOGGED PER DAILY DEFECT SIGN OFF SHEET RESTROOM-TOILET FULL/PLUGGED SCAX211 06/18/2012 SCAX211-232 ECMS02-2012-1888 1602: R/R HOLDING TANK WONT DUMP 12: BROKEN UNCLOGGED PER DDSS R/R HOLDING TANK WONT DUMP SCAX211 06/06/2012 SCAX211-232 ECMS02-2012-1638 1602: R/R HOLDING TANK WONT DUMP 12: BROKEN SCAX211 04/04/2012 SCAX211-231 ECMS02-2012-1630 1602: RSTROOM-TOILET FULL/PLUGGED 12: +USE SCAX211 04/04/2012 SCAX211-224 ECMS02-2012-1630 1000: DORS-SIDE DOORS WILL NOT OPEN 12: INSPECTED SCAX211 02/14/2012 SCAX211-223 ECMS02-2012-477 1602: RESTROOM-TOILET FULL/PLUGGED No Failure/Cause Entered SCAX211 12/14/2011 SCAX211-220 ECMS02-2011-2282 ECMS02-2011-2282 TH41: BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS SCAX211 12/14/2011 SCAX211-220 ECMS02-2011-2282 TH41: BROKEN EMERGENCY PULL RING COVER BEDIATED BY BOMBADIED BROKEN EMERGENCY PULL RING COVER BEDIATES	SCAX211	07/06/2012 SCAX211-235	No Work Order Assigned	1400: WINDOWS-WINDOWS CRACKED/BROKEN		REPLACED AT CMF	WINDOWS-WINDOWS CRACKED/BROKEN
SCAX211 06/18/2012 SCAX211-232 ECMS02-2012-1688 1602: R/R HOLDING TANK WONT DUMP SCAX211 06/06/2012 SCAX211-231 ECMS02-2012-1563 1602: RESTROOM-TOILET FULL/PLUGGED SCAX211 04/04/2012 SCAX211-231 ECMS02-2012-1030 1000: DOORS-SIDE DOORS WILL NOT OPEN SCAX211 04/04/2012 SCAX211-224 ECMS02-2012-1030 1000: DOORS-SIDE DOORS WILL NOT OPEN 12: INSPECTED SCAX211 02/14/2012 SCAX211-223 ECMS02-2012-1030 1000: DOORS-SIDE DOORS WILL NOT OPEN 12: INSPECTED SCAX211 12/14/2011 SCAX211-223 ECMS02-2012-477 1602: RESTROOM-TOILET FULL/PLUGGED SCAX211 12/14/2011 SCAX211-220 ECMS02-2011-2282 ECMS02-2012-477 1602: RESTROOM-TOILET FULL/PLUGGED SCAX211 12/14/2011 SCAX211-220 ECMS02-2011-2282 ECM							
SCAX211 06/06/2012 SCAX211-231 ECMS02-2012-1563 1602: RESTROOM-TOILET FULL/PLUGGED 12: +USE UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET RESTROOM-TOILET FULL/PLUGGED 12: HUSE UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET RESTROOM-TOILET FULL/PLUGGED 12: HUSE UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET RESTROOM-TOILET FULL/PLUGGED 12: HUSE UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET DOORS WILL NOT OPEN 12: INSPECTED DOORS-SIDE DOORS WILL NOT OPEN 12: INSPECTED DOORS-SIDE DOORS WILL NOT OPEN 12: HUSE UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET DOORS-SIDE DOORS WILL NOT OPEN 12: HUSE UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET DOORS-SIDE DOORS WILL NOT OPEN 12: INSPECTED DOORS-SIDE DOORS WILL NOT OPEN 12: INSPECTED DOORS-SIDE DOORS WILL NOT OPEN 12: INSPECTED DOORS-SIDE DOORS WILL NOT OPEN 12: HUSE UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET DOORS-SIDE DOORS WILL NOT OPEN 12: HUSE DOORS-SIDE DOORS-SIDE DOORS WILL NOT OPEN 12: HUSE DOORS-SIDE DOORS WILL NOT OPEN 12: HUSE DOORS-SIDE DOORS-SID							
SCAX211 02/14/2012 SCAX211-223 ECMS02-2012-477 1602: RESTROOM-TOILET FULL/PLUGGED No Failure/Cause Entered WATERED AND DUMPED DURING DAILY INSPECTION PROCESS RESTROOM-TOILET FULL/PLUGGED SCAX211 12/14/2011 SCAX211-220 ECMS02-2011-2282 ECMS02-2011-2282 T141: BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS PER DAILY DEFECT SHEET NO REPLACEMENTS AVAILABLE PER ROTEM BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS PER DAILY DEFECT SHEET BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS No Failure/Cause Entered No Failure/Cause Entered BROKEN COVER PER DAILY DEFECT SHEET BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS No Failure/Cause Entered BROKEN COVER PER DAILY DEFECT SHEET BROKEN EMERGENCY PULL RING COVER B/O @ A-END STAIRS		06/06/2012 SCAX211-231	ECMS02-2012-1563	1602: RESTROOM-TOILET FULL/PLUGGED	12: +USE	UNCLOGGED TOILETS PER DAILY DEFECT SIGN OFF SHEET	RESTROOM-TOILET FULL/PLUGGED
SCAX211 12/14/2011 SCAX211-220 ECMS02-2011-2282 1141: BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS PER DAILY DEFECT SHEET NO REPLACEMENTS AVAILABLE PER ROTEM NO REPLACEMENTS AVAILABLE PER ROTEM BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS PER DAILY DEFECT SHEET NO REPLACEMENTS AVAILABLE PER ROTEM BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS PER DAILY DEFECT SHEET BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS NO Failure/Cause Entered NO Failure/Cause Entered BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS PER DAILY DEFECT SHEET BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS NO Failure/Cause Entered NO Failure/Cause Entered BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS NO Failure/Cause Entered NO FAIlure/Cause Entered NO FAIlure/Cause Entered NO FAIlure/Cause Entered BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS NO FAIlure/Cause Entered NO FAIlure/Cause Entered NO FAIlure/Cause Entered							
SCAY211 12/14/2011 SCAY211 219 ECMS02 2011 2281 1141: BROKEN EMERGENCY PULL RING COVER B/O @ A-END STAIRS BROKEN EMERGENCY PULL RING COVER B/O @ A-END STAIRS			ECMS02 2011 2202	1141: BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS			BROKEN CAR NUMBER DECAL MISSING ON BOTTOM OF A-END STAIRS
	SCAX211	12/14/2011 SCAX211-219	ECMS02-2011-2281	1141: BROKEN EMERGENCY PULL RING COVER B/O @ A-END STAIRS	No Failure/Cause Entered	REPLACE BROKEN COVER. REPAIRED BY BOMBARDIER.	BROKEN EMERGENCY PULL RING COVER B/O @ A-END STAIRS

EQUIP	DATE	SERVICE	WORK	SYMPTOM	FAILURE	CORRECTION COMMENT	WARRANTY COMPLAINT
ID	REPORTED	SCAX211-218	ORDER ID ECMS02-2011-2229	COMMENT 1141: BROKEN EMERGENCY BRAKE PULL COVER MISSING	COMMENT No Failure/Course Entered	RESECURED COVER TO WALL	BROKEN EMERGENCY BRAKE PULL COVER MISSING
SCAX211 SCAX211	12/08/2011	SCAX211-216 SCAX211-217	ECMS02-2011-2229	PER DAILY DEFECT SHEET 1141: BROKEN BIKE STRAPS MISSING	No Failure/Cause Entered	CONSUMABLE. PART NOT IN STOCK. ON ORDER. NO ETA PER TOM FROM	PER DAILY DEFECT SHEET BROKEN BIKE STRAPS MISSING
SCAZII	12/08/2011			PER DAILY DEFECT SHEET 1007: DOORS-JAMMED RESTROOM DOOR STUCK CLOSED	No Failure/Cause Entered	MATERIAL CONTROL.	PER DAILY DEFECT SHEET DOORS-JAMMED RESTROOM DOOR STUCK CLOSED
SCAX211	11/25/2011	SCAX211-215	ECMS02-2011-2100	PER DAILY DEFECT SHEET	No Failure/Cause Entered	REPLACED DOOR PER DAILY DEFECT SIGN OFF SHEET	PER DAILY DEFECT SHEET
SCAX211	11/10/2011	SCAX211-214		1605: RESTROOM LEAKS 915: MISC-POOR RIDE QUALITY-LATERAL-BOUNCE-VIBRATION	No Failure/Cause Entered	No Correction Entered	RESTROOM LEAKS MISC-POOR RIDE QUALITY-LATERAL-BOUNCE-VIBRATION
SCAX211	11/04/2011	SCAX211-212	ECMS02-2011-1869	COUPLER CARRIER BOLTS BROKEN	12: BROKEN- CARRIER BOLTS- BOTH	No Correction Entered	COUPLER CARRIER BOLTS BROKEN
SCAX211 SCAX211	10/20/2011 10/12/2011	SCAX211-206 SCAX211-205	ECMS02-2011-1711 ECMS02-2011-1625	1602: TOILET PLUGGED R/R LOCKED OUT PER DAILY DEFECT SHEET 1601: TOILET B/O	No Failure/Cause Entered No Failure/Cause Entered	TOILET UNCLOG PER DAILY DEFECT SIGN OFF SHEET M.L.	TOILET PLUGGED R/R LOCKED OUT PER DAILY DEFECT SHEET TOILET B/O
SCAX211	10/12/2011	SCAX211-205 SCAX211-204	ECMS02-2011-1629	1004: STAFF KEY @ DOOR 4 NOT WORKING AS INTENDED	No Failure/Cause Entered	UNCLOGGED PER DAILY DEFECT SIGN OFF SHEET J.E. ADJUST LIMIT SWITCH OF STAFF KEY - PER DAILY DEFECT SIGN OFF SHEET	STAFF KEY @ DOOR 4 NOT WORKING AS INTENDED
SCAX211	10/12/2011	SCAX211-204 SCAX211-203	ECMS02-2011-1610	1141: BROKEN BIKE STRAPS MISSING	No Failure/Cause Entered	INSTALL BIKE STRAPS AT CAR 211 AND 243 C.M.	BROKEN BIKE STRAPS MISSING
SCAX211	10/06/2011	SCAX211-202	ECMS02-2011-1504	1601: RESTROOM-TOILET ODOR - PER DAILY DEFECT SHEET	No Failure/Cause Entered	UNCLOGGED PER DAILY DEFECT SIGN OFF	RESTROOM-TOILET ODOR - PER DAILY DEFECT SHEET
SCAX211	09/22/2011	SCAX211-201	ECMS02-2011-1440	1602: RESTROOM-TOILET FULL/PLUGGED	No Failure/Cause Entered	UNCLOGGED PER DAILY DEFECT SHEET	RESTROOM-TOILET FULL/PLUGGED
SCAX211	06/08/2011	SCAX211-197	ECMS02-2011-769	1000: DOORS-SIDE DOORS WILL NOT OPEN AT BALDWIN PARK 10 CARRY BY S		No Correction Entered	DOORS-SIDE DOORS WILL NOT OPEN AT BALDWIN PARK 10 CARRY BY'S
SCAX211 SCAX211	04/01/2011	SCAX211-181 SCAX211-180	ECMS02-2011-409 ECMS02-2011-385	1001: DOORS-SIDE DOORS WILL NOT CLOSE 1201: LIGHTING-EMERGENCY LIGHTING DEFECTIVE CAR IS DARK.	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	ODD-NUMBERED DOORS LIGHTING-EMERGENCY LIGHTING DEFECTIVE CAR IS DARK.
SCAX211	03/31/2011	SCAX211-179	ECMS02-2011-346	1001: DOORS-SIDE DOORS WILL NOT CLOSE	No Failure/Cause Entered	No Correction Entered	DOORS-SIDE DOORS WILL NOT CLOSE
SCAX211 SCAX211	03/31/2011	SCAX211-178 SCAX211-177	ECMS02-2011-408 ECMS02-2011-328	1001: DOORS-SIDE DOORS WILL NOT CLOSE 1300: PA-PA INOPERATIVE	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	ODD-NUMBERED DOORS DID NOT FULLY CLOSE PA-PA INOPERATIVE
SCAX211	03/23/2011	SCAX211-177		1114: HVAC NOT OPERATIONAL	No Failure/Cause Entered	No Correction Entered	HVAC NOT OPERATIONAL
SCAX211	02/07/2011	SCAX211-164		1121: SIDE DOOR DOES NOT OPEN	No Failure/Cause Entered	UNABLE TO DUPLICATE.	SIDE DOOR DOES NOT OPEN
SCAX211 SCAX211	02/04/2011 01/26/2011	SCAX211-163 SCAX211-161	No Work Order Assigned ECMS02-2011-61	1121: SIDE DOOR DOES NOT OPEN - ONCE EACH SIDE 1141: BROKEN - WATER ON FLOOR OUTSIDE OF RESTROOM	No Failure/Cause Entered No Failure/Cause Entered	TESTED NO DEFECT FOUND . CONDUCTOR DIDNT HOLD BUTTON DOWN No Correction Entered	SIDE DOOR DOES NOT OPEN - ONCE EACH SIDE BROKEN - WATER ON FLOOR OUTSIDE OF RESTROOM
SCAX211	01/17/2011	SCAX211-159	ECMS02-2011-49	1114: HVAC NOT OPERATIONAL (HOT CAR)	No Failure/Cause Entered	No Correction Entered	HVAC NOT OPERATIONAL (HOT CAR)
SCAX211 SCAX211	01/14/2011 01/13/2011	SCAX211-157 SCAX211-156	ECMS02-2011-49 ECMS02-2011-49	1064: WINDOW CRACKED / BROKEN 1114: NOT OPERATIONAL HVAC HOT CAR	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	WINDOW CRACKED / BROKEN NOT OPERATIONAL HVAC HOT CAR
SCAX263	02/23/2015	SCAX263-293167	ECMS02-2015-576	1605: WATER LEAKING FROM BEHIND R/R WALL	12: BROKEN	No Correction Entered	
SCAX263 SCAX263		SCAX263-265423 SCAX263-254224	· ·	1400: WINDOWS-WINDOWS CRACKED/BROKEN 1602: R/R HOLDING TANK IS FULL	No Failure/Cause Entered 12: BROKEN	No Correction Entered DRAINED HOLDING TANK	WINDOWS-WINDOWS CRACKED/BROKEN R/R HOLDING TANK IS FULL
SCAX263	08/07/2014	SCAX263-235561	No Work Order Assigned	1600: R/R NO BIOCIDE	12: BROKEN	BIOCIDE ADDED	R/R NO BIOCIDE
SCAX263		SCAX263-230560		1300: DESTINATION SIGN B/O. ERROR CODE DC-61 AND 62	12: BROKEN 12: CONDUCTOR REPORTS THE FIRST THREE CARS IN THE CONSIST HAVE	No Correction Entered	DESTINATION SIGN B/O. ERROR CODE DC-61 AND 62
SCAX263	02/25/2014	SCAX263-189248	No Work Order Assigned	1602: RESTROOM-TOILET FULL/PLUGGED	OUT OF SERVICE RESTROOMS.	TOILET UNCLOGGED, ADDED WATER. WORKING AS INTENDED.	RESTROOM-TOILET FULL/PLUGGED
SCAX263		SCAX263-188884	ŭ	1602: RESTROOM-TOILET FULL/PLUGGED	12: CONDUCTOR REPORTS C #256 & C #263 R/R LOCKED OUT DUE TO CLOGGED TOILET.	UNCLOGGED TOILET, ADDED WATER. WORKING AS INTENDED.	RESTROOM-TOILET FULL/PLUGGED
SCAX263 SCAX263		SCAX263-185656 SCAX263-185094		1502: FIRE EXTINGUISHER EXPIRES 2-14-14 UPPER LEVEL 1600: RESTROOM-NO WATER	12: FIRE EXTINGUISHER EXPIRES 2-14-14 UPPER LEVEL 12: RESTROOM-NO WATER	CHANGED OUT FIRE EXTINGUISHER WITH GOOD DATE. MACADI ADDED WATER.	FIRE EXTINGUISHER EXPIRES 2-14-14 UPPER LEVEL RESTROOM-NO WATER
SCAX263	01/31/2014	SCAX263-182395	No Work Order Assigned	1502: PASSENGER URINATED ON FLOOR AND SEAT	12: CONDUCTOR REPORTS THAT A PASSENGER URINATED ON C #263 BY ST #131-132. THE SEAT CUSHION AND THE FLOOR ARE DRENCHED WITH URINE.	REPLACED SEAT; SEAT COVER BOTTOM 2P FLIP UP BENCH SEAT ROTEM	PASSENGER URINATED ON FLOOR AND SEAT
SCAX263				1400: B/O WINDOW ST #120	12: B/O WINDOW ST #120	REPLACED WINDOW ST #120	B/O WINDOW ST #120
SCAX263 SCAX263				1400: WINDOWS-WINDOWS CRACKED/BROKEN 1400: WINDOWS-WINDOWS CRACKED/BROKEN	12: WINDOWS-WINDOWS CRACKED/BROKEN No Failure/Cause Entered	REPLACED WINDOW ST #120 REPLACED WINDOW ST #120	WINDOWS-WINDOWS CRACKED/BROKEN WINDOWS-WINDOWS CRACKED/BROKEN
				1304: RECONNECT PEI CONTROL BOXES LOCATED AT THE BOTTOM OF EACH			
SCAX263	12/16/2013	SCAX263-170828	ECMS02-2013-1798	STAIRCASE AND IN THE RESTROOM. VERIFY THE IC AND PA COMMUNICATIONS REMAIN UNAFFECTED. DO NOT REMOVE THE SYSTEM INACTIVE LABELS OVER SELECTION BUTTON ON FRONT OF EACH CONTROL BOX.	No Failure/Cause Entered	PEI CONNECTED 12/18 AT SB	
SCAX263	10/15/2013	SCAX263-152497	ECMS02-2013-1798	106: ROTOR # 1 AND 3 IMPROPER TABS	12: BROKEN	No Correction Entered	ROTOR # 1 AND 3 IMPROPER TABS
SCAX263		SCAX263-146974		1602: R/R LOCKED OUT. TANK CLOGGED 1502: B END VESTIBULE CURTAIN WONT RETRACT	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	R/R LOCKED OUT. TANK CLOGGED B END VESTIBULE CURTAIN WONT RETRACT
				1502: FLOOR/STAIRS-LOOSE-BROKEN-DEFECTIVE	No Failure/Cause Entered	No Correction Entered	FLOOR/STAIRS-LOOSE-BROKEN-DEFECTIVE
				1604: DRINKING WATER HANDLE B/O LEAKE SPRAYS FLOOR 1300: NO P.A. C-AMP B/O	12: WW 12: TESTED AT CMF	CALLED ROTEM TO FIX PER SMP`129 NO DEFECT FOUND PER DDSS	DRINKING WATER HANDLE B/O LEAKE SPRAYS FLOOR NO P.A. C-AMP B/O
				1300: NO F.A. C-AMF B/O	12: C AMP TRIPPED BREAKER	RESET AND TESTED PER OLP REPORT	PA-PA INOPERATIVE
				1500: SEATS NEED CLEANING 700: THERMAL CRACKS ON ALL WHEELS		CLEANED SEATS: 30,36,6,4. DDSIGNOFF. NON - CONDEMNABLE THERMAL CRACKS. DDSIGNOFF.	SEATS NEED CLEANING THERMAL CRACKS ON ALL WHEELS
SCAX263	05/22/2013	SCAX263-109531	No Work Order Assigned	1400: UPPER LEVEL EMERGENCY WINDOW DECAL MISSING BY ST #39-40		DECAL ADDED. DDSIGNOFF.	UPPER LEVEL EMERGENCY WINDOW DECAL MISSING BY ST #39-40
		SCAX263-100684 SCAX263-84947		No Symptom Entered 0: NO FAILURE CODE PROVIDED	No Failure/Cause Entered	No Correction Entered No Correction Entered	
SCAX263 SCAX263	03/15/2013	SCAX263-84272	No Work Order Assigned	1600: TOILET FLAPPER NO OPENING.	No Failure/Cause Entered	ADJUSTED SEQUENCE VALVE. DDSIGNOFF.	TOILET FLAPPER NO OPENING.
SCAX263			No Work Order Assigned	1605: DRINKING FAUCET LEAKS	No Failure/Cause Entered	ROTEM NEEDS PARTS. CUT OUT WATER. DDSIGNOFF. No Correction Entered	DRINKING FAUCET LEAKS
				No Symptom Entered 1604: WATER RUNS IN TOILET	No Fallure/Cause Entered 18: LEAKING	REPLACED SEQUENCE VALVE. DDSIGNOFF./MG	WATER RUNS IN TOILET
SCAX263	02/12/2013	SCAX263-74132	No Work Order Assigned	1502: ST #74 ELECTRICAL COVER MISSING	44. WODN	COVER NOT IN STOCK, DDSIGNOFF.	ST #74 ELECTRICAL COVER MISSING
SCAX263 SCAX263				1600: RESTROOM-NO WATER 1605: DRINKING FAUCET WILL NOT SHUT-OFF	44: WORN 12: BROKEN	WATER ADDED. NO LEAKS FOUND. DDSIGNOFF. NO PARTS. CUT- OUT. DDSIGNOFF.	RESTROOM-NO WATER DRINKING FAUCET WILL NOT SHUT-OFF
SCAX263	01/08/2013	SCAX263-61285	No Work Order Assigned	1605: DRINKING FOUNTAIN WILL NOT STOP RUNNING	12: BROKEN	REPLACED DURING DAILY SERVICING PROCESS	DRINKING FOUNTAIN WILL NOT STOP RUNNING
SCAX263 SCAX263	01/07/2013 01/04/2013	SCAX263-61010 SCAX263-60462		915: DRINKING FAUCET B/O. CUT-OUT 1600: RESTROOM-NO WATER	12: BROKEN 12: USAGE	PARTS NOT IN STOCK REPORTED TO ROTEM. DDSIGNOFF. FILLED DURING DAILY SERVICING PROCESS	DRINKING FAUCET B/O. CUT-OUT RESTROOM-NO WATER
SCAX263	12/11/2012	SCAX263-54700		1605: RESTROOM-TOILET LEAKS	12: BROKEN	NO LEAK FOUND. FLUSHED DUMP TANK, REMOVED CLUG FROM DUMP TANK. DDSIGNOFF	
SCAX263	12/07/2012	SCAX263-53120	ECMS02-2012-3710	1605: RESTROOM-TOILET LEAKS	12: BROKEN	NO LEAK FOUND. FLUSHED DUMP TANK TESTED SYSTEM NO DEFECTS FOUND, DDSIGNOFF.	
SCAX263	12/05/2012	SCAX263-51340	ECMS02-2012-3651	1600: RESTROOM INSPECTION	12: BROKEN	WATER ADDED FOUND BAD CHECK VALVE FIREMAN SIDE ADVISED ROTEM, (WARRANTY), DDSS	
SCAX263	11/19/2012	SCAX263-48332	ECMS02-2012-3534	1600: RESTROOM-NO WATER	12: BROKEN	WATER ADDED FOUND BAD CHECK VALVE FIREMAN SIDE ADVISED	
SCAX263	11/16/2012	SCAX263-48142	ECMS02-2012-3517	1602: RESTROOM-TOILET FULL/PLUGGED	12: BROKEN	ROTEM.(WARRANTY). DDSS NO CLUG FOUND, TESTED SYSTEM NO DEFECT FOUND. DDSS	
SCAX263	11/01/2012	SCAX263-42114	ECMS02-2012-3363	1600: RESTROOM-NO WATER, B/O CHECK VALVE (FIREMAN SIDE)	12: BROKEN	ADVISED STV AND ROTEM WARRANTY ISSUE. DDSS	NEW MOD INCOPPOTION
SCAX263 SCAX263		SCAX263-41057 SCAX263-40579		1600: NEW MOD INSPECTION 1600: RESTROOM-NO WATER	12: BROKEN 12: BROKEN	NO DEFECTS FOUND. DDSS ADDED WATER (NO LEAKS FOUND). DDSS	NEW MOD INSPECTION
SCAX263	10/10/2012	SCAX263-34913	ECMS02-2012-3117	1600: RESTROOM-NO WATER	12: BROKEN	FILLED UP WATER. DDSS	WATER FOUNTAIN LEAVING FROM LAND F
SCAX263 SCAX263		SCAX263-32854 SCAX263-28128		1605: WATER FOUNTAIN LEAKING FROM HANDLE 1600: RESTROOM-NO WATER	12: BROKEN 12: USE	WATER FOUNTAIN FAUCET NOT IN STOCK PER ROTEM. DDSS SERVICED PER SMP129	WATER FOUNTAIN LEAKING FROM HANDLE
SCAX263	08/09/2012	SCAX263-16187	ECMS02-2012-2259	1602: RESTROOM-TOILET FULL/PLUGGED	12: BROKEN	TOILET UNCLOGGED PER DDSS	
SCAX263 SCAX263		SCAX263-10955 SCAX263-10443		1141: R/R TOILET IS OUT OF SYNC 1602: RESTROOM-TOILET FULL/PLUGGED	12: BROKEN 12: USE	No Correction Entered RR IN SERVICE WATERED AND DUMPED PER DDSS	
					•		

EQUIP	DATE	SERVICE	WORK	SYMPTOM	FAILURE	CORRECTION COMMENT	WARRANTY COMPLAINT
SCAX263	06/27/2012	SCAX263-8	ORDER ID ECMS02-2012-1832	COMMENT 1602: R/R LOCKED OUT. OUT OF SYNC	COMMENT 12: CLOGGED	REMOVED PER DAILY INSPECTION SHEET	
SCAX263	05/21/2012	SCAX263-5		1007: DOORS-JAMMED DOOR #7	12: NDF	TESTED NO DEFECT FOUND PER SMP129	DOORS-JAMMED DOOR #7
SCAX263	05/16/2012	SCAX263-4		1000: DOORS-SIDE DOORS WILL NOT OPEN	12: BROKEN	No Correction Entered	DOORS-SIDE DOORS WILL NOT OPEN
SCAX645		SCAX645-293986		900: STRUCK VEHICLE AT MP 406.23. SEVERE DAMAGE	12: BROKEN	No Correction Entered	DOORS SIDE BOOKS WILL HOT OF EN
SCAX645		SCAX645-292176		1141: LOOSE HANDRAIL SEAT 115	No Failure/Cause Entered	HADRAIL FOUND SECURE	LOOSE HANDRAIL SEAT 115
SCAX645	02/18/2015	SCAX645-292177	No Work Order Assigned	1141: NO DRINKING WATER COMING FROM SPOUT	No Failure/Cause Entered	CUT-IN FOUNTAIN, OK FOR SERVICE	NO DRINKING WATER COMING FROM SPOUT
SCAX645				1141: MAUL MISSING FROM EMERGENCY TOOLS	No Failure/Cause Entered	NOT IN STOCK	MAUL MISSING FROM EMERGENCY TOOLS
SCAX645		SCAX645-289115		1141: MAUL MISSING FROM EMERGENCY TOOLS	No Failure/Cause Entered	NOT IN STOCK	MAUL MISSING FROM EMERGENCY TOOLS
SCAX645				1141: STAFF KEY COVER SPRING BROKEN - DOOR 3	No Failure/Cause Entered	NOT IN STOCK	STAFF KEY COVER SPRING BROKEN - DOOR 3
SCAX645		SCAX645-289116		1141: PORTABLE MARKER LIGHT MISSING	No Failure/Cause Entered	NOT IN STOCK	PORTABLE MARKER LIGHT MISSING
SCAX645 SCAX645		SCAX645-289113		1141: DUMP CAP MISSING 1141: PASSENGER INJURY REPORT	No Failure/Cause Entered 12: BROKEN/	PREVIOUSLY REPLACED PASSENGER INJURY REPORT COMPLETED WITH NO DEFECTS NOTED.	DUMP CAP MISSING PASSENGER INJURY REPORT
				700: SHELLING AXLE #1 BOTH WHEELS/AXLE #2 MULTIPLE FLAT SPOTS 1/2 TO	1		SHELLING AXLE #1 BOTH WHEELS/AXLE #2 MULTIPLE FLAT SPOTS 1/2 TO 1
SCAX645	12/05/2014	SCAX645-273230	No Work Order Assigned	INCH LONG	12: BROKEN	WHEELS TRUED 12/5	INCH LONG
SCAVE4E	12/04/2014	CCAVC4E 070007	No Work Order Assistant	700: WHEELS 2-4 MULTIPLE FLAT SPOTS FROM 1/2 INCH TO 1 INCH AT TIME OF	12. PROVEN	CUT OUT AND WHEEL CITIED 42/F	WHEELS 2-4 MULTIPLE FLAT SPOTS FROM 1/2 INCH TO 1 INCH AT TIME OF
SCAX645	12/04/2014	SCAX645-273027	No Work Order Assigned	INSPECTION	12: BROKEN	CUT OUT AND WHEELS TRUED 12/5	INSPECTION
SCAX645		SCAX645-272897		1500: SEATS-SEATS LOOSE-TORN-DIRTY	22: MISALIGNED	No Correction Entered	PEDESTAL INCORRECTLY ORIENTED
SCAX645		SCAX645-272428		609: MARKER LIGHT B/O	12: BROKEN	MARKER LIGHT WORKING. NO DEFECTS FOUND	MARKER LIGHT B/O
SCAX645	11/21/2014	SCAX645-268424	No Work Order Assigned	903: MAIN RESERVOIR IS 10 PSI LESS THAN THE LOCOMOTIVE MR		QUALIFIED BOTH AIR GAUGES, HAD TO ADJUST MAIN RES GAUGE.	MAIN RESERVOIR IS 10 PSI LESS THAN THE LOCOMOTIVE MR
SCAX645	10/30/2014	SCAX645-262254	No Work Order Assigned	1000: DOORS INTERMITTENTLY WON'T OPEN FROM L/S DOOR STATION	12: BROKEN	DOORS INSPECTED AND TESTED MULTIPLE TIMES DURING DAILY INSPECTION NO DEFECTS FOUND.	DOORS INTERMITTENTLY WON'T OPEN FROM L/S DOOR STATION
				1300: AUTOMATED ANNOUNCEMENTS DO NOT ACKNOWLEDGE ON CERTAIN		INO DEFECTS FOUND.	
SCAX645	10/17/2014	SCAX645-256028	ECMS02-2014-1080	TRAINS	12: BROKEN	No Correction Entered	AUTOMATED ANNOUNCEMENTS DO NOT ACKNOWLEDGE ON CERTAIN TRAINS
SCAX645	08/26/2014	SCAX645-241668	ECMS02-2014-823	700: NON-CONDEMNABLE FLAT SPOTS 1 TO 1 1/2 INCHES LONG	12: BROKEN	No Correction Entered	NON-CONDEMNABLE FLAT SPOTS 1 TO 1 1/2 INCHES LONG
SCAX645		SCAX645-240100		700: FLAT SPOTS B END	12: BROKEN	WHEELS REPLACED	FLAT SPOTS B END
SCAX645		SCAX645-240041	ECMS02-2014-823	1605: R/R TOILET FLAPPER DOES NOT SEAL	12: BROKEN	No Correction Entered	R/R TOILET FLAPPER DOES NOT SEAL
SCAX645		SCAX645-236118		909: FRONT SUN VISOR B/O. UNABLE TO TIGHTEN DOWN	12: BROKEN	No Correction Entered	FRONT SUN VISOR B/O. UNABLE TO TIGHTEN DOWN
SCAX645	07/18/2014	SCAX645-228884	ECMS02-2014-649	1200: OVERHEAD LIGHT OUT LOWER LEVEL L/S CENTER	12: BROKEN	No Correction Entered	OVERHEAD LIGHT OUT LOWER LEVEL L/S CENTER
SCAX645	07/11/2014	SCAX645-226556	No Work Order Assigned	700: FLAT SPOTS B END. NON-CONDEMNABLE	12: BROKEN	PERFORMED WHEEL INSPECTION, ALL WHEELS STILL WITHIN COMPLIANCE	FLAT SPOTS B END. NON-CONDEMNABLE
				700: WHEEL #4 FLAT SPOT 1 1/2 INCHES LONG. WHEEL #3 FLAT SPOT 1 1/2			WHEEL #4 FLAT SPOT 1 1/2 INCHES LONG. WHEEL #3 FLAT SPOT 1 1/2 INCHES
SCAX645	07/09/2014	SCAX645-226018	No Work Order Assigned	INCHES LONG	12: BROKEN	PERFORMED WHEEL INSPECTION, ALL WHEELS STILL WITHIN COMPLIANCE.	LONG
SCAX645	07/08/2014	SCAX645-225992	ECMS02-2014-649	608: HEADLIGHT SWITCH DEFECTIVE	12: BROKEN	No Correction Entered	HEADLIGHT SWITCH DEFECTIVE
SCAX645	07/08/2014	SCAX645-225817	No Work Order Assigned	700: WHEEL #4 HAS 1 1/4 INCH FLAT SPOT		PERFORMED WHEEL INSPECTION, ALL WHEELS STILL WITHIN COMPLIANCE.	WHEEL #4 HAS 1 1/4 INCH FLAT SPOT
			-			,	
SCAX645		SCAX645-223588	ECMS02-2014-649	1004: P.A. PLUG LOCKING TAB BROKEN ON DOOR CONTROL STATION 1-3	12: BROKEN	No Correction Entered	P.A. PLUG LOCKING TAB BROKEN ON DOOR CONTROL STATION 1-3
SCAX645 SCAX645		SCAX645-211394 SCAX645-202970		700: B END ALL WHEELS HAVE THERMAL CRACKS 1400: WINDOWS-WINDOWS CRACKED/BROKEN/VISOR	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	B END ALL WHEELS HAVE THERMAL CRACKS WINDOWS-WINDOWS CRACKED/BROKEN/VISOR
SCAX645	03/18/2014	SCAX645-195299	No Work Order Assigned	609: R/S DITCH LIGHT IS INOPERATIVE	12: CONDUCTOR REPORTS THE R/S DITCH LIGHT IS OUT ON CC #645.	QMP REPLACED DEFECTIVE DITCH LIGHT. VERIFIED OPERATION OF LIGHTS.	R/S DITCH LIGHT IS INOPERATIVE
SCAX645	03/18/2014	SCAX645-194953	No Work Order Assigned	610: OVERHEAD ENGINEERS LIGHT B/O		REPLACED OVERHEAD ENGINEER LIGHT, WORKING AS INTENDED.	OVERHEAD ENGINEERS LIGHT B/O
SCAVEAE					12: WHEELS 1-2-5-7 HAVE 1 INCH TO 2 1/4 INCH FLAT SPOTS	PERFORM WHEEL INSPECTION, NO DEFECTS TO ADDRESS. STILL WITHIN IN	WHEELS 1.2 F. 7 HAVE 1 INCH TO 2.1/4 INCH ELAT SPOTS
SCAX645	03/17/2014	SCAX645-194415	No work Order Assigned	700: WHEELS 1-2-5-7 HAVE 1 INCH TO 2 1/4 INCH FLAT SPOTS	12: WHEELS 1-2-5-7 HAVE I INCH TO 2 1/4 INCH FLAT SPOTS	TOLERANCE.	WHEELS 1-2-5-7 HAVE 1 INCH TO 2 1/4 INCH FLAT SPOTS
SCAX645	03/17/2014	SCAX645-194413	No Work Order Assigned	915: REPORTED FOR ROUGH RIDER		INSPECTED TRUCKS, STOCKS, WHEELS, LINERS FOR ANY USUAL WEAR FOR	REPORTED FOR ROUGH RIDER
			g			DEFECTS.	
SCAX645	03/11/2014	SCAX645-193614	No Work Order Assigned	700: WHEELS-FLAT SPOTS/SHELLING	12: BROKEN	PERFORMED WHEEL INSPECTION, NO DEFECTS TO REPORT. ALL WHEELS STILL WITHIN TOLERANCE.	WHEELS-FLAT SPOTS/SHELLING
SCAX645	03/11/2014	SCAX645-193613	No Work Order Assigned	1200: LIGHTING-LIGHTS OUT/DEFECTIVE		REPLACED DEFECTIVE LIGHTS. ALL LIGHTS WORKING AS INTENDED.	LIGHTING-LIGHTS OUT/DEFECTIVE
SCAX645				1200: LIGHTING-LIGHTS OUT/DEFECTIVE	12: OVERHEAD LIGHT B/O	REPLACED OVERHEAD LIGHT. TESTED OK.	LIGHTING-LIGHTS OUT/DEFECTIVE
SCAX645	03/07/2014			700: WHEELS-FLAT SPOTS/SHELLING	12: REPORTED FOR FLAT-SPOTS /SHELLING.	PERFORMED WHEEL INSPECTION UPON CMF ARRIVAL, FOUND NO DEFECTS	WHEELS-FLAT SPOTS/SHELLING
					12. REPORTED FOR FLAT-SPOTS /SHELLING.	ON WHEELS, STILL WITHIN TOLERANCE.	WHEELS-FLAT SPOTS/SHELLING
SCAX645	03/06/2014	SCAX645-192720	No Work Order Assigned	1141: PASSENGER INJURY	No Failure/Cause Entered	INSPECTION COMPLETED. NO TRIPPING HAZARDS IDENTIFIED ON CONSIST	PASSENGER INJURY
SCAX645	03/04/2014	SCAX645-191819	No Work Order Assigned	700: #2 TRUCK WHEELS 3 AND 4 HAVE SHELL OUTS AND FLAT SPOTS	12: WHEELS-FLAT SPOTS/SHELLING/CAR SHAKES AT 50 MPH. FLATS SPOTS ARE NON-CONDEMNABLE.OLP	No Correction Entered	#2 TRUCK WHEELS 3 AND 4 HAVE SHELL OUTS AND FLAT SPOTS
SCAY645				700: #2 TRUCK WHEELS 3 AND 4 HAVE SHELL OUTS AND FLAT SPOTS	12: #2 TRUCK WHEELS 3 AND 4 HAVE SHELL OUTS AND FLAT SPOTS	PERFORM WHEEL INSPECTION, STILL WITHIN TOLERANCE.	#2 TRUCK WHEELS 3 AND 4 HAVE SHELL OUTS AND FLAT SPOTS
						PERFORM WHEEL INSPECTION, STILLL WITHIN TOLERANCE. NO DEFECTS TO	
SCAX645	02/14/2014	SCAX645-187436	No Work Order Assigned	700: WHEELS-FLAT SPOTS/SHELLING	No Failure/Cause Entered	ADDRESS AT THE TIME OF RELEASE.	WHEELS-FLAT SPOTS/SHELLING
					12: CONDUCTOR ALSO REPORTS CC #645 POSSIBLY HAS FLAT SPOTS. WHILE		
SCAX645	02/14/2014	SCAX645-186499	No Work Order Assigned	700: WHEELS-FLAT SPOTS/SHELLING	IN THE CAB CAR THE CONDUCTOR COULD HEAR WHAT SOUNDS TO HER LIKE	TOLERANCE	WHEELS-FLAT SPOTS/SHELLING
					FLAT SPOTS ON THE BEND R/S OF CC #645.	10111011101	
					12: CONDUCTOR REPORTS PRIOR TO ARRIVING TO RVS HE COULD HEAR A		
SCAX645	02/11/2014	SCAX645-185667	No Work Order Assigned	700: WHEELS-FLAT SPOTS	POSSIBLE FLAT SPOT COMING FROM THE B END OF CC #645. ONCE THEY ARRIVED TO RVS THE CONDUCTOR INSPECTED THE WHEELS AND FOUND THE	PERFORM WHEEL INSPECTION, STILL WITHIN TOLERANCE.	WHEELS-FLAT SPOTS
					FLAT SPOT ON WHEEL #3.	-	
SCAX645	01/13/2014	SCAX645-177028	ECMS02-2014-47	1500: SEATS-SEATS LOOSE-TORN-DIRTY	No Failure/Cause Entered	No Correction Entered	SEATS-SEATS LOOSE-TORN-DIRTY
SCAX645		SCAX645-174077		804: TAKES A LONG TIME FOR PCS TO RESET	12: BROKEN	No Correction Entered	TAKES A LONG TIME FOR PCS TO RESET
SCAX645	12/23/2013	SCAX645-172943	ECMS04-2014-74	001: TAKES A LONG TIME TO RECOVER FROM EMERGENCY	12: BROKEN	No Correction Entered	TAKES A LONG TIME TO RECOVER FROM EMERGENCY
	T			1304: RECONNECT PEI CONTROL BOXES LOCATED AT THE BOTTOM OF EACH			RECONNECT PEI CONTROL BOXES LOCATED AT THE BOTTOM OF EACH
				STAIRCASE AND IN THE RESTROOM. VERIFY THE IC AND PA			STAIRCASE AND IN THE RESTROOM. VERIFY THE IC AND PA
SCAX645	12/16/2013	SCAX645-170863	No Work Order Assigned	COMMUNICATIONS REMAIN UNAFFECTED. DO NOT REMOVE THE SYSTEM	No Failure/Cause Entered	No Correction Entered	COMMUNICATIONS REMAIN UNAFFECTED. DO NOT REMOVE THE SYSTEM
				INACTIVE LABELS OVER SELECTION BUTTON ON FRONT OF EACH CONTROL BOX.			INACTIVE LABELS OVER SELECTION BUTTON ON FRONT OF EACH CONTROL BOX.
SCAX645	12/13/2013	SCAX645-170460	ECMS04-2014-74	1400: WINDOWS-WINDOWS CRACKED/BROKEN	No Failure/Cause Entered	No Correction Entered	WINDOWS-WINDOWS CRACKED/BROKEN
SCAX645		SCAX645-169918	ECMS04-2014-74	1502: STRIKER PLATE FOR R/R DOOR HAS STRIPPED BOLT HOLE	12: BROKEN	No Correction Entered	STRIKER PLATE FOR R/R DOOR HAS STRIPPED BOLT HOLE
SCAX645		SCAX645-166342		610: OVERHEAD READING LIGHT IN CAB B/O	12: BROKEN	No Correction Entered	OVERHEAD READING LIGHT IN CAB B/O
SCAX645	11/19/2013	SCAX645-163956	ECMS04-2014-74	1502: HANDICAP DECALS MISSING AT ST #119-120	12: BROKEN	No Correction Entered	HANDICAP DECALS MISSING AT ST #119-120
		SCAX645-159721		900: CAR BODY DAMAGE A END	12: BROKEN	No Correction Entered	CAR BODY DAMAGE A END
		SCAX645-159719		610: OVERHEAD READING LIGHT B/O	12: BROKEN	No Correction Entered	OVERHEAD READING LIGHT B/O
		SCAX645-159450		906: MISC-RADIO INOPERATIVE	No Failure/Cause Entered	No Correction Entered	MISC-RADIO INOPERATIVE
SCAX645 SCAX645		SCAX645-151921 SCAX645-146976		1000: DOORS-SIDE DOORS WILL NOT OPEN 1600: RESTROOM-NO WATER	No Failure/Cause Entered 12: BROKEN	No Correction Entered No Correction Entered	DOORS-SIDE DOORS WILL NOT OPEN RESTROOM-NO WATER
		SCAX645-146976 SCAX645-146925		1007: DOORS-JAMMED	No Failure/Cause Entered	No Correction Entered No Correction Entered	DOORS-JAMMED
SCAX645		SCAX645-146892		1007: R/R DOOR LOCK B/O	12: BROKEN	No Correction Entered	R/R DOOR LOCK B/O
SCAX645		SCAX645-146891		1605: WATER DRIPPING IN BACK OF TOILET	12: BROKEN	No Correction Entered	
SCAX645	09/17/2013	SCAX645-146077	ECMS02-2013-1494	1605: POTABLE WATER RUNS OUT THE TANK FROM UNDERNEATH THE CAR	12: BROKEN	No Correction Entered	
SCAX645		SCAX645-145747		1605: RESTROOM-TOILET LEAKS	12: BROKEN	No Correction Entered	
SCAX645				1502: EMERGENCY TOOL KIT AND A END FIRE EXT PULL SEALS MISSING	12: REPLACED SEAL PER DDSS	No Correction Entered	EMERGENCY TOOL KIT AND A END FIRE EXT PULL SEALS MISSING
SCAX645				700: FADED EMERGENCY DECALS ON BOTH SIDES 1005: LOST DOOR COMPLETE CIRCUIT. DOOR STATION SHOWS DOORS	12: BROKEN	REPLACED.	FADED EMERGENCY DECALS ON BOTH SIDES
SCAX645	08/02/2013	SCAX645-131454	No Work Order Assigned	CLOSED	12: INSPECTED DOOR CIRCUIT AND DO DEFECTS WERE FOUND PER DDSS	No Correction Entered	LOST DOOR COMPLETE CIRCUIT. DOOR STATION SHOWS DOORS CLOSED
SCAX645	07/12/2013	SCAX645-125287	No Work Order Assigned	909: FIREMANS SIDE ELECTRIC MIRROR NOT ADJUSTABLE	12: BROKEN	REPLACED MIROR ASSEMBLY AND ADJUSTED PER DDSS	FIREMANS SIDE ELECTRIC MIRROR NOT ADJUSTABLE
				1602: RESTROOM-TOILET FULL/PLUGGED	12: PAX USE	TOILET UNCLOGGED PER SMP129	RESTROOM-TOILET FULL/PLUGGED
-							

EQUIP ID	DATE REPORTED	SERVICE REQUEST ID	WORK ORDER ID	SYMPTOM COMMENT	FAILURE COMMENT	CORRECTION COMMENT	WARRANTY COMPLAINT
		SCAX645-121675		1000: STAFF KEY COVER SPRING B/O	COMMENT	NIS. AS PER M24. DDSIGNOFF.	
				1502: CONDUCTORS DESK B/O		REPAIRED BY STORAGE. DDSIGNOFF.	CONDUCTORS DESK B/O
				909: FIREMAN SIDE MIRROR DIRTY 1502: FLOOR/STAIRS-LOOSE-BROKEN-DEFECTIVE		CLEANED BY JESSIE. DDSIGNOFF SCHEDULE FOR REPAIR. DDSIGNOFF.	FIREMAN SIDE MIRROR DIRTY FLOOR/STAIRS-LOOSE-BROKEN-DEFECTIVE
SCAX645	05/17/2013	SCAX645-107290	ECMS02-2013-966	1000: STAFF KEY COVER SPRINGS B/O BOTH LEFT AND RIGHT		N.I.S. DDSIGNOFF.	
		SCAX645-107260		900: MISC-DEBRIS STRIKE/DAMAGE	12: BROKEN	No Correction Entered	
		SCAX645-100714 SCAX645-99475		No Symptom Entered 1103: A END HVAC B/O. SFB FAULT TRIPS BREAKER. WILL NOT RESET	No Failure/Cause Entered	No Correction Entered CAR CUT FROM SERVICE. DDSIGNOFF.	A END HVAC B/O. SFB FAULT TRIPS BREAKER. WILL NOT RESET
		SCAX645-98378	FCMS02-2013-534	1103: HVAC-NOT OPERATIONAL ON BOTH ENDS		SCHEDULED TO BE REPAIRED. DDSIGNOFF.	
SCAX645	04/17/2013	SCAX645-95555	No Work Order Assigned	915: THE DOOR BUZZER CAME ON. OPENED THE CONSIST DOORS AND FOUND A PASSENGER GETTING OFF THE EQUIPMENT	No Failure/Cause Entered	NO DEFECT FOUND. DDSIGNOFF.	THE DOOR BUZZER CAME ON. OPENED THE CONSIST DOORS AND FOUND A PASSENGER GETTING OFF THE EQUIPMENT
SCAX645	03/22/2013	SCAX645-86014		304: ENGINEER REPORTS NO MANUAL DYNAMIC BRAKING WHEN RUNNING		CAB FIREMAN SIDE M.U B/O USE ENGINE SIDE. #645 FIREMAN SIDE MU RECEPTACLE BAD. POSIBLY MISWIRED. SWAPPED CABLE TO ENGINEER SIDE DUE TO INSUFFICIENT TIME TO TROUBLESHOOT. DDSIGNOFF	ENGINEER REPORTS NO MANUAL DYNAMIC BRAKING WHEN RUNNING
SCAX645	03/19/2013	SCAX645-85052	ECMS02-2013-534	1200: LIGHTING-LIGHTS OUT/DEFECTIVE	No Failure/Cause Entered	No Correction Entered	
SCAX645	03/19/2013	SCAX645-84974	No Work Order Assigned	LVPS ISSUES- POSSIBLE BURNT OUT LVPS BOARD 0: CARD FILES REPROGRAMMED	12: CARD FILES REPROGRAMMED	CARD FILES REPROGRAMMED	NO FAILURE CODE PROVIDED
	02/20/2013	SCAX645-77777	No Work Order Assigned	1605: TOILET SEAL B/O		REPLACED FLAPPER SEAL. DDSIGNOFF.	TOILET SEAL B/O
		SCAX645-75338	No Work Order Assigned	No Symptom Entered 1502: PASSENGER VOMITED IN CAR	No Failure/Cause Entered 12: BROKEN	No Correction Entered No Correction Entered	PASSENGER VOMITED IN CAR
				610: OVERHEAD LIGHT B/O	12. DROKLIN	REPLACED LIGHT 2/13/2013. DDSIGNOFF.	OVERHEAD LIGHT B/O
	02/12/2013	SCAX645-74629	No Work Order Assigned	901: MISC-SPEED INDICATOR INOPERATIVE		REPAIRED 2/13/2013 BY ROTEM. DDSIGNOFF.	MISC-SPEED INDICATOR INOPERATIVE
		SCAX645-67265		901: MISC-SPEED / AMP INDICATOR INOPERATIVE 700: THERMAL CRACKS ON ALL WHEELS	No Failure/Cause Entered 12: BROKEN	No Correction Entered SCHEDULED FOR WHEEL TRUE	MISC-SPEED / AMP INDICATOR INOPERATIVE THERMAL CRACKS ON ALL WHEELS
		SCAX645-31394 SCAX645-26400	ECMS02-2012-2566		12: LATCH BROKEN	ROTEM REPAIRED	THERWAL GRACKS ON ALL WHILLES
		SCAX645-24490		700: WHEELS-FLAT SPOTS/SHELLING	12: NORMAL	SCHEDULED FOR WHEEL TRUE PER DDSS	
		SCAX645-19650 SCAX645-18356	No Work Order Assigned	1141: L/S ARM CAME APART FROM CONDUCTORS DESK	No Failure/Cause Entered 12: BROKEN	No Correction Entered REPARIED DURING DAILY INSPECTION PROCESS	L/S ARM CAME APART FROM CONDUCTORS DESK
SCAX645 SCAX645		SCAX645-18356 SCAX645-15698	ECMS02-2012-2220		12: NDF	NO DEFECTS FOUND PER DDSS	ES PINNI SAINIE AFAINT I NOINI GUINDUGTUNS DESN
SCAX645	08/06/2012	SCAX645-14846	No Work Order Assigned	608: R/S HEADLIGHT IS OUT	12: BROKEN	REPLACED AT LAUS PER MORNING UPDATE	R/S HEADLIGHT IS OUT
SCAX645				1500: PLACED STAINED SEAT BOTTOM COVER IN CAB CAR NOSE	12: PAX	REPLACED DURING DAILY SERVICING PROCESS FIXED BROKEN ARM RIVET SET BACK IN PLACE IT WORKS AS INTENDED PER	PLACED STAINED SEAT BOTTOM COVER IN CAB CAR NOSE
SCAX645	07/18/2012	SCAX645-8268	ECMS02-2012-1996	1501: CONDUCTORS DESK DEFECTIVE	12: BROKEN	SMP129	
		SCAX645-1493		700: THERMAL CRACKS ON ALL HWEELS ON CAB CAR	12: NON CONDEMNABLE	INSPECTED OK FOR SERVICE	
		SCAX645-1492		1602: RESTROOM-TOILET FULL/PLUGGED	12: USE	UNCLOGGED DURING DAILY SERVICE PROCESS	EDED MICCINIC
			No Work Order Assigned		12: BROKEN	REPLACED PER DAILY DEFECT SIGN OFF SHEET WHEEL #6 HAS 1 3/8" THERMAL CRACK = OK FOR SERVICE PER DAILY DEFECT	FRED MISSING
SCAX645		SCAX645-1184	-	106: ROTOR #6 HAS THERMAL CRACKS	12: BROKEN	SIGN OFF SHEET ONLY 1.3/8 INCH OK FOR SERVICE PER MANUFACTURER SPECS - DAILY DEFET	ROTOR #6 HAS THERMAL CRACKS
SCAX645 SCAX645		SCAX645-1182 SCAX645-1181		106: ROTOR #6 HAS THERMAL CRACKS 1600: RESTROOM-NO WATER	12: BROKEN 12: +USE	SIGN OFF SHEET FILLED WATER PER DAILY DEFECT SIGN OFF SHEET	ROTOR #6 HAS THERMAL CRACKS RESTROOM-NO WATER
		SCAX645-1180		1007: R/R DOORS-JAMMED LOCK PLATE IS LOOSE	12: BROKEN	ADJUSTED HARDWARE WORKING NORMALLY	R/R DOORS-JAMMED LOCK PLATE IS LOOSE
SCAX645	05/08/2012	SCAX645-1179	No Work Order Assigned	1141: HIGH WIDE DETECTION 20.1 AXLE #4	12: BROKEN	CREW REPORTS INSPECTED TRAIN. NO DEFECT FOUND.	HIGH WIDE DETECTION 20.1 AXLE #4
SCAX645	04/24/2012	SCAX645-1178	ECMS02-2012-1097	1600: RESTROOM-NO WATER	12: BROKEN	ADDED WATER WORKING AS INTENDED PER DAILY DEFECT SIGN OFF SHEET	RESTROOM-NO WATER
SCAX645		SCAX645-1177		300: WHEEL SLIP DROPS LOAD ONLY IN CAB CAR LEAD.	12: CHECKED ALL MU CABLE BY PUTTING 3 VOLTS THROUGH TRAINLINE - ALSO EHCEKD AMP GAUGE WIRES	NO DEFECT FOUND PER DAILY DEFECT SIGN OFF SHEET	WHEEL SLIP DROPS LOAD ONLY IN CAB CAR LEAD.
		SCAX645-1176 SCAX645-1175		1141: AIR ISSUES AT CMF YARD 1602: RESTROOM-TOILET FULL/PLUGGED	12: CREW ERROR DETERMINATION 12: +USE	CLASS 1 TESTED OK PER DAILY DEFECT SIGN OFF SHEET UNCLOGGED PER DAILY DEFECT SIGN OFF SHEET	AIR ISSUES AT CMF YARD RESTROOM-TOILET FULL/PLUGGED
SCAX645		SCAX645-1021		1103: HVAC-NOT OPERATIONAL	12: BROKEN	ROTEM CLEARED FAULTS	HVAC-NOT OPERATIONAL
		SCAX645-1020		606: ELECT-CIRCUIT BREAKERS TRIPPED 800: ATS/ALERTOR-INOPERATIVE NO IIATS ALARM	12: BROKEN 12: MAP 8 PERFORMED		ELECT-CIRCUIT BREAKERS TRIPPED
SCAX645 SCAX645		SCAX645-1019 SCAX645-1017		1602: RESTROOM-TOILET FULL/PLUGGED TOILET IS HARD TO FLUSH	12: +USE	OK FOR SERVICE UNCLOGGED PER DAILY DEFECT SIGN OFF SHEET	ATS/ALERTOR-INOPERATIVE NO IIATS ALARM RESTROOM-TOILET FULL/PLUGGED TOILET IS HARD TO FLUSH
SCAX645	03/09/2012	SCAX645-1016		1141: BROKEN/ MR CUT OUT COCK HARD TO REACH	12: DESIGN	WAITING FOR FLEET MOD	BROKEN/ MR CUT OUT COCK HARD TO REACH
		SCAX645-1015 SCAX645-1013		1602: RESTROOM-TOILET FULL/PLUGGED 1141: BROKEN/RADIO HANDSET NOT WORKING PROPERLY	12: NO SEAL ON FLAPPER BROKEN No Failure/Cause Entered	REPLACED BY VTM PER DAILY DEFECT SIGN OFF SHEET ADJUSTED AND TESTED OK FOR SERVICE PER MORNING MEETING	RESTROOM-TOILET FULL/PLUGGED BROKEN/RADIO HANDSET NOT WORKING PROPERLY
		SCAX645-1013 SCAX645-1009		1603: RESTROOM-SINK NOT DRAINING-PLUGGED	No Failure/Cause Entered	No Correction Entered	RESTROOM-SINK NOT DRAINING-PLUGGED
SCAX645	01/20/2012	SCAX645-1008		1141: BROKEN/ R/R DRINKING FOUNTAIN IS LEAKING	No Failure/Cause Entered	REPLACE FOUNTAIN PER DAILY DEFECT SIGN OFF SHEET	BROKEN/ R/R DRINKING FOUNTAIN IS LEAKING
SCAX645 SCAX645	01/17/2012 12/20/2011	SCAX645-1007 SCAX645-694		802: ATS-AUDIBLE ALARM INOPERATIVE 1141: BROKEN/ A END MR ANGLE COCK HARD TO OPEN	No Failure/Cause Entered No Failure/Cause Entered	PERFORMED SMP8 AND PASSED - OK FOR SERVICE VALVE LUBED AND ADJUSTED. OK FOR SERVICE PER BOMBARDIER.	ATS-AUDIBLE ALARM INOPERATIVE BROKEN/ A END MR ANGLE COCK HARD TO OPEN
				1600: RESTROOM-NO WATER NO BIOCIDE			RESTROOM-NO WATER NO BIOCIDE
SCAX645	12/16/2011	SCAX645-693	ECMS02-2011-2308	PER DAILY DEFECT SHEET	No Failure/Cause Entered	FILLED PER DAILY DEFECT SIGN OFF SHEET	PER DAILY DEFECT SHEET
SCAX645	12/15/2011	SCAX645-691	ECMS02-2011-2297	1141: CAUTION WATCH YOUR HEAD DECAL MISSING ABOVE SEAT #9 PER DAILY DEFECT SHEET	No Failure/Cause Entered	NO REPLACEMENTS AVAILABLE PER ROTEM	CAUTION WATCH YOUR HEAD DECAL MISSING ABOVE SEAT #9 PER DAILY DEFECT SHEET
SCAX645	12/14/2011	SCAX645-690	No Work Order Assigned	1400: WINDOWS-WINDOWS CRACKED/BROKEN SMALL NON-EMERGENCY WINDOW.	No Failure/Cause Entered	WINDOW REPLACED DURING DAILY INSPECTION PER CHECKLIST	WINDOWS-WINDOWS CRACKED/BROKEN SMALL NON-EMERGENCY WINDOW.
SCAX645	12/07/2011	SCAX645-689	ECMS02-2011-2359		No Failure/Cause Entered	No Correction Entered	
SCAX645	11/16/2011	SCAX645-686	ECMS02-2011-1963	1141: KEY CONTROL SWITCH SOUNDS ALARM WHEN IN THE OFF POSITION PER DAILY DEFECT SWITCH	No Failure/Cause Entered	RESET DETECTORS AND ALARM WENT AWAY. OK FOR SERVICE.	KEY CONTROL SWITCH SOUNDS ALARM WHEN IN THE OFF POSITION PER DAILY DEFECT SWITCH
SCAX645	11/14/2011	SCAX645-685	ECMS02-2011-1948	609: ELECT-AUXILIARY LIGHT(S) INOPERATIVE	No Failure/Cause Entered	REPLACED AT LAUS PER MORNING MEETING	ELECT-AUXILIARY LIGHT(S) INOPERATIVE
SCAX645	11/08/2011	SCAX645-683	ECMS02-2011-1886	1602: RESTROOM-TOILET FULL/PLUGGED	No Failure/Cause Entered	2ND SHIFT INSTALLED NEW GASKETY DUMPED AND WATERED CAR - TESTS OK FOR SERVICE	RESTROOM-TOILET FULL/PLUGGED
SCAX645	10/28/2011	SCAX645-681	ECMS02-2011-1786	1141: BROKEN EXTERIOR STEP @ DOOR # 1-3 YELLOW SAFETY TAPE IS PEELING OFF PER DAILY DEFECT SHEET	No Failure/Cause Entered	REPLACED TAPE PER DAILY DEFECT SIGN OFF SHEET M.J.	BROKEN EXTERIOR STEP @ DOOR # 1-3 YELLOW SAFETY TAPE IS PEELING OFF PER DAILY DEFECT SHEET
	1		=======================================	1200: LIGHTING-LIGHTS DIM / AMP GAUGE	No Failure/Cause Entered	No Correction Entered	LIGHTING-LIGHTS DIM / AMP GAUGE
SCAX645	10/19/2011	SCAX645-679	ECMS02-2011-1710		i e e e e e e e e e e e e e e e e e e e	NO SPARE RAMP NEEDED DUE TO MODIFIED RAMP IN CAR - PER DAILY	
	10/19/2011 10/13/2011	SCAX645-679 SCAX645-678	ECMS02-2011-1710 ECMS02-2011-1641	1141: BROKEN NO SPARE ADA RAMP IN CAB NOSE	No Failure/Cause Entered	INSPECTION SHEET C M	BROKEN NO SPARE ADA RAMP IN CAB NOSE
SCAX645			ECMS02-2011-1641	1141: BROKEN NO SPARE ADA RAMP IN CAB NOSE 1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121	No Failure/Cause Entered No Failure/Cause Entered	INSPECTION SHEET C.M. REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M.	BROKEN NO SPARE ADA RAMP IN CAB NOSE BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121
SCAX645 SCAX645 SCAX645	10/13/2011	SCAX645-678 SCAX645-677	ECMS02-2011-1641 ECMS02-2011-1640	1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 700: WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL	No Failure/Cause Entered	REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M. CRACKS DO NOT EXCEED 1" SPEC FOR SERVICE PER DAILY INSPECTION	BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL
SCAX645 SCAX645 SCAX645 SCAX645	10/13/2011 10/13/2011 10/13/2011	SCAX645-678 SCAX645-677 SCAX645-676	ECMS02-2011-1641 ECMS02-2011-1640 ECMS02-2011-1639	1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 700: WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK	No Failure/Cause Entered No Failure/Cause Entered	REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M. CRACKS DO NOT EXCEED 1" SPEC FOR SERVICE PER DAILY INSPECTION SHEET (STORAGE) E.A.	BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK
SCAX645 SCAX645 SCAX645 SCAX645 SCAX645	10/13/2011 10/13/2011 10/13/2011 10/12/2011	SCAX645-678 SCAX645-677 SCAX645-676 SCAX645-675	ECMS02-2011-1641 ECMS02-2011-1640 ECMS02-2011-1639 ECMS02-2011-1626	1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 700: WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK 1600: RESTROOM-NO WATER NO BIOCIDE	No Failure/Cause Entered No Failure/Cause Entered No Failure/Cause Entered	REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M. CRACKS DO NOT EXCEED 1" SPEC FOR SERVICE PER DAILY INSPECTION	BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK RESTROOM-NO WATER NO BIOCIDE
SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645	10/13/2011 10/13/2011 10/13/2011 10/12/2011 10/12/2011	SCAX645-678 SCAX645-677 SCAX645-676 SCAX645-675 SCAX645-674	ECMS02-2011-1641 ECMS02-2011-1640 ECMS02-2011-1639 ECMS02-2011-1626 ECMS02-2011-1603	1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 700: WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK 1600: RESTROOM-NO WATER NO BIOCIDE 010: AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF	No Failure/Cause Entered No Failure/Cause Entered No Failure/Cause Entered No Failure/Cause Entered	REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M. CRACKS DO NOT EXCEED 1" SPEC FOR SERVICE PER DAILY INSPECTION SHEET (STORAGE) E.A. CALLED M99 TO FILL PER DAILY DEFECT SIGN OFF SHEET M.R. WORKING CORRECTLY BUT STIFF = OK FOR USE PER DAILY DEFECT SIGN OFF SHEET D.C.	BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK RESTROOM-NO WATER NO BIOCIDE AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF
SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645	10/13/2011 10/13/2011 10/13/2011 10/12/2011 10/12/2011 10/11/2011	SCAX645-678 SCAX645-677 SCAX645-676 SCAX645-675 SCAX645-674 SCAX645-673	ECMS02-2011-1641 ECMS02-2011-1640 ECMS02-2011-1639 ECMS02-2011-1626 ECMS02-2011-1603 ECMS02-2011-1571	1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 700: WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK 1600: RESTROOM-NO WATER NO BIOCIDE 010: AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF 1602: RESTROOM-TOILET FULL/PLUGGED - RESTROOM LOCKED OUT	No Failure/Cause Entered	REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M. CRACKS DO NOT EXCEED 1" SPEC FOR SERVICE PER DAILY INSPECTION SHEET (STORAGE) E.A. CALLED M99 TO FILL PER DAILY DEFECT SIGN OFF SHEET M.R. WORKING CORRECTLY BUT STIFF = OK FOR USE PER DAILY DEFECT SIGN OFF SHEET D.C. UNCLOGGED TOILET AND WORKING OK PER DAILY SIGN OFF SHEET M.L.	BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK RESTROOM-NO WATER NO BIOCIDE AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF RESTROOM-TOILET FULL/PLUGGED - RESTROOM LOCKED OUT
SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645	10/13/2011 10/13/2011 10/13/2011 10/12/2011 10/12/2011 10/11/2011 10/11/2011	SCAX645-678 SCAX645-677 SCAX645-676 SCAX645-675 SCAX645-674 SCAX645-673 SCAX645-672	ECMS02-2011-1641 ECMS02-2011-1640 ECMS02-2011-1639 ECMS02-2011-1626 ECMS02-2011-1603 ECMS02-2011-1571 ECMS02-2011-1569	1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 700: WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK 1600: RESTROOM-NO WATER NO BIOCIDE 010: AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF 1602: RESTROOM-TOILET FULL/PLUGGED - RESTROOM LOCKED OUT 010: AUTOMATIC BRAKE IS HARD TO RELEASE FROM MIN POSITION PER DAILY DEFECT SHEET	No Failure/Cause Entered	REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M. CRACKS DO NOT EXCEED 1" SPEC FOR SERVICE PER DAILY INSPECTION SHEET (STORAGE) E.A. CALLED M99 TO FILL PER DAILY DEFECT SIGN OFF SHEET M.R. WORKING CORRECTLY BUT STIFF = OK FOR USE PER DAILY DEFECT SIGN OFF SHEET D.C. UNCLOGGED TOILET AND WORKING OK PER DAILY SIGN OFF SHEET M.L. OK FOR SERVICE PER DAILY DEFECT SIGN OFF SHEET C.M.	BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK RESTROOM-NO WATER NO BIOCIDE AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF RESTROOM-TOILET FULL/PLUGGED - RESTROOM LOCKED OUT AUTOMATIC BRAKE IS HARD TO RELEASE FROM MIN POSITION PER DAILY DEFECT SHEET
SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645 SCAX645	10/13/2011 10/13/2011 10/13/2011 10/12/2011 10/12/2011 10/11/2011 10/11/2011 10/07/2011	SCAX645-678 SCAX645-677 SCAX645-676 SCAX645-675 SCAX645-674 SCAX645-673	ECMS02-2011-1641 ECMS02-2011-1640 ECMS02-2011-1639 ECMS02-2011-1626 ECMS02-2011-1603 ECMS02-2011-1571 ECMS02-2011-1569 ECMS02-2011-1518	1141: BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 700: WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK 1600: RESTROOM-NO WATER NO BIOCIDE 010: AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF 1602: RESTROOM-TOILET FULL/PLUGGED - RESTROOM LOCKED OUT 010: AUTOMATIC BRAKE IS HARD TO RELEASE FROM MIN POSITION PER DAILY	No Failure/Cause Entered	REPLACED BY C NEFF PER DAILY INSPECTION SHEET C.M. CRACKS DO NOT EXCEED 1" SPEC FOR SERVICE PER DAILY INSPECTION SHEET (STORAGE) E.A. CALLED M99 TO FILL PER DAILY DEFECT SIGN OFF SHEET M.R. WORKING CORRECTLY BUT STIFF = OK FOR USE PER DAILY DEFECT SIGN OFF SHEET D.C. UNCLOGGED TOILET AND WORKING OK PER DAILY SIGN OFF SHEET M.L.	BROKEN MISSING HANDICAP STICKER FROM SEAT 120-121 WHEELS-FLAT SPOTS/SHELLING ROTOR ON WHEEL #6 HAS THERMAL CRACK RESTROOM-NO WATER NO BIOCIDE AUTO BRAKE HANDLE STICKS FROM MINIMUM TO RELEASE BRAKE HANDLE WORKS BUT STIFF RESTROOM-TOILET FULL/PLUGGED - RESTROOM LOCKED OUT AUTOMATIC BRAKE IS HARD TO RELEASE FROM MIN POSITION PER DAILY

EQUIP ID	DATE REPORTED	SERVICE REQUEST ID	WORK ORDER ID	SYMPTOM COMMENT	FAILURE COMMENT	CORRECTION COMMENT	WARRANTY COMPLAINT
SCAX645	10/03/2011	SCAX645-517	ECMS02-2011-1493	1141: ZERO SPEED FAILED TO PICK UP	No Failure/Cause Entered	TESTEDY FOUND SIGNAL COMING FROM LOCO #853 PER ROTEM. OK FOR SERVICE PER ROTEM. CONFIRMED BY BOMBARDIER.	ZERO SPEED FAILED TO PICK UP
	09/26/2011	SCAX645-516	ECMS02-2011-1518	1602: RESTROOM-TOILET FULL/PLUGGED	No Failure/Cause Entered	DUMPED CAR OK FOR SERVICE	RESTROOM-TOILET FULL/PLUGGED
SCAX645 SCAX645	09/08/2011	SCAX645-513 SCAX645-512	No Work Order Assigned	101: BRAKES-AUTOMATIC BRAKE DEFECTIVE 1003: DOORS-DOORS CLOSE UNEXPECTEDLY /CREW DOOR #4	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered PER DAILY DEFECT SHEETS ROTEM REPORTS THAT THE DEFECT IS	BRAKES-AUTOMATIC BRAKE DEFECTIVE DOORS-DOORS CLOSE UNEXPECTEDLY /CREW DOOR #4
	08/09/2011	SCAX645-511	•	609: ELECT-AUXILIARY LIGHT(S) INOPERATIVE	No Failure/Cause Entered	RESOLVED (DETAILS NOT PROVIDED) REPLACED AND TESTED	LEFT DITCH LIGHT
	07/22/2011	SCAX645-510		911: MISC-HORN INOPERATIVE	No Failure/Cause Entered	LAUS (KRIS M.) REASSEMBLED HORN BUTTON SWITCH AND TESTED OK.	MISC-HORN INOPERATIVE
SCAX645	07/20/2011	SCAX645-509	No Work Order Assigned	1100: HVAC-TOO HOT	48: LOW PRESSURE LOW PRESSURE FAULT	RESET HVACS- ROTEM	HVAC-TOO HOT
	07/05/2011	SCAX645-198	No Work Order Assigned		No Failure/Cause Entered	RESET WITH LAP TOP AT LAUS	HVAC-TOO HOT
	07/01/2011	SCAX645-197		1103: HVAC-NOT OPERATIONAL	No Failure/Cause Entered 21: MISADJUSTED	REPAIRED BY ROTEM	HVAC-NOT OPERATIONAL
SCAX645	06/21/2011	SCAX645-194	ECMS02-2011-1032	1004: DOORS-DOOR CONTROL STATION DEFECTIVE 806: CONSTANT ALARM WHEN THE 'CAB SET-UP' SWITCH IS IN THE 'OFF'	DOOR INTERLOCK SWITCH NOT ADJUSTED CORRECTLY	DOOR INTERLOCK SWITCHES ADJUSTED. OK FOR SERVICE	DOORS-DOOR CONTROL STATION DEFECTIVE
SCAX645	06/17/2011	SCAX645-193	ECMS02-2011-820	POSITION	No Failure/Cause Entered	No Correction Entered	CONSTANT ALARM WHEN THE `CAB SET-UP' SWITCH IS IN THE `OFF' POSITION
	06/14/2011 06/10/2011	SCAX645-192 SCAX645-191	ECMS02-2011-795 ECMS02-2011-903	1300: PA-PA INOPERATIVE 806: PA-PA INOPERATIVE	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	INCORRECT AUTOMATED ANNOUNCEMENT PEI / ATTENDANT CALL ALARM WHEN TRAILING
	06/07/2011	SCAX645-187	ECMS02-2011-902	1602: RESTROOM-TOILET FULL/PLUGGED	No Failure/Cause Entered	No Correction Entered	RESTROOM-TOILET FULL/PLUGGED
SCAX645	05/23/2011	SCAX645-182	ECMS02-2011-661	1600: RESTROOM-NO WATER	No Failure/Cause Entered	No Correction Entered	WHEN ADDING WATER TO CARY THE WATER IMMEDIATELY COMES OUT OF THE OVERFLOW PIPE
				1007: UPON HARD CLOSING OF RESTROOM DOORY THE INSIDE LOCK			UPON HARD CLOSING OF RESTROOM DOORY THE INSIDE LOCK ENGAGES AND
SCAX645	05/10/2011	SCAX645-179	ECMS02-2011-572	ENGAGES AND THE DOOR CAN NOT BE OPEN WITH OUT A KEY. THIS OCCURS ON A TURN OR IF A PASSENGER/CREW CLOSES THE DOOR TOO HARD. NEW LOCKING MECHANISM MODIFICATION REQUIRED.	No Failure/Cause Entered	No Correction Entered	THE DOOR CAN NOT BE OPEN WITH OUT A KEY. THIS OCCURS ON A TURN OR IF A PASSENGER/CREW CLOSES THE DOOR TOO HARD. NEW LOCKING MECHANISM MODIFICATION REQUIRED.
SCAX645		SCAX645-177	ECMS02-2011-582	1500: TOILET SEAT LOOSE	No Failure/Cause Entered	No Correction Entered	TOILET SEAT LOOSE
SCAX645 SCAX645	04/21/2011	SCAX645-175 SCAX645-173	ECMS02-2011-685 ECMS02-2011-463	1007: DOORS-JAMMED 1000: DOORS-SIDE DOORS WILL NOT OPEN (RESTROOM DOOR)	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	RESTROOM DOOR OFF TRACK DOORS-SIDE DOORS WILL NOT OPEN (RESTROOM DOOR)
SCAX645	04/19/2011	SCAX645-167	ECMS02-2011-440	1300: PA-PA INOPERATIVE PEI ALARM	No Failure/Cause Entered	No Correction Entered	PA-PA INOPERATIVE PEI ALARM
	04/18/2011	SCAX645-166 SCAX645-165	No Work Order Assigned ECMS02-2011-445	906: MISC-RADIO INOPERATIVE 1007: DOORS-JAMMED	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	DELAY REPORT SHOWS RADIO ON CC #645 IS "INAUDIBLE". RESTROOM DOOR IS HARD TO OPEN AND CLOSE.
SCAX645	04/15/2011	SCAX645-164	ECMS02-2011-444	1200: LIGHTING-LIGHTS OUT/DEFECTIVE	No Failure/Cause Entered	No Correction Entered	"RESTROOM OCCUPIED" LIGHT
	04/15/2011	SCAX645-163	ECMS02-2011-421	1001: DOORS-SIDE DOORS WILL NOT CLOSE	No Failure/Cause Entered	No Correction Entered	DOOR #1 AND #3 INOPERATIVE PEI / ATTENDANT CALL ALARM
	04/13/2011	SCAX645-162 SCAX645-6	ECMS02-2011-446 ECMS02-2011-301	1300: INOPERATIVE PEI / ATTENDANT CALL ALARM 906: MISC-RADIO INOPERATIVE	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered No Correction Entered	RADIO VERY WEAK
	03/22/2011	SCAX645-5	ECMS02-2011-302	1002: DOORS-DOORS OPEN/CLOSE TOO FAST/SLOW	No Failure/Cause Entered	No Correction Entered	DOORS-DOORS OPEN/CLOSE TOO FAST/SLOW
	03/16/2011	SCAX645-3 SCAX645-2		105: BP HOSES SEPERATION 1044: PA INOPERATIVE / DEFECTIVE	No Failure/Cause Entered No Failure/Cause Entered	No Correction Entered TESTED OK	BP HOSES SEPERATION PA INOPERATIVE / DEFECTIVE
	02/14/2011	SCAX645-1		010: B-END AIR HOSE TOO LOW	No Failure/Cause Entered	ADJUST HOSES	CAUSED UDE AT MAGNOLIA AVE.y RVS
SCAX870	02/19/2015	SCAX870-292544	No Work Order Assigned	901: ENGINEER REPORTED SPEEDOMETER NEEDS CALIBRATION	12: BROKEN/	CALIBRATED SPEEDOMETER AND VERIFIED CORRECT WHEEL SIZE, UTILIZED THE SPEED VERIFIER FOR CORRECT SPEEDS AND OVERSPEED FEATURE.	ENGINEER REPORTED SPEEDOMETER NEEDS CALIBRATION
			No Work Order Assigned No Work Order Assigned	1141: OIL ON WALKWAY UNDER MAIN ENGINE/HEP	No Failure/Cause Entered	OIL CLEANED PEI BOX PRESENT DURING INSPECTION	OIL ON WALKWAY UNDER MAIN ENGINE/HEP PEI BOX MISSING
		SCAX870-292167 SCAX870-292164		1502: MISSING COMM AND MU CABLES	No Failure/Cause Entered 12: BROKEN	No Correction Entered	FEI BOX IVISSING
		SCAX870-289145		ELVER	No Failure/Cause Entered	SECURED 480 CABLE	ENGINEER'S SIDE REAR 480V HEP CABLE TOUCHING GRAB IRON/CUT LEVER
				200: MAIN ENGINE WOULD NOT START. RESET CPU BREAKER 700: FRONT F/S 480 PLUG B/O	12: BROKEN/ 12: BROKEN/BAD ORDER #1 PIN	No Correction Entered REPLACED THE #1 PIN ON THE BOMB CAR.	MAIN ENGINE WOULD NOT START. RESET CPU BREAKER FRONT F/S 480 PLUG B/O
SCAX870	11/21/2014	SCAX870-268568	No Work Order Assigned	911: MISC-HORN INOPERATIVE	45: WRONG PART	SRD CREATED FOR THE WRONG LOCOMOTIVE, READ THE DESCRIPTION	MISC-HORN INOPERATIVE
				2000: R/S HEP SHORT LOOPED		No Correction Entered C#188 A-END FEMALE 480V RECEPTACLE PIN DEFECTIVE. REPAIRED	R/S HEP SHORT LOOPED
				2000: HEP-LOST HEP ON ONE SIDE OF TRAIN	12: BROKEN	DEFECTIVE 480 PIN, BOTH SIDES ONLINE	HEP-LOST HEP ON ONE SIDE OF TRAIN
				201: ENGINE-SHUT DOWN NO REASON 202: LOW WATER PRESSURE INDICATION	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	ENGINE-SHUT DOWN NO REASON LOW WATER PRESSURE INDICATION
				212: ENGINE-FLUID LEAKS WATER-OIL-FUEL	No Failure/Cause Entered	No Correction Entered	
SCAX870	10/27/2014	SCAX870-260869	No Work Order Assigned	605: ELECT-START MOTORS BURNT UP		CMF ROBERT H. AND FRANK G.) REPLACED 2- STARTERS AND L #870 STARTED UP RIGHT AWAY WITH NO ISSUES.	ELECT-START MOTORS BURNT UP
SCAX870	10/14/2014	SCAX870-255256	No Work Order Assigned	611: MARKER AND NUMBER LIGHTS HAVE NO POWER. BAD PIN IN CONNECTOR	3	THE 9G PLUG HAD BURNT PINS, REPLACED THE CONNECTOR.	MARKER AND NUMBER LIGHTS HAVE NO POWER. BAD PIN IN CONNECTOR
				304: BLENDED BRAKING B/O. NON-COMPLIANCE TAG ISSUED		No Correction Entered	BLENDED BRAKING B/O. NON-COMPLIANCE TAG ISSUED
SCAX870	10/08/2014	SCAX870-253538	No Work Order Assigned	304: FAILED BLENDED BRAKE TEST ON COMPUTER		No Correction Entered HORN RELAY AIR VALVE FOUND WITH A DEFECTIVE PLUNGER. REBUILT RELA'	FAILED BLENDED BRAKE TEST ON COMPUTER
SCAX870	10/07/2014	SCAX870-253367	No Work Order Assigned	911: MISC-HORN INOPERATIVE	12: BROKEN	VALVE REPLACED DURING 4YR INSPECTION, 10/7/2014. VERIFIED ELECTRICAL OK FROM DESKTOP HORN SWITCH TO MAGNET VALVE.	
SCAX870	09/17/2014	SCAX870-247013	No Work Order Assigned	301: ENGINE-FUEL PROBLEMS-BUBBLES IN SIGHT GLASS (PH)	12: BROKEN	No Correction Entered	ENGINE-FUEL PROBLEMS-BUBBLES IN SIGHT GLASS (PH)
SCAX870	09/15/2014	SCAX870-246097	No Work Order Assigned	301: LOADING-PARTIAL LOADING		No Correction Entered QMP VERIFIED C#134 BOTH SIDES OF HVAC COOLING OK, COMPRESSOR	LOADING-PARTIAL LOADING
SCAX870	09/10/2014	SCAX870-245500	No Work Order Assigned	301: LOADING-PARTIAL LOADING	No Failure/Cause Entered	TURNS ON, COOLANT LEVEL MIGHT BE LOW CAUSING TEMPERATURE DIFFERENCE. QMP REPORTED C#248 B-ENDIA-END HVAC WORKING OK, BOTH SIDES SHOW FULL COOL. CMF FOLLOW-UP THIS MORNING.	LOADING-PARTIAL LOADING
SCAX870	09/04/2014	SCAX870-243678	No Work Order Assigned	301: LOADING-PARTIAL LOADING		SNB QMP INSPECTED EQUIPMENT FOR MECHANICAL DEFECTS, NONE FOUND. NO FAULTS IN COMPUTER. LT1=HP=2993/RPM=904/LR%=100 // LT2=HP=3023/RPM=904/LR%=88. CALE VALDEZ INSPECTED PRIOR TO DEPARTURE, CONFIRMED SELF-LOAD TEST VITALS NORMAL. RIDING TO MONITOR, REPORTS AS M301, NO ISSUES AND â¿¿RUNNING LIKE A CHAMPâ¿.	LOADING-PARTIAL LOADING
			No Work Order Assigned	301: REPORTED FOR LOW HORSEPOWER		No Correction Entered	REPORTED FOR LOW HORSEPOWER
				001: SPEEDOMETER IS OVER 3 MPH		VERIFIED THE WHEEL SIZE, AND MADE THE CORRECT ADJUSTMENTS	SPEEDOMETER IS OVER 3 MPH
SCAX870	09/04/2014	SCAX870-243584	No Work Order Assigned			#1 PIN FOUND BAD ORDER, REPLACED AND RESTORED POWER.	HEP ON RUN AND R/S CUT-OUT
SCAX870 SCAX870	09/04/2014 08/28/2014	SCAX870-243584 SCAX870-242052	No Work Order Assigned No Work Order Assigned	2000: HEP ON RUN AND R/S CUT-OUT	Y to PROVEN	TIGHTENED HARDWARE AND PERFORMED OUTBOUND, NO LEAKS AT THE	MAIN ENGINE TURBO LEAKING OIL BETWEEN AFTER COOLERS ABOVE FLY
SCAX870 SCAX870 SCAX870	09/04/2014 08/28/2014 08/18/2014	SCAX870-243584 SCAX870-242052 SCAX870-239292	No Work Order Assigned No Work Order Assigned No Work Order Assigned	2000: HEP ON RUN AND R/S CUT-OUT 212: MAIN ENGINE TURBO LEAKING OIL BETWEEN AFTER COOLERS ABOVE FL' WHEEL		TIME OF RELEASE	WHEEL
SCAX870 SCAX870 SCAX870 SCAX870	09/04/2014 08/28/2014 08/18/2014 07/31/2014	SCAX870-243584 SCAX870-242052 SCAX870-239292 SCAX870-233508	No Work Order Assigned No Work Order Assigned No Work Order Assigned ECMS01-2014-293	2000: HEP ON RUN AND R/S CUT-OUT 212: MAIN ENGINE TURBO LEAKING OIL BETWEEN AFTER COOLERS ABOVE FL' WHEEL 700: 1 INCH SHELLING SPOT ON WHEEL R1	12: BROKEN 12: WHEELS TRUED	TIME OF RELEASE WHEELS TRUED ON 92DAY PM	WHEEL 1 INCH SHELLING SPOT ON WHEEL R1
SCAX870 SCAX870 SCAX870 SCAX870 SCAX870	09/04/2014 08/28/2014 08/18/2014 07/31/2014 07/28/2014	SCAX870-243584 SCAX870-242052 SCAX870-239292 SCAX870-233508 SCAX870-232724	No Work Order Assigned No Work Order Assigned No Work Order Assigned ECMS01-2014-293 No Work Order Assigned	2000: HEP ON RUN AND R/S CUT-OUT 212: MAIN ENGINE TURBO LEAKING OIL BETWEEN AFTER COOLERS ABOVE FL' WHEEL 700: 1 INCH SHELLING SPOT ON WHEEL R1 304: LOADING-NO DYNAMIC BRAKE		TIME OF RELEASE WHEELS TRUED ON 92DAY PM SELF TEST PASSED FOR BLENDED BRAKING. INSPECTION TO BE PERFORMED AT CMF.	WHEEL 1 INCH SHELLING SPOT ON WHEEL R1 LOADING-NO DYNAMIC BRAKE
SCAX870 SCAX870 SCAX870 SCAX870 SCAX870 SCAX870	09/04/2014 08/28/2014 08/18/2014 07/31/2014 07/28/2014 07/21/2014	SCAX870-243584 SCAX870-242052 SCAX870-239292 SCAX870-233508 SCAX870-232724 SCAX870-229384	No Work Order Assigned No Work Order Assigned No Work Order Assigned ECMS01-2014-293 No Work Order Assigned No Work Order Assigned	2000: HEP ON RUN AND R/S CUT-OUT 212: MAIN ENGINE TURBO LEAKING OIL BETWEEN AFTER COOLERS ABOVE FL' WHEEL 700: 1 INCH SHELLING SPOT ON WHEEL R1 304: LOADING-NO DYNAMIC BRAKE 1502: FIRE EXTINGUISHER ON FIREMANS SIDE OF HEP EXPIRED 7-19	12: WHEELS TRUED	TIME OF RELEASE WHEELS TRUED ON 92DAY PM SELF TEST PASSED FOR BLENDED BRAKING. INSPECTION TO BE PERFORMED AT CMF. APPLIED FIRE EXTINGUISHER WITH A GOOD DATE	WHEEL 1 INCH SHELLING SPOT ON WHEEL R1 LOADING-NO DYNAMIC BRAKE FIRE EXTINGUISHER ON FIREMANS SIDE OF HEP EXPIRED 7-19
SCAX870 SCAX870 SCAX870 SCAX870 SCAX870 SCAX870 SCAX870 SCAX870	09/04/2014 08/28/2014 08/18/2014 07/31/2014 07/28/2014 07/21/2014 07/11/2014	SCAX870-243584 SCAX870-242052 SCAX870-239292 SCAX870-233508 SCAX870-232724 SCAX870-229384 SCAX870-227000	No Work Order Assigned No Work Order Assigned No Work Order Assigned ECMS01-2014-293 No Work Order Assigned No Work Order Assigned ECMS01-2014-262	2000: HEP ON RUN AND R/S CUT-OUT 212: MAIN ENGINE TURBO LEAKING OIL BETWEEN AFTER COOLERS ABOVE FL' WHEEL 700: 1 INCH SHELLING SPOT ON WHEEL R1 304: LOADING-NO DYNAMIC BRAKE		TIME OF RELEASE WHEELS TRUED ON 92DAY PM SELF TEST PASSED FOR BLENDED BRAKING. INSPECTION TO BE PERFORMED AT CMF.	WHEEL 1 INCH SHELLING SPOT ON WHEEL R1 LOADING-NO DYNAMIC BRAKE

EQUIP ID	DATE REPORTED	SERVICE REQUEST ID	WORK ORDER ID	SYMPTOM COMMENT	FAILURE COMMENT	CORRECTION COMMENT	WARRANTY COMPLAINT
SCAX870	06/26/201			304: REPORTED FOR NO DYNAMIC OR BLENDED BRAKING	12: MECH TECH INSPECTED AND VERIFIED ALL FAULTS RESET, VERIFIED GOOD DBI TEST DURING CLASS 1, VERIFIED 74/24T, PERFORMED BLENDED	MECH TECH INSPECTED AND VERIFIED ALL FAULTS RESET, VERIFIED GOOD DBI TEST DURING CLASS 1, VERIFIED 74/24T, PERFORMED BLENDED BRAKE	REPORTED FOR NO DYNAMIC OR BLENDED BRAKING
SCAX870	06/25/201	4 SCAX870-223548	No Work Order Assigned	402: HEP-WILL NOT RAMP UP	BRAKE TEST (PASSED OK). FURTHER INSPECTION AT CMF 12: HESS AND VRCR NOT RECEIVING PROPER SIGNALS TO ENERGIZE THE GEN FIELD. POSSIBLE ISSUE WITH THE MAGNETIC PICKUP	TEST (PASSED OK). FURTHER INSPECTION AT CMF HESS AND VRCR NOT RECEIVING PROPER SIGNALS TO ENERGIZE THE GEN FIELD. POSSIBLE ISSUE WITH THE MAGNETIC PICKUP	HEP-WILL NOT RAMP UP
SCAX870	06/09/201	4 SCAX870-220337	No Work Order Assigned	100: BRAKES-BRAKES WILL NOT APPLY-RELEASE-MAINTAIN	No Failure/Cause Entered	SLACK ADJUSTER PINS WERE VERIFIED IN PLACE AND SECURED PRIOR TO CMF DEPARTURE	BRAKES-BRAKES WILL NOT APPLY-RELEASE-MAINTAIN
SCAX870	05/06/201	4 SCAX870-208873	No Work Order Assigned	804: PTC SYSTEM NON-FUNCTIONAL		SYSTEM WAS LEFT CUT-OUT FOR SERVICE.	PTC SYSTEM NON-FUNCTIONAL
SCAX870	04/21/201	4 SCAX870-202982	ECMS01-2014-165	403: C27 HEP GENERATOR INSPECTION.	No Failure/Cause Entered	INSPECT HEP GENERATOR FOR CHAFED, LOOSE, OR BURNT WIRING, CORRECT AS REQUIRED. CLEAN BACK OF GENERATOR WITH COMPRESSED AIR. INSPECT CONDITION OF DIODES, RESISTORS, AND SUPPRESSORS ON REAR OF GENERATOR.	C27 HEP GENERATOR INSPECTION.
		4 SCAX870-200364		300: NO LOAD. AUX GEN FAULT	12: BROKEN	No Correction Entered	NO LOAD. AUX GEN FAULT
SCAX870 SCAX870		4 SCAX870-200126 4 SCAX870-199172		004: AIR COMPRESSOR OIL IS APPROXIMATELY 1.5 GALLONS LOW 212: FUEL TANK LEAK	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	AIR COMPRESSOR OIL IS APPROXIMATELY 1.5 GALLONS LOW FUEL TANK LEAK
SCAX870		4 SCAX870-196829	No Work Order Assigned	914: NO SAND	12: CONDUCTOR REPORTS L #870 HORN IS CONSTANTLY ON, BUTTON IS NOT	ADDED SAND.	NO SAND
SCAX870	03/21/201	4 SCAX870-196229	No Work Order Assigned	910: MISC-LOWER HORN INOPERATIVE-CUT-IN UPPER HORN	RESPONDING.	No Correction Entered PERFORM BATTERY MAINTENANCE, BATTERIES HOLDING CHARGE, WILL	MISC-LOWER HORN INOPERATIVE-CUT-IN UPPER HORN
SCAX870	02/28/201		-	903: MISC-LOAD METER/GAUGES DEFECTIVE	No Failure/Cause Entered	MONITOR.	MISC-LOAD METER/GAUGES DEFECTIVE
SCAX870 SCAX870		4 SCAX870-176608 3 SCAX870-173266		212: FUEL TANK LEAK 405: HEP DROPS 3-4 TIMES WITH A FREQUENCY TRIP	12: CRACKED FUEL TANK 12: BROKEN	REPALCED FUEL TANK No Correction Entered	FUEL TANK LEAK HEP DROPS 3-4 TIMES WITH A FREQUENCY TRIP
SCAX870		3 SCAX870-173265		212: FUEL TANK LEAKING	12: BROKEN	No Correction Entered	FUEL TANK LEAKING
SCAX870 SCAX870		3 SCAX870-172988 3 SCAX870-172191	ECMS04-2014-23 ECMS04-2014-23	100: BRAKE CYLINDER GOES TO 90 PSI ON PENALTY APPLICATION 909: ENGINEER SIDE WIPER B/O	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	BRAKE CYLINDER GOES TO 90 PSI ON PENALTY APPLICATION ENGINEER SIDE WIPER B/O
SCAX870		3 SCAX870-170438	ECMS04-2014-23	700: GRILL ON FIREMANS SIDE OF LOCO BODY PUSHED IN	12: BROKEN	No Correction Entered	GRILL ON FIREMANS SIDE OF LOCO BODY PUSHED IN
SCAX870		3 SCAX870-169923	ECMS04-2014-23	700: GRILL ON FIREMANS SIDE PUSHED IN. SIDE OF LOCO	12: BROKEN	No Correction Entered	GRILL ON FIREMANS SIDE PUSHED IN. SIDE OF LOCO
SCAX870 SCAX870		3 SCAX870-168957 3 SCAX870-164872		212: WATER LEAK AT MAIN ENGINE PIPE TO COMPRESSOR 301: LOADING-PARTIAL LOADING	12: BROKEN	No Correction Entered No Correction Entered	WATER LEAK AT MAIN ENGINE PIPE TO COMPRESSOR LOADING-PARTIAL LOADING
SCAX870		3 SCAX870-164672 3 SCAX870-154422		212: OIL FILTER NEAR COMPRESSOR LEAKING	12: BROKEN 12: BROKEN	No Correction Entered	OIL FILTER NEAR COMPRESSOR LEAKING
SCAX870		3 SCAX870-154421		212: MAIN ENGINE OIL LEAK AT REAR OF ENGINE	12: BROKEN	No Correction Entered	MAIN ENGINE OIL LEAK AT REAR OF ENGINE
SCAX870		3 SCAX870-154221		212: OIL FILTER LEAKING	12: BROKEN	No Correction Entered	OIL FILTER LEAKING
SCAX870		3 SCAX870-151923		300: LOADING-NOT LOADING	No Failure/Cause Entered	No Correction Entered	LOADING-NOT LOADING
SCAX870 SCAX870		3 SCAX870-145706 3 SCAX870-145704	ECMS01-2013-953 ECMS01-2013-953	1500: FIREMAN SIDE SEAT TORN 212: OIL LEAKING FROM TUBE RIGHT ABOVE FLYWHEEL	12: BROKEN 12: BROKEN	No Correction Entered No Correction Entered	FIREMAN SIDE SEAT TORN OIL LEAKING FROM TUBE RIGHT ABOVE FLYWHEEL
SCAX870		3 SCAX870-144709	ECMS01-2013-953	004: AIR COMPRESSOR OIL LOW 1.5 GALLONS	12: BROKEN	No Correction Entered	AIR COMPRESSOR OIL LOW 1.5 GALLONS
SCAX870	08/23/201	3 SCAX870-138686	ECMS01-2013-953	212: ENGINE-FLUID LEAKS WATER-OIL-FUEL	No Failure/Cause Entered	No Correction Entered	ENGINE-FLUID LEAKS WATER-OIL-FUEL
SCAX870	06/20/201		-	202: UNABLE TO RESET LOW COOLANT PRESSURE	12: SENSOR FAILURE	AIR BOX PRESSURE SENSOR SHORTED CAUSING MAX FAILURE OF SENSOR. DDSIGNOFF.	UNABLE TO RESET LOW COOLANT PRESSURE
SCAX870 SCAX870		3 SCAX870-114464 3 SCAX870-107251		700: WHEELS-FLAT SPOTS/SHELLING	No Foilure/Course Entered	NO DAMAGE OF FLAT SPOTS FOUND. DDSIGNOFF. REPLACE REMOVED BRACKET AND CLAMPS.	WHEELS-FLAT SPOTS/SHELLING
SCAX870		3 SCAX870-107231		209: INSUFFICIENT FUEL LINE SUPPORT 004: AIR DRYER INDICATOR WHITE	No Failure/Cause Entered	REPLACED AIR DRYER, DDSIGNOFF.	INSUFFICIENT FUEL LINE SUPPORT AIR DRYER INDICATOR WHITE
SCAX870				1502: RED FLAG MISSING		RED FLAGS REPLACED. DDSIGNOFF.	RED FLAG MISSING
SCAX870		3 SCAX870-105024		800: ATS INDICATION AT ALL SIGNALS		MP8 DONE. DDSIGNOFF.	ATS INDICATION AT ALL SIGNALS
SCAX870 SCAX870		3 SCAX870-101561 3 SCAX870-100888		900: MISC-DEBRIS STRIKE/DAMAGE 2000: HEP-LOST HEP ON ONE SIDE OF TRAIN		REMOVED FROM SERVICE. DDSIGNOFF. REPAIRED BY NIGHT CREW. DDSIGNOFF.	MISC-DEBRIS STRIKE/DAMAGE HEP-LOST HEP ON ONE SIDE OF TRAIN
SCAX870	04/16/201			900: MISC-DEBRIS STRIKE/DAMAGE		COSMETIC ONLY. NO UNSAFE CONDITIONS AS A RESULT. SERVICABLE. DDSIGNOFF.	MISC-DEBRIS STRIKE/DAMAGE
SCAX870	04/04/201	3 SCAX870-91305	No Work Order Assigned	209: MAIN ENGINE FUEL PUMP FAILURE		REPLACED. DDSIGNOFF.	MAIN ENGINE FUEL PUMP FAILURE
SCAX870	03/06/201			212: OIL LEAK SOMEWHERE NEAR FLYWHEEL ENGINEER SIDE		UNABLE TO IDENTIFY SOURCE OF LEAK. CLEANED. DDSIGNOFF.	OIL LEAK SOMEWHERE NEAR FLYWHEEL ENGINEER SIDE
SCAX870	03/04/201			702: TRIPPED DRAGGING DETECTOR		NO DEFECT FOUND DDSIGNOFF.	TRIPPED DRAGGING DETECTOR
SCAX870 SCAX870	02/26/201			800: ATS/ALERTOR-INOPERATIVE 304: BLENDED BRAKES B/O. CUT-OUT		TESTED AND NO DEFECT FOUND. DDSIGNOFF. REPLACED PRESSURE TRANSDUCER. DDSIGNOFF.	ATS/ALERTOR-INOPERATIVE BLENDED BRAKES B/O. CUT-OUT
SCAX870		3 SCAX870-77113		212: PH - REPOWER HOSE REPLACEMENT	12: DUE TO AGE	No Correction Entered	BLENDED BIVAILED BIO. 001-001
SCAX870		3 SCAX870-74635		212: ENGINE-FLUID LEAKS FUEL	18: LEAKING	CUT - OUT. DDSIGNOFF.	ENGINE-FLUID LEAKS FUEL
				700: WHEELS-FLAT SPOTS/SHELLING		NON- CONDEMNABLE. DDSIGNOFF (2/4/2013)	WHEELS-FLAT SPOTS/SHELLING
SCAX870				700: WHEELS-FLAT SPOTS/SHELLING 405: HEP-FREQUENCY TRIP	12: BROKEN	NON- CONDEMNABLE. DDSIGNOFF (2/4/2013) HEP CUT BACK IN. NO DEFECT FOUND. DDSIGNOFF.	WHEELS-FLAT SPOTS/SHELLING HEP-FREQUENCY TRIP
SCAX870				212: ENGINEER SIDE OIL LEAK FROM TURBO	12: BROKEN	WIPED DOWN AND CLEANED UP. DDSS	ENGINEER SIDE OIL LEAK FROM TURBO
SCAX870	12/04/201	2 SCAX870-51304	No Work Order Assigned	404: HEP-HUNTING	12: BROKEN	REPLACED VOLTAGE RELAY. TESTED RELAY WITH VOLTAGE AND IT FAILED	HEP-HUNTING
SCAX870	12/03/201			401: HEP-STARTS/WILL NOT STAY RUNNING	12: DEC2020 BAD	REPLACED AND REPAIRED WIRING PER FRB BLUE	HEP-STARTS/WILL NOT STAY RUNNING
SCAX870 SCAX870	11/26/201			407: HEP COMPUTER SCREEN READ-OUT IS ERRATIC 702: MISSING #8 VENT PROTECTOR FRONT TRUCK	12: BROKEN 12: BROKEN	NO DEFECT FOUND ON HEP SCREEN. DDSS REPLACED #8 VENT PROTECTOR. DDSS	HEP COMPUTER SCREEN READ-OUT IS ERRATIC MISSING #8 VENT PROTECTOR FRONT TRUCK
SCAX870	11/26/201			916: MISC-ACCIDENT DAMAGE	12: BROKEN	DOWNLOADED, HORN TEST BY STORAGE TEAM. DDSS	MISC-ACCIDENT DAMAGE
SCAX870	11/21/201	2 SCAX870-49160	No Work Order Assigned	212: OIL BY TURBO	12: BROKEN	CLEANED UP ALL OIL TURBO. DDSS	OIL BY TURBO
SCAX870				610: OVERHEAD LIGHT IN NOSE B/O	12: BROKEN	REPLACED BULB. DDSS	OVERHEAD LIGHT IN NOSE B/O
SCAX870 SCAX870	11/08/201	2 SCAX870-44154 2 SCAX870-40664		1141: SYSTEM GROUND FAULT 212: OIL LEAKING FROM TURBO ONTO FLYWHEEL	12: BROKEN 12: BROKEN	No Correction Entered LEAK OIL IS CLEARED BUT THE SOURCE SCHEDULE FOR REPAIR TO BE	SYSTEM GROUND FAULT OIL LEAKING FROM TURBO ONTO FLYWHEEL
SCAX870				1200: CAB LIGHT BALLAST B/O	12: BROKEN	REPAIRED ON THE NEXT PM. DDSS REPLACED. DDSS	CAB LIGHT BALLAST B/O
SCAX870	10/16/201			401: HEP L/S TRANSFERRING POWER FROM R/S	12: BROKEN	HEP REPAIRED. DDSS	HEP L/S TRANSFERRING POWER FROM R/S
SCAX870				004: 2 WHITE BULLSEYES ON AIR DRYER	12: BROKEN	INDICATOR NOT WHITE. DDSS	2 WHITE BULLSEYES ON AIR DRYER
SCAX870 SCAX870	10/12/201			400: HEP SHUTS DOWN ON ITS OWN/LOGS ON COMPUTER EFCO REQUEST 400: HEP-SHUTS DOWN-WON'T START	12: BROKEN 12: BROKEN	REMOVED FROM SERVICE. DDSS DGC 2020 DOWNLOAD, TEST AND REPROGRAM. FRB	HEP SHUTS DOWN ON ITS OWN/LOGS ON COMPUTER EFCO REQUEST HEP-SHUTS DOWN-WON'T START
SCAX870			No Work Order Assigned	400: HEP-SHUTS DOWN/ NO FAULTS OR ALARMS	12: BROKEN	No Correction Entered	HEP-SHUTS DOWN/ NO FAULTS OR ALARMS
SCAX870	09/14/201			1200: OVERHEAD CAB LIGHT B/O	12: BROKEN	REPLACED COVER PER DDSS	OVERHEAD CAB LIGHT B/O
SCAX870	09/06/201		0	402: HEP-WILL NOT RAMP UP	12: NDF	RIDER ON TRAIN FOUND NO DEFECTS AND HAD NO TROUBLE PUTTING BOTH SIDES ONLINE PER MORNING UPDATE	HEP-WILL NOT RAMP UP
SCAX870	08/21/201		No Work Order Assigned		No Failure/Cause Entered	No Correction Entered REPLACED VOLT REG AND FILTERS LOAD TESTED FOR 3 HOURS	
SCAX870	08/17/201	2 SCAX870-18923	· ·	2000: HEP DROP OUT ON BOTH SIDES INTERMITTENTLY	12: ENGINE HUNTING NO VOLTAGE OUTPUT - DIRTY FUEL FILTERS	480VAC 60HZ 80PSI FUEL PER TECH UPDATE SHEET	HEP DROP OUT ON BOTH SIDES INTERMITTENTLY
SCAX870	08/09/201	2 SCAX870-16522		001: VALLEY/VENTURA DISPATCHER REPORTS CREW IS UNABLE TO BUILD MR PRESSURE.	12: CREW ERROR	OK FOR SERVICE PER MORNING FRB	VALLEY/VENTURA DISPATCHER REPORTS CREW IS UNABLE TO BUILD MR PRESSURE.
SCAX870	08/07/201	2 SCAX870-15373	No Work Order Assigned	702: MP 65.9 TRIPPED HIGH/WIDE DETECTOR AXEL #19 LEFT (L #870 AXEL #2) .	12: BROKEN	INSPECTED DURING DAILY SERVICING AND OK PER MORNING UPDATE	MP 65.9 TRIPPED HIGH/WIDE DETECTOR AXEL #19 LEFT (L #870 AXEL #2) .
SCAX870	07/27/201	2 SCAX870-11046	No Work Order Assigned	300: LOADING-NOT LOADING	12: BROKEN	CAB CAR 685 HAD THROTTLE CONTROLLER REPLACED PER MORNING UPDATE	LOADING-NOT LOADING
SCAX870	07/12/201			401: HEP-STARTS/WILL NOT STAY RUNNING	12: FUEL WATER SEPERATOR CLOGGED	CLEANED SEPERATOR AND REPLACED FUEL FILTER PER DDSS	HEP-STARTS/WILL NOT STAY RUNNING
SCAX870	06/22/201	2 SCAX870-6103	No Work Order Assigned	403: HEP-WILL NOT GO ON-LINE	12: FREQ TRIP	ADJUSTED PER FRB	HEP-WILL NOT GO ON-LINE

EQUIP	DATE	SERVICE	WORK	SYMPTOM	FAILURE	1	
ID	REPORTED	REQUEST ID	WORK ORDER ID	COMMENT	COMMENT	CORRECTION COMMENT	WARRANTY COMPLAINT
SCAX870	06/15/2012	SCAX870-6102	No Work Order Assigned	405: HEP-FREQUENCY TRIP	12: LOW FUEL PSI FROM CLOGGED FUEL FILTERS NOT CHANGED AT 45DAYS DUE TO PARTS NIS	REPLACED FILTERS AND CREATED 45 DAY SCHEDULING ON MONTHLY PM CALANDER PUT ON PARTS OUT OF STOCK BOARD	HEP-FREQUENCY TRIP
SCAX870	05/29/2012	SCAX870-6101	No Work Order Assigned	303: LOADING- HUNTING NOT MAKING TRACK SPEED	12: AIR FILTERS DIRTY	REPLACED AIR FILTERS PER DAILY DEFECT SIGN OFF SHEET	LOADING- HUNTING NOT MAKING TRACK SPEED
SCAX870	04/27/2012	SCAX870-6097		1141: BROKEN/MAIN ENGINE SURGING AT TAKE OFF	12: BROKEN	No Correction Entered	BROKEN/MAIN ENGINE SURGING AT TAKE OFF
SCAX870	04/26/2012	SCAX870-6096		303: LOADING- HUNTING SURGING		No Correction Entered	LOADING- HUNTING SURGING
SCAX870	04/11/2012	SCAX870-5772	No Work Order Assigned		12: REVERSER PUT FORWARD AND ENGINE STARTED	NO DEFECT FOUND DURING DAILY INSPECTION PROCESS	AESS
SCAX870	03/12/2012	SCAX870-5770		1141: FRONT AIR HOSE TRIPPED DRAGGING DETECTOR AT MP 7.8	12: CREW ERROR DID NOT SECURE	REPLACED HOSE PER DAILY DEFECT SIGN OFF SHEET	FRONT AIR HOSE TRIPPED DRAGGING DETECTOR AT MP 7.8
SCAX870	02/15/2012	SCAX870-5614	No Work Order Assigned	1141: BROKEN / DITCH LIGHTS TURN ON WITH HEADLIGHT ON DIM	No Failure/Cause Entered	REPLACED SWITCH PER DAILY DEFECT SIGN OFF SHEET	BROKEN / DITCH LIGHTS TURN ON WITH HEADLIGHT ON DIM
SCAX870	02/13/2012	SCAX870-5611	No Work Order Assigned	1141: BROKEN / HEADLIGHT ROTARY SWITCH	No Failure/Cause Entered	REPLACED WITH NEW SWITCH AND OK FOR SERVICE PER DAILY DEFECT SIG OFF SHEET	N BROKEN / HEADLIGHT ROTARY SWITCH
SCAX870	01/11/2012	SCAX870-5609		1141: HANDBRAKE PROBLEM RELEASING.	No Failure/Cause Entered	REPLACED HANDBRAKE DURING DAILY INSPECTION PROCESS	HANDBRAKE PROBLEM RELEASING.
SCAX870	08/23/2011	SCAX870-5293		201: ENGINE-SHUT DOWN NO REASON / LOST POWER WEST OF CP 31 WHILE ARRIVING AT LAUS PLATFORM	No Failure/Cause Entered	REPLACING RADIATOR	ENGINE-SHUT DOWN NO REASON / LOST POWER WEST OF CP 31 WHILE ARRIVING AT LAUS PLATFORM
SCAX870	08/18/2011	SCAX870-5291		301: LOADING-PARTIAL LOADING /TRAIN ONLY GETTING 350 AMPS AND TRACK AT AROUND 20MPH/25 MPH. DOWNHILL NO ISSUES. FLAT LAND NO ISSUES.	No Failure/Cause Entered	REPLACING RADIATOR SEE ECMS01-2011- 579	LOADING-PARTIAL LOADING /TRAIN ONLY GETTING 350 AMPS AND TRACK AT AROUND 20MPH/25 MPH. DOWNHILL NO ISSUES. FLAT LAND NO ISSUES.
SCAX870	08/05/2011	SCAX870-5288	No Work Order Assigned	1141: MAIN ENGINE WEAK POWER GOING UP HILL	No Failure/Cause Entered	NO DEFECT FOUND	MAIN ENGINE WEAK POWER GOING UP HILL
SCAX870	08/01/2011	SCAX870-5286	No Work Order Assigned	306: LOADING-ERRATIC ENGINE SPEEDS LOW HORSE POWER	No Failure/Cause Entered	LOAD TESTED EQUIPMENT AND NO DEFECTS FOUND WORKING AS INTENDED	LOADING-ERRATIC ENGINE SPEEDS LOW HORSE POWER
SCAX870	04/18/2011	SCAX870-5131	No Work Order Assigned	904: MISC-DOOR OVERRIDE DISABLED NO GREEN LIGHTS	No Failure/Cause Entered	FOUND DEFECT ON CARS LOAD TETS WAS GOOD	MISC-DOOR OVERRIDE DISABLED NO GREEN LIGHTS
SCAX870	01/07/2011	SCAX870-4800	No Work Order Assigned	331: ENGINE SHUT DOWN - WATER LEVEL FULL - TRIPPED LOW WATER	No Failure/Cause Entered	ADJUSTED WATER LEVEL	ENGINE SHUT DOWN - WATER LEVEL FULL - TRIPPED LOW WATER
SCAX870	08/30/2010	SCAX870-4481	No Work Order Assigned	010: AIR BRAKES	No Failure/Cause Entered	REPLACED ADA307 BOARD	AIR BRAKES
SCAX870	08/27/2010	SCAX870-4479		1021: ALERTER DOES NOT FUNCTION AT ALL	No Failure/Cause Entered	FIXED GROUND FAILT IN TRAILING LOCO 872	ALERTER WOULD NOT RESET
SCAX870	08/03/2010	SCAX870-4476		711: GROUND RELAY ACTION IN POWER - NO LOCK-OUT	No Failure/Cause Entered	FOUND GROUNDS IN WIRING MAIN GEN	GROUND RELAY ACTION IN POWER - NO LOCK-OUT
SCAX870	07/07/2010	SCAX870-4472	No Work Order Assigned		No Failure/Cause Entered	No Correction Entered	VOLTAGE TRIPS
SCAX870	07/07/2010	SCAX870-4471		1114: NOT OPERATIONAL	No Failure/Cause Entered	REPLACED GRIDS	NOT OPERATIONAL
SCAX870	06/30/2010	SCAX870-4469		1114: NOT OPERATIONAL	No Failure/Cause Entered	REPLACED GRIDS	NOT OPERATIONAL
SCAX870	06/29/2010	SCAX870-4468		529: ONE SIDE WON'T GO ON LINE / DROPS	No Failure/Cause Entered	MPI REPLACED CONTACTOR	ONE SIDE WON'T GO ON LINE / DROPS
SCAX870	05/06/2010	SCAX870-4460		529: ONE SIDE WON'T GO ON LINE / DROPS	No Failure/Cause Entered	REPLACED FIREMAN SIDE FRONT AND REAR #1 PINS.	ONE SIDE WON'T GO ON LINE / DROPS
SCAX870	11/19/2008	SCAX870-4153		715: COMPUTER INDICATED FLASHOVER IN POWER	No Failure/Cause Entered	No Correction Entered	COMPUTER INDICATED FLASHOVER IN POWER
SCAX870		SCAX870-3457		711: GROUND RELAY ACTION IN POWER - NO LOCK-OUT	No Failure/Cause Entered	No Correction Entered	GROUND RELAY ACTION IN POWER - NO LOCK-OUT
SCAX870	00, 10, 200	SCAX870-3321		1065: CAB SEATS DEFECTIVE	No Failure/Cause Entered	REPAIRED OK SERVICE	CAB SEATS DEFECTIVE
SCAX870		SCAX870-3156		711: GROUND RELAY ACTION IN POWER - NO LOCK-OUT	No Failure/Cause Entered	OK FOR SERVICE	GROUND RELAY ACTION IN POWER - NO LOCK-OUT
SCAX870	07/10/2007	SCAX870-3155		913: INTERMITTENT NO LOAD	No Failure/Cause Entered	LOAD TESTED OK	INTERMITTENT NO LOAD
SCAX870	06/26/2007	SCAX870-3154		115: TRIPPED ENGINE OVERSPEED -	No Failure/Cause Entered	RESET OK FOR SERVICE	TRIPPED ENGINE OVERSPEED -
SCAX870	06/25/2007	SCAX870-3153		711: GROUND RELAY ACTION IN POWER - NO LOCK-OUT	No Failure/Cause Entered	RESET OK FOR SERVICE	GROUND RELAY ACTION IN POWER - NO LOCK-OUT
SCAX870	06/18/2007	SCAX870-3152		123: ENGINE SMOKING EXCESSIVELY	No Failure/Cause Entered	CHECKED UNDER LOAD TEST OK FOR SERVICE	ENGINE SMOKING EXCESSIVELY
SCAX870	05/09/2007	SCAX870-2826		118: ENGINE SHUT DOWN - LAY SHAFT STUCK	No Failure/Cause Entered	REPLACED STUCK INJECTOR	ENGINE SHUT DOWN - LAY SHAFT STUCK
SCAX870	04/13/2007	SCAX870-2817		123: TURBO FAILURE		REPLACED TURBO	TURBO FAILURE
SCAX870	03/08/2007	SCAX870-2664		123: ENGINE SMOKING EXCESSIVELY	No Failure/Cause Entered	No Correction Entered	ENGINE SMOKING EXCESSIVELY
SCAX870	11/09/2006	SCAX870-2505		115: TRIPPED ENGINE OVERSPEED - RESET OK	No Failure/Cause Entered	COULD NOT DUPLICATE	TRIPPED ENGINE OVERSPEED - RESET OK
SCAX870		SCAX870-253	ECMS01-2005-389		No Failure/Cause Entered	No Correction Entered	
SCAX870	05/05/2004	SCAX870-429	ECMS01-2004-208		No Failure/Cause Entered	No Correction Entered	
SCAX870	03/31/2004	SCAX870-444	ECMS01-2004-124		No Failure/Cause Entered	No Correction Entered	