

4-18	161.1	AD 2012-03-06 DASH NOT APPLY AUSTAR FUEL SYSTEM NOT INSTALLED AD 2012-10-13 DASH NOT APPLY TO THIS ENGINE MODEL.
3-7-2016	160.1	REMOVED FUEL PUMP FROM ENGINE TO BE REPAIRED. A [REDACTED]
3-28-2016	160.1	REINSTALLED FUEL PUMP P/N 649358-60A4 S/N B12HA155 REPAIRED BY D&G SUPPLY. REINSTALLED PER CONTINENTAL MAINTENANCE MANUAL AND SET FUEL PRESSURE TO SPECIFICATION IN MANUAL. [REDACTED]