Pag	e N	0
-----	-----	---

DA	IN	TOTAL TIME SINCE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
12-3	1-134536.	OVERHAL	4536.1	Replaced RH Main gear cylinder abembly with bervicable used PIN 65489-002. Part was removed From Piper PA-32-260, N 33315, 5/N 7500017. Total time on part is 4171.6 Hours. Part has been inspected IAW piper maint, manual and found to be airworthy. Installed new quad ring PIN 484-769. Installation of PIN 65489-002 eliminates the recurrent inspection requirement of Piper service bulletin # 1131. Serviced strut with
1-3-14	4542.8			TAN piper maint, manual, Replaced nose tire and tube with 5.00x6 6ply condor and 6.00x6 michelin tube. Disassembled, inspected, and reassembled wheel work done TAN piper maint, manual.
1-13-14	4581,0			Certify this Air Frame has been Inspected in Accordance with a 50 Hr Inspection and was Determined to be in Air Signed: SUB-TOTALS this page