Aircraft Rec	ord General Inforn	nation		
			Model L/GF Registration Number	
Date of Manufa	ecture 09/	2012	inegionation realises	
Engine(s) curre	TABIRU	Model 3300		Serial 33A 1813
Manufacturer_		Aodel		Serial
	rrently installed: SENSENIC	н	Model WC62	FK-S8
				Serial A 5 6313
Blade Model		Serial	Serial	Serial
Blade Model		Serial	Serial	Serial

I certify that this aircraft has been inspected in accordance with the scope and detail of Appendix D to Part 43 and found to be in a condition for safe operations.  9-14-2012  Reginald R. Corkum  Date  Owner/Builder	YEAR: JUIZ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs Entries must be endorsed with Name, Rating and C		DATE_	RECORDING TACH TIME	FLIGH
Reginald R. Corkum Date					accordance with the scope and d D to Part 43 and found to be in a	etail of Appendix condition for safe		-	
Owner/Builder — — — — — — — — — — — — — — — — — — —					Reginald R. Corkum				
		-			Owner/Builder			-	
						-1			

YEAR: RECORTACH TIME	DING TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repair® and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pagies for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT
			I find this Aircraft meets the requirements for the Airworthiness Certificate (AWC) requested and I have issued a SPECIAL-EXPERIMENTAL "for the Purpose of Operating Amateur Built -Aircraft" AWC  Gary D Meuer			

anufacturer TABIRO AIRCLAFT	DTY (T)	3300	
erial 33A KI3			Sertificate V/A
his engine is currently installed in aircraft			,
inimum Octane Fuel 100LC or 93 A	OCAS Oil Grade	Summer 100W	Winter 100W or 15W-50
	0	11	_ vviiito.
agneto Time 25° BTDC fixed	Roint Setting	.010"	Firing Order
park Plug Gap . OZZ "	Roint Setting	,010"	Firing Order
agneto Time 25° BTDC fixed	2000	, 010"	Firing Order

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Ø		Ø	Filled w/8.5 Qts Acroshell 100 mineral
Ø		以,2	Ran engine. Inspected for leaks - none found
		5	Retorque cylander head bolts @ 5 hrs
		15	Retorque cylander head bolts @ 15 hrs
0			
	TACH	TACH FLIGHT	TACH TIME FLIGHT TIME IN SERVICE

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT
DATE		