

ATTACHMENT 4

TO

MAINTENANCE RECORDS GROUP CHAIRMAN'S
FACTUAL REPORT

DCA13MA133

Major Alterations

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
54034655		02/15/2004	ST00440SE	A300-3440-13310-E	A300 ENHANCED GROUND PROXIMITY WARNING SYSTEM PEAKS AND OBSTACLES ACTIVATION		
54034655		02/15/2004	ST00381SE	A300-3440-13310-E	A300 ENHANCED GROUND PROXIMITY WARNING SYSTEM PEAKS AND OBSTACLES ACTIVATION		
54034664		02/15/2004	ST00440SE	A300-3440-12405-F	A300 ENHANCED GROUND PROXIMITY WARNING COMPUTER REPLACEMENT		
54034643		02/15/2004		A300-2550-12892-B	A300-600F: REMOVAL OF LD-6 RESTRAINT LOCKS IN FWD & AFT CARGO COMPARTMENTS		
54034605		03/01/2004	SA6076NM	A300-3440-15562-G	A300 TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS II) CHANGE 7.0 INSTALLATION		
54034583		09/04/2004	SA6076NM	M-3450-20413-C	ACSS TRANSPONDER SOFTWARE UPGRADE TO 7517800-10005 FOR ELEMENTARY AND ENHANCED SURVEILLANCE		

*entered in error
Ja.*

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
54034861		06/16/2005		A300-2220-21390-A	A300: REPLACE FLIGHT AUGMENTATION COMPUTER WITH NEW M8 STANDARD, SERVICE BULLETIN A300-22-6050		A300-22-6050
54034670		08/13/2005		A300-3450-20952-A	A300: REMOVE AND REPLACE ATC/TCAS CONTROL PANEL P/N G6992-21 WITH ATC/TCAS CP P/N G6992-28		
54034868		03/14/2006		A300-3460-21623-B	A300-FLIGHT MANAGEMENT COMPUTER (FMC) - VNAV PATH SOFTWARE UPGRADE AND CONVERSION OF P/N 4052510-979 TO P/N 4052510-981. AIRBUS SERVICE BULLETIN A300-34-6139		A300-34-6139
54034886		03/30/2006		A300-2560-23730-C	A300: ADDITIONAL EMERGENCY EQUIPMENT INSTALLATION		

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
54034897		10/17/2006	ST01185WI-D	A300-2310-20681-B	A300 COMMUNICATION - INSTALLATION OF HF ANTENNA COUPLERS AND ACTIVATION OF HIGH FREQUENCY (HF) COMMUNICATION SYSTEMS		
54034904		11/25/2006		A300-3150-22288-C	A300: ECAM W32 MOD. REPLACE ECAM SYMBOL GENERATOR UNIT P/N 9612670330 WITH P/N9612670330 WITH P/N 9612670332 AND WIRING CHANGES PER AIRBUS SB A300 -31-6124, A300-31-6116 AND A300-31-6117		A300-31-6124
54034904		11/25/2006		A300-3150-22288-C	A300: ECAM W32 MOD. REPLACE ECAM SYMBOL GENERATOR UNIT P/N 9612670330 WITH P/N9612670330 WITH P/N 9612670332 AND WIRING CHANGES PER AIRBUS SB A300 -31-6124, A300-31-6116 AND A300-31-6117		A300-31-6116

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
54034904		11/25/2006		A300-3150-22288-C	A300: ECAM W32 MOD. REPLACE ECAM SYMBOL GENERATOR UNIT P/N 9612670330 WITH P/N9612670330 WITH P/N 9612670332 AND WIRING CHANGES PER AIRBUS SB A300 -31-6124, A300-31-6116 AND A300-31-6117		A300-31-6117
54034923		12/07/2006	ST01185WI-D	A300-2310-20681-C	A300 COMMUNICATION - INSTALLATION OF HF ANTENNA COUPLERS AND ACTIVATION OF HIGH FREQUENCY (HF) COMMUNICATION SYSTEMS		
54034706		04/05/2007		A300-3150-22288-C	A300: ECAM W32 MOD. REPLACE ECAM SYMBOL GENERATOR UNIT P/N 9612670330 WITH P/N9612670330 WITH P/N 9612670332 AND WIRING CHANGES PER AIRBUS SB A300 -31-6124, A300-31-6116 AND A300-31-6117		A300-31-6116

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
54034706		04/05/2007		A300-3150-22288-C	A300: ECAM W32 MOD. REPLACE ECAM SYMBOL GENERATOR UNIT P/N 9612670330 WITH P/N9612670330 WITH P/N 9612670332 AND WIRING CHANGES PER AIRBUS SB A300 -31-6124, A300-31-6116 AND A300-31-6117		A300-31-6117
54034706		04/05/2007		A300-3150-22288-C	A300: ECAM W32 MOD. REPLACE ECAM SYMBOL GENERATOR UNIT P/N 9612670330 WITH P/N9612670330 WITH P/N 9612670332 AND WIRING CHANGES PER AIRBUS SB A300 -31-6124, A300-31-6116 AND A300-31-6117		A300-31-6124
54034698		11/15/2007		A300-3460-21623-D	A300-FLIGHT MANAGEMENT COMPUTER (FMC) - VNAV PATH SOFTWARE UPGRADE AND CONVERSION OF P/N 4052510-979 TO P/N 4052510-981. AIRBUS SERVICE BULLETIN A300-34-6139		A300-34-6139

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
54034723		06/16/2008	ST01459WI-D	M-2320-28388-D	COMMUNICATIONS - DLM/CMU 900 ACARS SOFTWARE INSTALLATION		
54034723		06/16/2008	ST01276WI-D	M-2320-28388-D	COMMUNICATIONS - DLM/CMU 900 ACARS SOFTWARE INSTALLATION		
54034675		08/03/2008		A300-2210-27613-A	A300: REPLACE FLIGHT CONTROL COMPUTERS WITH NEW M2 STANDARD. AIRBUS SERVICE BULLETIN A300-22-6053		A300-22-6053
54034683		08/31/2008	ST02877AT	M-3440-28906-B	MULTI-FLEET: ACSS MODE S ATC TRANSPONDER UPGRADE FROM 7517800-10005 TO 7517800-10007		
54034732		01/10/2009		A300-2130-26720-D	A300: CABIN PRESSURE CONTROL AND MONITORING - SERVICE BULLETIN A300-21-6049, AUTOMATIC OPENING LOGIC OF OUTFLOW VAVLES ON GROUND - AD 2007-25-06		A300-21-6049

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
54795561		05/06/2009		A300-2840-29652-B	A300: LEFT AND RIGHT OUTER FUEL TANK LOW LEVEL WARNING LIGHT DEACTIVATION - AIRBUS SB A300-28A6096		A300-28A6096
55971116		09/01/2009		A300-3150-29886-C	A300: INSTALL FLIGHT WARNING COMPUTER WITH NEW S15 SOFTWARE, ACTIVATE PROGRAM PIN OPTIONS FOR NEW S15 STANDARD AND FOR CABIN RESIDUAL PRESSURE INDICATION ONECAM WARNING PER SERVICE BULLETINS A300-31-6135,A300-31-6136,AND A300-21-6048		A300-31-6135

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
55971116		09/01/2009		A300-3150-29886-C	A300: INSTALL FLIGHT WARNING COMPUTER WITH NEW S15 SOFTWARE, ACTIVATE PROGRAM PIN OPTIONS FOR NEW S15 STANDARD AND FOR CABIN RESIDUAL PRESSURE INDICATION ONECAM WARNING PER SERVICE BULLETINS A300-31-6135,A300-31-6136,AND A300-21-6048		A300-21-6048
55971116		09/01/2009		A300-3150-29886-C	A300: INSTALL FLIGHT WARNING COMPUTER WITH NEW S15 SOFTWARE, ACTIVATE PROGRAM PIN OPTIONS FOR NEW S15 STANDARD AND FOR CABIN RESIDUAL PRESSURE INDICATION ONECAM WARNING PER SERVICE BULLETINS A300-31-6135,A300-31-6136,AND A300-21-6048		A300-31-6136

Major Alteration Current Status Summary Report

Printed: 08/14/2013 06:57:30

Tail:N155UP Major Alteration

Total records: 32

Doc ID	Engine Serial Number	Date	STC Number	EO Number	EO Description	Vendor Doc Number	SB Number
58960482		10/02/2010	ST02866CH	M-2320-37453-B	A300/B757/B767/MD11: ACARS CORE 6.15 AND AOC 103 SOFTWARE INSTALLATION		
60961691		07/10/2011		A300-3460-38997-D	A300 - FLIGHT MANAGEMENT COMPUTER (FMC) - MAGVAR SOFTWARE UPGRADE AND CONVERSION OF P/N 4052510-981 TOP/N 4052510-983. AIRBUS SB A300-34-6172/HONEYWELL SB 4052510-34-6030		A300-34-6172
60961691		07/10/2011		A300-3460-38997-D	A300 - FLIGHT MANAGEMENT COMPUTER (FMC) - MAGVAR SOFTWARE UPGRADE AND CONVERSION OF P/N 4052510-981 TOP/N 4052510-983. AIRBUS SB A300-34-6172/HONEYWELL SB 4052510-34-6030		4052510-34-6030
62306560		01/26/2012	ST03921AT	M-2370-42815-D	MULTI-FLEET:2 HOUR COCKPIT VOICE RECORDER (CVR) COMPLIANCE FOR CFR PART 121.359 (I)		