

COPY

CIU
LANES

WO# 31301025

N 1120W S/N B0386 OWNER Martinaire

PAGE 01/01

Date: 1-15-13		Description of discrepancy		Description of inspection and/or repair								
ACTT:	10132.1	Hobbs:	0425.6	Engine/Prop S/N: (Lt)	(Rt)	Insp	mech	date	hours			
SQ#	ATA	A/C LANDINGS:	156289	SQ#	Component S/N: off	18986	on	5610				
1	34	Pilot reports L/H Attitude Gyro inop in CIU.		1	Flew From LAN to CIU. Removed and replaced L/H Attitude gyro with repaired serviceable gyro. IAW c208 M.M. Ch. 37-20-00 pg 205 Sec 7A,B. Ran engines. ops checks good. Flew From CIU-LAN				CS	CS	1-15	3.0

SQ#	QTY	Part Number	Description	SQ#	QTY	Part Number	Description
	1	060-0017-00	S/N 5610 KI-256 Flight Command Indicator				

COPY

< Check box if back is used for additional parts issued.

The aircraft and/or component has been inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Martinaire Aviation LLC., 2618 East Circle Drive, Lansing, MI. Repair Station No. M36R626Y

ACTT 10132.1 DATE 1-15-13 HOBBS 425.6

Inspector's Signature: [Redacted]

1-15-13	1-15-13	1-15-13	1-15-13
CS Preliminary	CS Hidden	CS Progressive	CS Final

Inspector's Stamp or Initials & Date

Form MI-108

01/15/2013 15:54

DOUG PARTS