

Attachment 3

Minimum Equipment List Defect Log

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 1

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2007/07/20	34100	86	2 M MEL PSION LOAD PLAN COMPUTER S/N ABXS150 WILL NOT PRINT.	56236	1
799AX	2007/07/20	34100	86	2 M MEL DEFERRED: 56236 DEFERRED PER MEL 25-63-5 TIME LIMIT CODE 14. MBCB		1
799AX	2007/07/20	34100	86	2 M MEL 11/17/07.		1
799AX	2007/07/22	34100	91	2 M OWRKING DI 56236		3
799AX	2007/07/22	34100	91	2 M CLEAR DI 56236 REMOVED & REPLACED #2 LOAD PLAN COMPUTER		3
799AX	2007/07/22	34100	91	2 M IAW AMM 25-57-33-5 OPS CHECK NORMAL PLACARD REMOVED.		3
799AX	2007/07/24	34100	93	1 P MEL 74 21 01 02 RIGHT ENG FAILED TO LIGHT OFF WITH IGN 1 SELECTED. START	56262	1
799AX	2007/07/24	34100	93	1 P MEL NORMAL WITH SW IN BOTH.		1
799AX	2007/07/24	34100	93	1 P MEL DEFERRED DI 56262. DEFERRED #1 IGN IAW B767 MEL 74-00-1B, CAT C, CODE		1
799AX	2007/07/24	34100	93	1 P MEL 11. MBCB 8-3-07. PLACARD INSTALLED.		1
799AX	2007/07/24	34100	95	1 M DI#56262 IN WORK RIGHT ENG PLUG 1 FAILED TO START		3
799AX	2007/07/24	34100	95	1 M CLR # 56262 REPLACED LEAD AND PLUG AND CK'D OK PER AMM 74-21-01		3
799AX	2007/07/25	34184	0	1 M MEL STATUS MSG "CABIN ALT AUTO 1" DISPLAYED ON EICAS.	56282	1
799AX	2007/07/25	34184	0	1 M MEL DEFERRED 56282 DEFERRED CABIN ALT AUTO 1 IAW B767 MEL 21-31-1A,		1
799AX	2007/07/25	34184	0	1 M MEL CAT C, CODE 11. MBCB 08/04/07. PLACARD INSTALLED.		1
799AX	2007/07/26	34184	5	2 M DI#56282 IN WORK CABIN ALT AUTO 1 INOP		3
799AX	2007/07/26	34184	5	2 M CLR#56282 REMOVED AND REPLACED #1 AUTO CABIN PRESSURE CONTROLLER AIW		3
799AX	2007/07/26	34184	5	2 M B767 MM 21-31-02-4 CHECKS NORMAL PLACARDS REMOVED		3
799AX	2007/07/25	34184	2	1 M MEL PALLET LOCK 42G BROKEN AT STATION 1225 POSITION M8R.	56284	1
799AX	2007/07/25	34184	2	1 M MEL DEFERRED 56284 REMOVED LOCK DEFERRED PER MEL 25-54-1A		1
799AX	2007/07/25	34184	2	1 M MEL CAT C CODE 11 MAINT PROCEDURED C/W PLACARD INSTALLED.		1
799AX	2007/07/26	34184	4	1 M WORKING DI 56284 BROKE FLOOR LOCK UPPER CARGO.		3
799AX	2007/07/26	34184	4	1 M CLEAR DI 56284 REPLACED FLOOR LOCK PART # 56320-01 CLEAR DI		3
799AX	2007/07/26	34184	4	1 M AN REMOVED PLACARD AS REQUIRED.		3
799AX	2007/08/01	34184	17	1 M MEL YELLOW REV LIGHT RIGHT REVERSER ILLUMINATED SENSOR 171 FAULTED	56362	1
799AX	2007/08/01	34184	17	1 M MEL ON PROX. UNIT.		1
799AX	2007/08/01	34184	17	1 M MEL DEFERRED 56362 DEFERRED RIGHT THRUST REVERSER IAW B767		1
799AX	2007/08/01	34184	17	1 M MEL MEL 78.31.1A MAINT. PROCEDURES COMPLIED WITH. PLACARD INSTALLED A/C		1
799AX	2007/08/01	34184	17	1 M MEL RELEASED TO CAT III OPERATIONAL. CAT C CODE 11 MBCB 8/11/07		1
799AX	2007/08/01	34184	21	1 M WORKING DI #56362 RT T/R LIGHT AMBER		2
799AX	2007/08/01	34184	21	1 M T/S #56362 PERFORMED BITE CHECK OF PSEU. FAULT #171 STORED.		2
799AX	2007/08/01	34184	21	1 M REACTIVATED RIGHT T/R. CYCLED SEVERAL TIMES NO FAULTS STORED.		2
799AX	2007/08/01	34184	21	1 M DEACTIVATED RT T/R IAW B767 MEL 78-31-1A. CHECKED WIRING TO T/R STOW		2
799AX	2007/08/01	34184	21	1 M SW #165 NO DEFECTS NOTED NEW SW RIDING IN COCKPIT LIBRARY ITEM REMAINS		2
799AX	2007/08/02	34184	27	1 M ON DI		2
799AX	2007/08/02	34184	27	1 M WORKING DI #56362 R T/R LIGHT AMBER		3
799AX	2007/08/02	34184	27	1 M CLEAR #56362 FOUND WIRE W332-07TB-20 BROKE AT SPLICE SM 2. RESPLICED		3
799AX	2007/08/02	34184	27	1 M WIRE AS REQUIRED RT T/R OPERATIONAL CHECK GOOD IAW B767 MM CHAPTER		3
799AX	2007/08/02	34184	27	1 M 78-31-00. A/C RELEASED CAT IIIB OPERATIONAL PLACARD REMOVED		3
799AX	2007/08/01	34184	22	1 P MEL 36 10 XA R ISLN VALVE FAILED IN CLSD POSITION - NO EICAS MSG	56376	1
799AX	2007/08/01	34184	22	1 P MEL DEFERRED #56376 DEFERRED RT ISOLATION VALVE PER MEL 36-11-6 CAT C		1
799AX	2007/08/01	34184	22	1 P MEL CODE 11 MBCB 8-11-07 C/B PULLED PLACARD INSTALLED MAINT PROCEDURES		1
799AX	2007/08/01	34184	22	1 P MEL C/W		1
799AX	2007/08/01	34184	23	1 M WORKING DI #56376		3

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 2

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2007/08/01	34184	23	1 M CLEAR #56376 RIGHT ISOLATION VALVE OPERATES NORMALLY IAW B767 MM REF	56376	3
799AX	2007/08/01	34184	23	1 M 36-11-04-4. PLACARD REMOVED		3
799AX	2007/08/14	34097	6	2 M MEL SECOND OBSERVERS O2 MASK NOT WORKING PROPERLY	56574	1
799AX	2007/08/14	34097	6	2 M MEL DEFER #56574		1
799AX	2007/08/14	34097	6	2 M MEL DEFERRED 2ND OBSERVERS SEAT IAW 767 MEL 35-11-2-2 CAT D CODE 14		1
799AX	2007/08/14	34097	6	2 M MEL MBCB 12/12/07 MUST BER REPAIRED REPLACED BY 12/12/07 PLACARDED		1
799AX	2007/08/15	34097	10	2 M WORKING DI #56574 OBSERVERS O2 MASK		3
799AX	2007/08/15	34097	10	2 M CLEAR #56574 REMOVED & REPLACED OBSERVERS O2 REG BOX ASSY IAW B767 MM		3
799AX	2007/08/15	34097	10	2 M 35-11-51-4. LK & OPS CK GOOD PLACARD REMOVED		3
799AX	2007/08/14	34097	8	1 M MEL RIGHT T/R REV UNLOCK LIGHT ILLUMINATED	56577	1
799AX	2007/08/14	34097	8	1 M MEL DEFERRED #56577 DEFERRED I/A/W 767 MEL 78-36-1A ACCOMPLISHED MX		1
799AX	2007/08/14	34097	8	1 M MEL PROCEDURE 78-31-1 PLACARDED CODE 11 CAT C MBCB 8-24-07		1
799AX	2007/08/15	34097	10	3 M WORKING DI #56577 RT T/R UNLOCK LIGHT		3
799AX	2007/08/15	34097	10	3 M CLEAR #56577 PERFORMED BITE ON PSEU. NO FAULTS. INSPECTED WIRING ON		3
799AX	2007/08/15	34097	10	3 M ENG TO PYLON & SHOOK. NO FAULTS. CHECKED CLEARANCES OF ALL SWITCHES		3
799AX	2007/08/15	34097	10	3 M IAW B767 MM 78-36-01-4. TARGETS CK GOOD. CYCLED T/R 25 TIMES NO FAULTS		3
799AX	2007/08/15	34097	10	3 M CLEARED DI PLACARD REMOVED		3
799AX	2007/08/20	34097	23	2 M MEL PER MAINTENANCE CONTROL DEACTIVATE AND DEFER RT ENG THRUST REVERSER	56663	1
799AX	2007/08/20	34097	23	2 M MEL FOR AMBER LIGHT HISTORY.		1
799AX	2007/08/20	34097	23	2 M MEL DEFERRED: 56663 DEFERRED RT ENG THRUST REVERSER PER B767 MEL 78-31-1A		1
799AX	2007/08/20	34097	23	2 M MEL MAINTENANCE PROCEDURE 78-31-1 C/W. MBCB AUG. 30, 07. PLACARD INSTALLED		1
799AX	2007/08/20	34097	23	2 M MEL AIRCRAFT RELEASED CAT IIIA OPERATIONAL. CODE 11.		1
799AX	2007/08/21	34097	25	2 M WORKING DI 56663 RT ENG T/R.		2
799AX	2007/08/21	34097	25	2 M T/S DI 56663 R & R ACTUATOR LOCK PROXIMITY SENSOR ON RIGHT ENG. DUE		2
799AX	2007/08/21	34097	25	2 M TO NUMEROUS SPLICES ON CONNECTORS. IAW B767 MM 78-36-01-4.		2
799AX	2007/08/21	34097	25	1 M RIGHT ENGINE THRUST REVERSER LIGHT INTERMITTENT.		3
799AX	2007/08/21	34097	25	1 M CLEAR DI 56663 REMOVED & REPLACED PSEU RT T/R INDICATION CARDS M-5		3
799AX	2007/08/21	34097	25	1 M & M-6 IAW B767 MM 32-09-06-4. REF ITEM 2 THIS LOG PAGE FOR OTED		3
799AX	2007/08/21	34097	25	1 M ACTUATOR SENSOR REPLACEMENT & OPS CK. PLACARD REMOVED AIRCRAFT		3
799AX	2007/08/21	34097	25	1 M RELEASED TO CAT IIIB OPS.		3
799AX	2007/08/28	34097	38	1 M MEL "REV" AMBER INDICATION ON EICAS WITH REVERSER STORED ON RT ENG	56793	1
799AX	2007/08/28	34097	38	1 M MEL DEFER #56793 MEL CODE 11		1
799AX	2007/08/28	34097	38	1 M MEL DEFERRED THE RT THRUST REVERSER IAW B767 MEL 78-31-1A CAT C CODE 11		1
799AX	2007/08/28	34097	38	1 M MEL C/W MAINTENANCE PROCEDURES 78-31-1 PLACARD INSTALLED. AIRCRAFT		1
799AX	2007/08/28	34097	38	1 M MEL RELEASED CAT IIIA		1
799AX	2007/08/30	34097	44	1 M WORKING DI #56793 AMBER "REV" WITH RT REVERSER STOWED		2
799AX	2007/08/30	34097	44	1 M T/S #56793 VERIFIED RESISTANCE OF RH ACTR LOCK PROX SENSOR S165 WITH		2
799AX	2007/08/30	34097	44	1 M NO DEFECTS NOTED REITERMINATED SPLICE SM2 DUE TO RESISTANCE CHECK AND		2
799AX	2007/08/30	34097	44	1 M HAVING TO CUT OFF TEFLON SLEEVE. ALL WIRING BACK TO ORIGINAL		2
799AX	2007/08/30	34097	44	1 M CONFIGURATION. ITEM REMAINS ON DI ALL WIRING IAW B767 WDM 78-36-21 PG1		2
799AX	2007/08/30	34097	44	2 M WORKING DI #56793 RT ENG REVERSER		3
799AX	2007/08/30	34097	44	2 M CLEAR #56793 REMOVED & REPLACED PSEU, OPS CK OF PSEU & REVERSER GOOD		3
799AX	2007/08/30	34097	44	2 M IAW B767 MM 32-09-04-4. ACFT RELEASED TO CAT IIIB OPERATIONAL		3
799AX	2007/08/30	34097	44	2 M PLACARD REMOVED		3

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 3

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2007/09/05	34293	52	1 P MEL 34 61 16 01 CAPT CDU DISPLAY BLANK. SELECTING ALTERNATE FMC SOURCE	56876	1
799AX	2007/09/05	34293	52	1 P MEL DID NOT CORRECT FAULT		1
799AX	2007/09/05	34293	52	1 P MEL DEFERRED #56876 DEFERRED LEFT FMC CDU INOP PER B767 MEL 34-61-1-1A		1
799AX	2007/09/05	34293	52	1 P MEL CAT C CODE 11 PLACARD INSTALLED MBCB 9-15-07		1
799AX	2007/09/05	34293	54	1 M WORKING DI 56876		3
799AX	2007/09/05	34293	54	1 M CLEAR DI 56876 REMOVED AND REPLACED CAPTS FMC CONTROL DISPLAY,		3
799AX	2007/09/05	34293	54	1 M TEST GOOD IAW B767 AMM 34-61-02-2 10. PLACARD REMOVED.		3
799AX	2007/09/06	34293	58	1 M MEL LH INB TAIL NAV LIGHT INOP ON WALKAROUND.	56930	1
799AX	2007/09/06	34293	58	1 M MEL DEFERRED 56930 DI FOR LIGHT INOP PER MEL 33-43-1-1B.		1
799AX	2007/09/06	34293	58	1 M MEL MBCB 9-17-2007. CODE 11		1
799AX	2007/09/07	34293	60	1 M WORKING DI 56930 C/W INB TAIL NAV LIGHT INOP		3
799AX	2007/09/07	34293	60	1 M CLR #56930.		3
799AX	2007/09/07	34293	60	1 M RELAMPED LIGHT. OPS CHECKS GOOD IAW ABX 767 AMM 33-43-02 DI CLEARED		3
799AX	2007/09/07	34293	60	1 M PLACARD REMOVED		3
799AX	2007/09/08	34293	63	1 P MEL 23 12 09 04/05 XMISS & REC ON C VHF INOP ALL STATIONS.	56965	1
799AX	2007/09/08	34293	63	1 P MEL DEFERRED 56965 DEFERRED "C" VHF I/A/W 767 MEL 23-11-1. CAT D.		1
799AX	2007/09/08	34293	63	1 P MEL MBCB 1/6/08. PLACARDED. CODE 14		1
799AX	2007/09/08	34293	65	1 M WORKING DI 56965 DI IN WORK (C/VHF/COMM)		3
799AX	2007/09/08	34293	65	1 M CLEAR DI 56965 VERIFIED CENTER VHF COMM TRANCEIVER INSP/DEAD.		3
799AX	2007/09/08	34293	65	1 M REMOVED AND REPLACED CNETER VHF COMM TRANSCEIVER. SYSTEM CHECKS GOOD		3
799AX	2007/09/08	34293	65	1 M ON GND IAW ABX 767 GMM 23-12-01-4. PLACARD REMOVED.		3
799AX	2007/09/12	34293	74	2 M MEL WHILE PERFORMING PREDEPARTURE CK, FOUND LEFT FWD NAV LIGHT INOP.	57026	1
799AX	2007/09/12	34293	74	2 M MEL RELAMPED WITH NO HELP. (LEFT WING)		1
799AX	2007/09/12	34293	74	2 M MEL DEFERRED #57026 DEFERRED IAW B767 MEL 33-43-1-1B CAT C. MBCB 09-22-07		1
799AX	2007/09/12	34293	74	2 M MEL PLACARD INSTALLED CODE 11		1
799AX	2007/09/13	34293	75	1 M DI#57026 IN WORK LH FWD NAV LIGHT INOP		3
799AX	2007/09/13	34293	75	1 M CLR#57026 RELAMPED FWD BULB ON LT NAV LIGHT AS REQUIRED CHECKS GOOD		3
799AX	2007/09/13	34293	75	1 M PLACARD REMOVED		3
799AX	2007/09/21	34293	94	1 P MEL PEDESTAL LIGHTS FOR SPEEDBRAKE HANDLE NOT ILLUMINATED (EXCEPT FRO UP	57170	1
799AX	2007/09/21	34293	94	1 P MEL POSITION)		1
799AX	2007/09/21	34293	94	1 P MEL DEF DI 57170 DEFERRED THE SPEEDBRAKE LIGHT PANEL PER MEL 33-11-19		1
799AX	2007/09/21	34293	94	1 P MEL PLACARD INSTALLED		1
799AX	2007/09/21	34293	97	1 M DI 57170 IN WORK.		3
799AX	2007/09/21	34293	97	1 M CLEARED: 57170 RELAMPED OPS CHECKS GOOD ABX PSM 900-9-1-11. PLACARD		3
799AX	2007/09/21	34293	97	1 M REMOVED.		3
799AX	2007/09/25	34162	5	3 M MEL PSION W/B COMPUTER #2, PT #A08484-503, S/N ABXS570 HAS MAINT CHK. EXE	57212	1
799AX	2007/09/25	34162	5	3 M MEL ERROR, TYPE LOAD EXCEPTION		1
799AX	2007/09/25	34162	5	3 M MEL DEFERRED #57212 DEFERRED IAW B767 MEL 25-63-5. MBCB 01-23-08		1
799AX	2007/09/25	34162	5	3 M MEL PLACARD INSTALLED CODE 14		1
799AX	2007/09/26	34162	12	1 M DI 57212 IN WORK. PSION WBC #2.		2
799AX	2007/09/26	34162	12	1 M T/S: 57212 PSION WBC #2 PROGRAM CORRUPT. COLD REST NO HELP. REMAINS		2
799AX	2007/09/26	34162	12	1 M ON DI.		2
799AX	2007/09/28	34162	18	1 M WORKING DI 57212 PSION WBQ #2		3
799AX	2007/09/28	34162	18	1 M CLR DI 57212 VERIFIED-REPROGRAMED #2 PSION WORK ABOUT OPS CHK		3

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 4

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2007/09/28	34162	18	1 M CHK GOOD IAW B767 MM 25-57-33-5 PLACARD REMOVED	57212	3
799AX	2007/10/02	34162	25	2 M MEL OUTBASE WEIGHT /BALANCE COMPUTERS LCD SCREEN NOT READABLE	57306	1
799AX	2007/10/02	34162	25	2 M MEL DEFER #57306 MEL CODE 14		1
799AX	2007/10/02	34162	25	2 M MEL DEFERRED "OUTBASE" WEIGHT/BALANCE COMPUTER IAW MEL 25-63-5 CAT C CODE		1
799AX	2007/10/02	34162	25	2 M MEL 14 THIS IS DI #57306 PLACARD INSTALLED. MAINT PROCEDURES C/W		1
799AX	2007/10/02	34162	25	2 M MEL MBCB 30 JAN 08		1
799AX	2007/10/03	34162	27	1 M WORKING DI 57306 OUTBASE WBC		3
799AX	2007/10/03	34162	27	1 M CLR DI 57306 REMOVED AND REPLACED OUTBASE WBC CHKS OK IAW 767AMM		3
799AX	2007/10/03	34162	27	1 M 25-57-02 PLACARD REMOVED		3
799AX	2007/10/16	34584	11	1 M MEL TAKE OFF CONFIG LIGHT ON, FLAP WARNING & AURAL WARNING HORN	57446	1
799AX	2007/10/16	34584	11	1 M MEL DEFERRED #57446 DEFERRED LEFT EICAS COMPUTER PER MEL 31-41-1-2 CAT A		1
799AX	2007/10/16	34584	11	1 M MEL CODE 27 MAINT PROCD C/W PLACARD INSTALLED		1
799AX	2007/10/16	34584	12	3 M WORKING DI 57446		3
799AX	2007/10/16	34584	12	3 M LT EICAS COMPUTER		3
799AX	2007/10/16	34584	12	3 M CLR DI 57446 REMOVED AND REPLACED LEFT EICAS COMPUTER WITH SERVICABLE		3
799AX	2007/10/16	34584	12	3 M ASSY, REFI B767 AMM 31-41-02 PLACARD REMOVED		3
799AX	2007/10/16	34584	11	2 M MEL LEFT AFT I/B POSITION LIGHT INOP	57447	1
799AX	2007/10/16	34584	11	2 M MEL DEFERRED #57447 RELAMPED NO HELP. DEFERRED PER MEL 33-43-1-1B CAT C		1
799AX	2007/10/16	34584	11	2 M MEL CODE 11 MAINT PROC. C/W PLACARD INSTALLED		1
799AX	2007/10/16	34584	15	2 M DI 57447 IN WORK. LEFT I/B POSITION LIGHT INOP.		3
799AX	2007/10/16	34584	15	2 M CLEARED: 57447 FOUND LEFT AFT I/B POSITION LIGHT BULB LOOSE,		3
799AX	2007/10/16	34584	15	2 M RESECURED BULB. OPS CHECKED GOOD. PLACARD REMOVED.		3
799AX	2007/10/16	34584	13	1 M MEL OTB WBC DISPLAY UNREADABLE.	57452	1
799AX	2007/10/16	34584	13	1 M MEL DEFERRED: 57452 DEFERRED PER B767 MEL 25-63-5. MBCB 2-13-08. PLACARD		1
799AX	2007/10/16	34584	13	1 M MEL INSTALLED. CODE 14.		1
799AX	2007/10/16	34584	15	3 M DI 57452 IN WORK. OUTBASE WBC DISPLAY BAD.		3
799AX	2007/10/16	34584	15	3 M CLEARED: 57452 REMOVED AND REPLACED OUTBASE WBC. OPS CHECKS GOOD IAW		3
799AX	2007/10/16	34584	15	3 M B767 AMM 25-57-00. PLACARD REMOVED.		3
799AX	2007/10/17	34584	20	1 M MEL WEIGHT AND BALANCE COMPUTER WILL NOT FEED PAPER	57476	1
799AX	2007/10/17	34584	20	1 M MEL DEFERRED DI 57476 PER MEL 25-63-5 CAT D CODE 14 MAINT PROCD C/W		1
799AX	2007/10/17	34584	20	1 M MEL PLACARD INSTALLED.		1
799AX	2007/10/17	34584	21	2 M WORKING DI 57476. WBC PRINTER WILL NOT FEED PAPER.		3
799AX	2007/10/17	34584	21	2 M CLEARED DI 57476. REMOVED AND REPLACED WBC PRINTER. WBC PRINTER OPS		3
799AX	2007/10/17	34584	21	2 M CHECKS GOOD IAW B767 AMM 25-57-00. PLACARD REMOVED.		3
799AX	2007/10/23	34584	37	1 P MEL BOTH N1 AND EGT NAILS FLUTTERING RAPIDLY WITH L EICAS STATUS MESSAGE	57549	1
799AX	2007/10/23	34584	37	1 P MEL DEFER #57549 MEL CODE 27		1
799AX	2007/10/23	34584	37	1 P MEL DEFERRED L EICAS COMPUTER PER MEL 31-41-12 CAT A CODE 27 MBCB 1 FLT		1
799AX	2007/10/23	34584	37	1 P MEL DAY CIRCUIT BREAKER PULLED AND COLLARD AND PLACARD INSTALLED		1
799AX	2007/10/24	34584	39	1 M WORKING DI 57549 LT EICS COMPUTER.		3
799AX	2007/10/24	34584	39	1 M CLEAR DI 57549 R & R'ED LT EICAS COMPUTER IAW B767 AMM		3
799AX	2007/10/24	34584	39	1 M SYS TESTS GOOD PLACARD REMOVED.		3
799AX	2007/11/13	34527	81	2 M MEL OBSERVERS SEAT AUDIO SELECT PANEL IN-OPERATIVE.	57834	1

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 5

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2007/11/13	34527	81	2 M MEL DEFERRED DI# 57834 DEF. AUDIO PANEL PER 767 MEL 25-11-2-2 MUST BE	57834	1
799AX	2007/11/13	34527	81	2 M MEL CLEARED BY 03/12/08. CODE 14		1
799AX	2007/11/13	34527	84	1 M WORKING DI 57834 RT OBSERVERS AUDIO PANEL		3
799AX	2007/11/13	34527	84	1 M CLEAR DI 57834 REMOVED AND REPLACED RT OBSERVERS AUDIO PANEL CKS		3
799AX	2007/11/13	34527	84	1 M GOOD IAW 767 MM 23-51-01 PLACARDS REMOVED		3
799AX	2007/11/13	34527	82	1 P MEL RT ENG VIBS REACHED 2.8 FAN IN CLIMBOUT. SECOND WRITE UP EVENT	57839	1
799AX	2007/11/13	34527	82	1 P MEL RECORDED		1
799AX	2007/11/13	34527	82	1 P MEL DEF DI 57839 EXAMING ENG #2 BEHOUST INLETS MASTER CHIP DETECTION AND		1
799AX	2007/11/13	34527	82	1 P MEL COMPLETE ENG INTERIOR FOR OBVIOUS DEFECTS, NONE FOUND, REF FIM		1
799AX	2007/11/13	34527	82	1 P MEL 71-05-00 DEFERRED VIBRATION INDICATION SYSTEM IAW ABX MEL 77-31-1		1
799AX	2007/11/13	34527	82	1 P MEL PLACARD INSTALLED CREW ADVISED NO VIBRATION WAS FELT		1
799AX	2007/11/14	34527	86	1 M WORKING DI 57839 IN WORK		3
799AX	2007/11/14	34527	86	1 M CLR DI 57839 REMOVED FAN BLADES CLEANED, LUBED AND REINSTALLED BLADES		3
799AX	2007/11/14	34527	86	1 M IAW B767 MM 72-31-02-4 AND 72-31-02-7 RAN #2 ENG TO T/O 103%. MAX		3
799AX	2007/11/14	34527	86	1 M STEADY VIBE OF 1.9 @ 101.0% N1 RETORQUED SPINNER IAW 767 MM		3
799AX	2007/11/14	34527	86	1 M 72-31-01-4 PLACARD REMOVED		3
799AX	2007/11/20	34011	0	1 P MEL 21 30 17 02 EICAS MSG CABIN ALT AUTO 2 DISPLAYED AIRCRAFT ON	57906	1
799AX	2007/11/20	34011	0	1 P MEL GROUND MSG WOULD NOT CLEAR.		1
799AX	2007/11/20	34011	0	1 P MEL DEFERRED 57906 DEFERRED CABIN ALT AUTO 2 IAW MEL 21-31-1A		1
799AX	2007/11/20	34011	0	1 P MEL CAT "C" CODE 11 THIS IS DI # 57906 PLACARD INSTALLED MAINT.		1
799AX	2007/11/20	34011	0	1 P MEL PROCEDURES C/W MBCB NOV. 30, 2007.		1
799AX	2007/11/20	34011	1	2 M WORKING DI 57906		2
799AX	2007/11/20	34011	1	2 M T/S DI 57906 PERFORMED BITE ON #2 CABIN AUTO PRESURIZATION CONTROLLER		2
799AX	2007/11/20	34011	1	2 M PER B767 AMM 21-30-00 OPS CK OK ITEM REMAINS ON DI		2
799AX	2007/11/21	34011	6	3 M WORKING DI 57906 DI IN WORK (CABIN PRESSURE CONTROLLER)		3
799AX	2007/11/21	34011	6	3 M CLEAR DI 57906 REMOVED & REPLACED THE #2 CABIN PRESSURE CONTROLLER		3
799AX	2007/11/21	34011	6	3 M PER AMM 21-31-02. PLACARDS REMOVED.		3
799AX	2007/11/20	34011	3	1 P MEL EICAS BAL KNOB LOOSE, DOES NOT AFFECT BALANCE OF BOTH EICAS DISPLAYS	57917	1
799AX	2007/11/20	34011	3	1 P MEL DEFERRED #57917 BALANCE KNOB LIGHTING DEFERRED PER MEL 33-11-1A, DI		1
799AX	2007/11/20	34011	3	1 P MEL #57917 PLACARD INSTALLED AND C/W MAINT PROCEDURES MBCB 12-01-07 CODE		1
799AX	2007/11/20	34011	3	1 P MEL 11		1
799AX	2007/11/21	34011	4	1 M WORKING DI #57917		3
799AX	2007/11/21	34011	4	1 M CLEAR #57917 REPLACED EICAS DISPLAY SELECT PANEL PER B767 MM 31-41-03		3
799AX	2007/11/21	34011	4	1 M -4 OPS CHECK GOOD PLACARD REMOVED		3
799AX	2007/11/22	34011	8	1 M MEL EICAS STATUS MESSAGE CABIN ALT AUTO 1	57931	1
799AX	2007/11/22	34011	8	1 M MEL DEFERRED #57931 DEFERRED AUTO PRESSURE CONTROL SYSTEM 1 PER MEL 21-31		1
799AX	2007/11/22	34011	8	1 M MEL -1A MAINTENANCE PROCEDURES C/W PLACARD INSTALLED. MBCB 12-20-07		1
799AX	2007/11/22	34011	8	1 M MEL CODE 11		1
799AX	2007/11/22	34011	9	3 M WORKING DI #57931 T/S "CABIN ALT AUTO 1"		2
799AX	2007/11/22	34011	9	3 M T/S #57931 T/S PER FIM 21-31-00 FIG 109 AND BITE TEST SHOWS "AC		2
799AX	2007/11/22	34011	9	3 M MOTOR" ON CONTROLLER NO. 1 VERIFIED & RESET - OK. MSG CLEARED INSP		2
799AX	2007/11/22	34011	9	3 M BOTH FLOW CONTROL THROAT PRESSURE SENSING PROBES FOR DAMAGE, NONE		2
799AX	2007/11/22	34011	9	3 M FOUND. DI STILL VALID		2
799AX	2007/11/22	34011	10	3 M WORKING DI #57931 CABIN ALT AUTO 1		3
799AX	2007/11/22	34011	10	3 M CLEAR #57931 REMOVED & REPLACED OUTFLOW VALVE MOTOR ASSY INCLUDING		3

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 6

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2007/11/22	34011	10	3 M ACTUATOR PER AMM 21-31-05, NOTE, FREEDOM OF OUTFLOW VALVE CHECKED TO	57931	3
799AX	2007/11/22	34011	10	3 M BE NORMAL. DI CLEARED. PLACARD REMOVED		3
799AX	2007/12/15	33945	69	1 P MEL 49 11 05 00 APU FAILED TO START. FAULT LGT ILLUM & EICAS MSG APU	58291	1
799AX	2007/12/15	33945	69	1 P MEL FAULT DISPLAYED. ADDITIONAL START ATTEMPTS UNSUCCESSFUL.		1
799AX	2007/12/15	33945	69	1 P MEL DEFERRED: 58291 DEFERRED APU PER B767 MEL 49-11-1A. CAT "C", CODE 11.		1
799AX	2007/12/15	33945	69	1 P MEL MAINT. PROC. C/W. PLACARD INST. MBCB 12-25-07.		1
799AX	2007/12/17	33945	71	2 M WORKING DI 58291 APU DEFERRAL		3
799AX	2007/12/17	33945	71	2 M CLEARING DI 58291 R & R LOW PRESSURE SWITCH PER AMM 49-74-02-4. OPS		3
799AX	2007/12/17	33945	71	2 M CK'S OK PLACARD REMOVED.		3
799AX	2007/12/19	33945	79	1 M MEL FWD LOWER CARGO COMPARTMENT HAS A CARGO LATERAL LOCK ELECTRICALLY	58341	1
799AX	2007/12/19	33945	79	1 M MEL INOP - POSITION 2L.		1
799AX	2007/12/19	33945	79	1 M MEL DEFERRED DI 58341. LOCK WORKS MANUALLY; DEFERRED FWD LOWER CARGO		1
799AX	2007/12/19	33945	79	1 M MEL HANDLING SYSTEM IAW B767 MEL 25-53-1. MAINTENANCE PROCEDURES C/WED,		1
799AX	2007/12/19	33945	79	1 M MEL PLACARD INSTALLED. MBCB 4-17-08. CODE 14.		1
799AX	2007/12/19	33945	82	3 M WORKING DI 58341 WORKING DI		3
799AX	2007/12/19	33945	82	3 M CLEAR DI 58341 PERFORMED OPERATIONAL CK FLC CARGO SYSTEM		3
799AX	2007/12/19	33945	82	3 M GUIDES & DRIVES NO DEFECT NOTED.		3
799AX	2007/12/24	33945	94	1 P MEL APU WOULD NOT START ON THE DESCENT OR ON THE GRND.	58401	1
799AX	2007/12/24	33945	94	1 P MEL DEFERRED 58401 DEFERRED AIW MEL 49-11-1A PLACARDS		1
799AX	2007/12/24	33945	94	1 P MEL INSTALLED MBCB 01/04/08 CODE 11		1
799AX	2007/12/29	34885	53	1 M WORKING DI 58401 APU		3
799AX	2007/12/29	34885	53	1 M CLEAR DI 58401 REMOVED AND REPLACED APU IAW B767 AMM 49-11-01-4		3
799AX	2007/12/29	34885	53	1 M OPC GOOD. PLACARD REMOVED.		3
799AX	2008/01/07	34885	69	1 M MEL CTR & RT READING LIGHTS INTERMITTENT - SUPERNUMERARY	58565	1
799AX	2008/01/07	34885	69	1 M MEL DEFERRED #58565 DEF PER MEL 33-14-1 MPCW PLAC INSTALLED MBCB 5-7-8		1
799AX	2008/01/07	34885	69	1 M MEL CODE 14		1
799AX	2008/01/11	34885	86	1 M WORKING DI #58565		2
799AX	2008/01/11	34885	86	1 M T/S #58565		2
799AX	2008/01/11	34885	86	1 M TROUBLESHOOT, NEEDS SWITCH #120125-03 FOR BOTH		2
799AX	2008/01/12	34885	89	2 M WORKING DI #58565		2
799AX	2008/01/12	34885	89	2 M SUPERNUMERARY READING LIGHTS		2
799AX	2008/01/12	34885	89	2 M T/S #58565		2
799AX	2008/01/12	34885	89	2 M REMOVED AND REPLACED CTR READING LIGHT ON/OFF SWITCH . OPERATION		2
799AX	2008/01/12	34885	89	2 M NORMAL PER AMM 33-22-01 RT LIGHT STILL INTMT. ITEM REMAINS ON DI		2
799AX	2008/01/13	34885	92	1 M WORKING DI#58565		3
799AX	2008/01/13	34885	92	1 M CLEARED DI#58565 REMOVED AND REPLACED RT READING LIGHT SWITCH REF		3
799AX	2008/01/13	34885	92	1 M B767-200 AMM 25-23-01		3
799AX	2008/01/08	34885	74	1 P MEL SUPERNUMERARY SUPPLEMENTAL HEAT INOP	58584	1
799AX	2008/01/08	34885	74	1 P MEL DEFERRED #58584 DEFERRED PER MEL 21-45-3 MPCW PLAC. INSTALLED MBCB		1
799AX	2008/01/08	34885	74	1 P MEL 01/19/08 CODE 11		1
799AX	2008/01/16	34542	1	3 M WORKING DI#58584 SUPERNUMARY HEAT INOP		2
799AX	2008/01/16	34542	1	3 M T/S DI#58584		2
799AX	2008/01/16	34542	1	3 M FOUND BOTH HEATERS INOP REMOVED & REPLACED RT HEATER IAW MM 21-45-00		2
799AX	2008/01/16	34542	1	3 M CHECKS GOOD LEFT HEATER STILL INOP REMAINS ON DI		2

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 7

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2008/01/11	34885	86	2 M WORKING DI #58584	58584	2
799AX	2008/01/11	34885	86	2 M T/S #58584		2
799AX	2008/01/11	34885	86	2 M WITH A/C IN AIR MODE, VERIFIED NO PWR @ HEATER LT AND RT, VERIFIED		2
799AX	2008/01/11	34885	86	2 M RELAY K2203 PIN 1 HAS NO GRD READS HIGH RESISTANCE W/PACKS RUNNING		2
799AX	2008/01/11	34885	86	2 M VERIFIED RELAY K2203 PIN 2 HAS 28 VDC		2
799AX	2008/01/12	34885	89	3 M WORKING DI #58584		2
799AX	2008/01/12	34885	89	3 M SUPERNUMERARY HEAT INOP		2
799AX	2008/01/12	34885	89	3 M T/S # 58584		2
799AX	2008/01/12	34885	89	3 M ACCESSED P36 PNL. REMOVED AND REINSTALLED RELAY K2203. RIGHT SUPER-		2
799AX	2008/01/12	34885	89	3 M NUMERARY HEAT BECAME OPERATIONAL LEFT HEATER STILL BLOWS COLD. WORK		2
799AX	2008/01/12	34885	89	3 M PERFORMED PER AMM 32-09-02. ITEM REMAINS ON DI		2
799AX	2008/01/13	34885	92	2 M WORKING DI#58584		2
799AX	2008/01/13	34885	92	2 M T/S DI #58584 REMOVED AND REPLACED RELAY K2203. HEATER STILL INOP,		2
799AX	2008/01/13	34885	92	2 M FURTHER T/S SHOWED POWER AT TB192 PIN XA1 IN PN37 PNL REF WBM 21-45-21		2
799AX	2008/01/13	34885	92	2 M SYSTEM REMAINS ON DI.		2
799AX	2008/01/13	34885	93	2 M WORKING DI 58584		2
799AX	2008/01/13	34885	93	2 M T/S #58584		2
799AX	2008/01/13	34885	93	2 M T/S LT SUPERNUMERARY SUPP HEAT HEATER TO RELAY K841 ALT B1 OHMS OK.		2
799AX	2008/01/13	34885	93	2 M W/K841 RELAY REMOVED GET 28 ULTS @ X1 & X2. DMI 58584 REMAINS OPEN		2
799AX	2008/01/18	34542	8	1 M WORKING DI 58584		3
799AX	2008/01/18	34542	8	1 M CLEAR DI 58584 REMOVED & REPLACED LH SUPERNUMARY HEATER IAW B767		3
799AX	2008/01/18	34542	8	1 M MM 21-45-21-4 PLACARD REMOVED.		3
799AX	2008/01/10	34885	82	1 M MEL LT AFT INBD NAV LIGHT INOP.	58633	1
799AX	2008/01/10	34885	82	1 M MEL DEFERRED #58633 DEFERRED LT AFT INBD NAV LIGHT IAW B767		1
799AX	2008/01/10	34885	82	1 M MEL MEL 33-43-1-1B MBCB 20 JAN 08 PLACARD INSTALLED. CODE 11		1
799AX	2008/01/12	34885	89	1 M WORKING DI #58633		3
799AX	2008/01/12	34885	89	1 M CLEAR #58633		3
799AX	2008/01/12	34885	89	1 M REPLACED LEFT AFT NAV LITE ASSY IAW MM 33-43-02-2. OPS CHECKS GOOD		3
799AX	2008/01/12	34885	89	1 M PLACARD REMOVED		3
799AX	2008/01/14	34885	94	2 M MEL RT "PACKOFF" LIGHT WON'T ILLUMINATE	58685	1
799AX	2008/01/14	34885	94	2 M MEL DEFERRED #58685 XFER TO DI58685 PER MEL 21-51-1 CAT C. MBCB 1-24-08		1
799AX	2008/01/14	34885	94	2 M MEL M864 CARD IS BAD IN P50, IAW W/D 21-51-21		1
799AX	2008/01/15	34885	97	1 M WORKING DI 58685 R/H PACK OFF LITE WILL NOT ILLUMINATE WITH		3
799AX	2008/01/15	34885	97	1 M PACK OFF.		3
799AX	2008/01/15	34885	97	1 M CLEAR DI 58685 REMOVED & REPLACED R/H PACK FLOW CONTROL CARD		3
799AX	2008/01/15	34885	97	1 M M864. OPS CHECK PACK GOOD ALL IAW B767 AMM 21-50-00. PLACARD REMOVED.		3
799AX	2008/01/14	34885	94	3 M MEL LT EICAS COMPT DISPLAY MAGENTA	58686	1
799AX	2008/01/14	34885	94	3 M MEL DEFERRED TO DI#58686 XFER TO DI 58686 PER MEL 31-41-1-2 CAT A MBCB		1
799AX	2008/01/14	34885	94	3 M MEL 1 FLT DAY.		1
799AX	2008/01/15	34885	98	1 M WORKING DI 58686 EICAS		3
799AX	2008/01/15	34885	98	1 M CLEAR DI 58686 VERIFIED, TRIED NEW LEFT EICAS COMPUTER NO HELP,		3
799AX	2008/01/15	34885	98	1 M REINSTALLED ORIGINAL COMPUTER. OPENED P8 CARD FILE RE-RACKED ALL VIDIO		3
799AX	2008/01/15	34885	98	1 M CARDS ALL DISPLAYS WORKING CORRECT. WATCHED DISPLAY FOR HALF AN		3
799AX	2008/01/15	34885	98	1 M HOUR NO DEFECTS EICAS TEST GOOD PER AMM CHAPT 31 (PLACARD REMOVED)		3
799AX	2008/01/17	34542	6	2 P MEL FWD CABIN CALL INOP & MARKED INOP (REF MEL 23-41-1-2D-1 COURIER	58751	1

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 8

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2008/01/17	34542	6	2 P MEL SUPERNUMERARY AUDIO ALTERING SYSTEM)	58751	1
799AX	2008/01/17	34542	6	2 P MEL DEF#58751 CODE 14 XFER TO DI 58751 PER MEL 23-41-1-2D-2 MBCB 5-17-08		1
799AX	2008/01/18	34542	7	2 M WORKING DI #58751 (FWD CABIN CALL INOP & MARKER INOP)		2
799AX	2008/01/18	34542	7	2 M T/S #58751 T/S PERFORMED PER FIM 23-42-00 FIG 103 KNOWN GOOD AUDIO		2
799AX	2008/01/18	34542	7	2 M ACCESSORY UNIT M108 INSTALLED AUDIO ACCESSORY UNIT AT FAULT DI STILL		2
799AX	2008/01/18	34542	7	2 M VALID. P/N 285T0001-211		2
799AX	2008/01/18	34542	8	2 M WORKING DI 58751 FWD CABIN CALL INOP MARKED INOP.		3
799AX	2008/01/18	34542	8	2 M CLEAR DI 58751 REMOVED & REPLACED M-51 PILOTS CALL PANEL ASSY		3
799AX	2008/01/18	34542	8	2 M IAW B767 AMM 23-20-01-4. ITEM CLEARED. PLACARD REMOVED.		3
799AX	2008/01/18	34542	7	1 P MEL LAV TEST LIGHT INOP	58756	1
799AX	2008/01/18	34542	7	1 P MEL DEFERRED #58756 PERFORMED LOGIC CONTROL MODULE TEST PER AMM 38-33-00		1
799AX	2008/01/18	34542	7	1 P MEL DET B DOES NOT ILLUM. KNOWN GOOD LCM M965 REPLACED, NO HELP. ALL		1
799AX	2008/01/18	34542	7	1 P MEL FUNCTIONS OF LAV WORKING, EXCEPT THE LIGHT SYSTEM TEST. DEFERRED PER		1
799AX	2008/01/18	34542	7	1 P MEL ABX MEL 38-30-1A. PLACARDED CODE 11		1
799AX	2008/01/20	34542	13	2 M DI#58756 IN WORK		2
799AX	2008/01/20	34542	13	2 M T/S#58756 REPLACED BULB ON SUPERNUMERARY PANEL NO HELP TO REMAIN ON DI		2
799AX	2008/01/20	34542	14	2 M DI#58756 IN WORK		3
799AX	2008/01/20	34542	14	2 M CLR#58756 T/S WASTE TANK SENSORS & LOGIC CONTROL MODULE VERIFIED		3
799AX	2008/01/20	34542	14	2 M MODULE & SENSOR "B" BAD REMOVED & REPLACED WASTE TANK LOGIC CONT		3
799AX	2008/01/20	34542	14	2 M MODULE & "B" LEVEL SENSOR IAW B767 38-33-03-2 & 38-33-01-4 SYSTEM TEST		3
799AX	2008/01/20	34542	14	2 M NORMAL PLACARD REMOVED DI CLEARED		3
799AX	2008/01/19	34542	11	1 M MEL RIGHT EICAS COMPUTER FAIL EICAS MESSAGE IN VIEW	58780	1
799AX	2008/01/19	34542	11	1 M MEL DEFERRED #58780 XFERRED RIGHT EICAS COMPUTER TO D/I 58780 RELEASED		1
799AX	2008/01/19	34542	11	1 M MEL PER MEL 31-41-1-2 CODE 27 MBCB 1 FLT		1
799AX	2008/01/19	34542	12	3 M DI#58780 IN WORK R EICAS COMPUTER		3
799AX	2008/01/19	34542	12	3 M CLR#58780 PERFORMED EICAS BITE PROCEDURE PER B767 FIM 31-41-00 FIG 103		3
799AX	2008/01/19	34542	12	3 M NO INTERFACE FAULTS AND NO INTERNAL FAULTS DISPLAYED ON TEST PAGE		3
799AX	2008/01/19	34542	12	3 M NO EICAS MESSAGES NOTED ON EICAS MESSAGE READOUT PER B767 2-A		3
799AX	2008/01/19	34542	12	3 M PLACARDS REMOVED		3
799AX	2008/01/20	34542	14	1 M MEL DI#58782 IN WORK LEFT AND RIGHT HF RADIOS INOP IN TRANSMET CONTINUOUS	58782	1
799AX	2008/01/20	34542	14	1 M MEL TUNING TONE WITH MIC KEYED AT HIGHER FREQ'S		1
799AX	2008/01/20	34542	14	1 M MEL DEF#58782 CODE 14 DEFERRED LEFT AND RIGHT HF SYSTEMS IAW MEL 23-11-1-		1
799AX	2008/01/20	34542	14	1 M MEL 2A1 MBCB 5/19/08 PLACARD INSTALLED		1
799AX	2008/01/27	34542	32	2 M WORKING DI 58782 LT & RT HF NO XMIT		2
799AX	2008/01/27	34542	32	2 M T/S DI 58782 #1 HF BITE CALLS OUT "COUPLER". R&R'D COUPLER #1, NO		2
799AX	2008/01/27	34542	32	2 M HELP; SWAPPED BACK TO ORIGINAL. COULD NOT GET ANYONE TO ANSWER #1 OR		2
799AX	2008/01/27	34542	32	2 M #2; COULD NOT GET THEM TO WORK WITH 4000 TESTER, STILL ON DI		2
799AX	2008/02/01	34542	47	1 M WORKING DI 58782 #1 AND #2 HF INOP.		3
799AX	2008/02/01	34542	47	1 M CLEAR DI 58782 FOUND HF NOT BONDING STRAP STILL INSTALLED ON		3
799AX	2008/02/01	34542	47	1 M FEEDLINE TO GROUND REMOVED SAME #1 AND #2 HF SYSTEMS CHECK GOOD		3
799AX	2008/02/01	34542	47	1 M IAW B767 MM 23-11-00-5 PLACARD REMOVED.		3
799AX	2008/03/13	33947	99	1 P MEL NO TERRAIN DISPLAY.	59499	1
799AX	2008/03/13	33947	99	1 P MEL DEFERRED 59499 DEFER PER MEL 34-46-1-6A PLACARDED.		1
799AX	2008/03/13	33947	99	1 P MEL CODE 8		1
799AX	2008/03/13	34671	0	2 M WORKING DI 59499. NO TERRAIN DISPLAY.		3

RRLIB/MELLOG_K1 thru K6

07/08/08 15:51:08

MEL DEFECT LOG FOR 799AX

PAGE 9

TAIL#	LOG_DATE	LOG	PG	ITM . DFR DISCREPANCY/ACTION	DEFERRED ITEM NO.	DISEQ
799AX	2008/03/13	34671	0	2 M CLEARED DI 59499. REMOVED AND REPLACED EGPWS COMPUTER TEST GOOD IAW	59499	3
799AX	2008/03/13	34671	0	2 M B767 AMM 34-46-00-5. PLACARD REMOVED.		3
799AX	2008/03/13	34671	0	1 P MEL 36 10 06 01 LEFT ENGINE HI STAGE LIGHT ILLUM. WOULD NOT GO OUT	59506	1
799AX	2008/03/13	34671	0	1 P MEL DURING COOLING PERIOD.		1
799AX	2008/03/13	34671	0	1 P MEL DEFERRED DI 59506. DEFERRED FAN AIR TEMP SYS ON LT ENGINE SECURED		1
799AX	2008/03/13	34671	0	1 P MEL FAN AIR MODULATION VALVE IN INTERMEDIATE POSITION IAW MEL 36-12-2-1.		1
799AX	2008/03/13	34671	0	1 P MEL PLACARD INSTALLED. CODE 11.		1
799AX	2008/03/20	34671	13	1 M WORKING DI 59506 LT ENGINE HI STAGE LIGHT DI		3
799AX	2008/03/20	34671	13	1 M CLEARING DI 59506 CHECKED OVER TEMP 490 SWITCH. CHECKED FATS & FAMU		3
799AX	2008/03/20	34671	13	1 M WITH TEST SET. FAMU MOVED WITHIN LIMITS. REMOVED AND REPLACED FATS		3
799AX	2008/03/20	34671	13	1 M FOR #1 ENGINE IAW B767 AMM 36-11-17 DI CLEARED. PLACARD REMOVED.		3
799AX	2008/06/21	34887	65	2 P MEL 25 11 05 02 F/O SEAT LUMBAR ADJUSTMENT INOP LEFT SIDE OF LUMBAR PAD	60773	1
799AX	2008/06/21	34887	65	2 P MEL ADJUST RIGHT SIDE DOES NOT		1
799AX	2008/06/21	34887	65	2 P MEL DEFERRED DI 60773 PLACED ON DEFERAL PER 25-11-1-2C AUTH 60773 PLACARD		1
799AX	2008/06/21	34887	65	2 P MEL INSTALLED		1
799AX	2008/06/24	34887	70	1 M WORKING DI #60773		3
799AX	2008/06/24	34887	70	1 M CLEAR #60773 REMOVED & REPLACED FO'S SEAT IAW B767 25-11-01. OPS		3
799AX	2008/06/24	34887	70	1 M CHECK GOOD. PLACARD REMOVED		3

* * * E N D O F R E P O R T * * *