

**Attachment 11-K**

**NATIONAL TRANSPORTATION SAFETY BOARD**

**Washington, D. C.**

**E58 Repair Form**

**(1 Page)**

9168738

# REPAIR ITEMS

ORIGINATED BY J Merriam  
 SYSTEM OR AREA 34  
 TYPE OPN. GT CALL CARD NO. \_\_\_\_\_

STATION JFX  
 N NO. 053  
 DATE 11/12/01

ITEM NO.	ATA SYS.	DISCREPANCY	REPAIRS/CORRECTIVE ACTION	MECHANIC			DESIGNEE/INSPECTOR	
				CODE	NAME	MAN HRS	MAN HRS	(if required)
1	34	#2 PITCH TRIM + LAW DAMP WANT ENGAGED	ACCOMP DFS TEST FLAGGED #2 FAC. RESET #2 FAC CBE ACCOMP DFS + LAND TEST SYST CMD NORMAL #2 SYST ENGAGED NORMALLY	(R)	JFX 5189 4683	0.2		

To: F. McGILL (F) 202-314-6349

Our tech guys ran this down pretty well. If you would like to discuss with them, I can set up a phone con.

Dan

DEC 06 '2001 13:07 9182923168 AMERICAN AIRLINES #178 P. 11/001