Attachment 6 Major Repairs and Alterations

US AIRWAYS Major Alterations List Aircraft Number : 106

ACFT	Equipment	Serial Number	Me Serial Number	Alteration Document	Description	Date Accomplished
106	A320-200	1044		5726-01008	A319/A320/A321 - MOD OF MLG RIB 5 BUSHINGS	25-SEP-2008
106	2123M55P01	LMDN2747	2747	7321-01073	ECU SOFTWARE VERSION 5.B.Q.	25-APR-2008
106	2123M55P01	LMDN2880	2880	7321-01073	ECU SOFTWARE VERSION 5.B.Q.	25-APR-2008
106	A320-200	1044		3243-01006	LANDING GEAR - PARKING - ULTIMATE BRAKING SYSTEM	24-APR-2008

an and a second se

na secondario de la constante d Indexe de la constante de la const

MAJOR REPAIRS

US AIRWAYS Major Repair List

	Re	gistation	n Numi	ber: N	106US	Serial Nu	1 mber: 1044	Manufacture:	AIRBUS A	Aire	raft Mode	I: A320-214	Ma	ajor Rep	pair Count 7	
SDA ID #	SDR #	SDA Date	ATA	STA	Check .	Defect Size	Defect Type	Part Name				Water Line From To	But Fron	t Line 1 To	LogPage	MON Status
23746	Not Reportable	4/9/2005	5 53-10	PIT	\$1 - C2	NUMERO US	DRILL MARK	FRAME	28 F	FWD	CARGO CO	٧P	5	24	JA-131-53500-001	
Repair	Description RI	EPLACEM	ENT PA	rt Ma	NUFACTUR	ED & REPLA	ACED	Repa	ir Docume	nt N	OT LISTED (• • • • • • •			
SDA ID #	SDR #	SDA Date	ATA	STA	Check	Defect Size	Defect Type	Part Name	-		-	Water Line From To	But From	tLine 1 To	LogPage	MON Status
23745	0478	4/10/200	5 53-10	PIT	SI	1/2"	CORRODED	FLOORBEAM	20		9 R				JA-220-53300-001	
Repair	Description RI	EMOVED	CORRO	SION, B	STALLED			Repa	ir Docume						• • • • • • • • • • • • • • • • • • • •	
SDA ID #	SDR #	SDA Date	ATA	STA	Check	Defect Size	Defect Type	Part Name	-		_	Water Line From To		t Line 1 TO	LogPage	MON Status
3692		4/16/200			\$2				25, AND WEB, PI) BET LATE	WEEN STRI	S BETWEEN FR NGERS 39 AND	41 R/H S	IDE	JA-131-53500	
Repair	Description	• • • • • • •		• • • •			*	Repa	ir Docume						****	*
SDA ID #	SDR #	SDA Date	ATA	STA	Check	Defect Size	Defect Type	Part Name				Water Line From To	But Fron	t Line 1 To	LogPage	MON Status
9096		5/22/200	2 53-30	BOS	RON				TWO DE CONE A		AME 85	ALLOWABLE				
Repair	Description	* *						Repa	ir Docume	nt SI		FIG 213, T/R PE			3-00-11	
SDA ID #	SDR #	SDA Date	ATA	STA	Check	Defect Size	Defect Type	Part Name	-		-	Water Line From To		t Line 1 To	LogPage	MON Status
9095	157	5/2/2002	2 53-30	TPA	CII				150 CR	ACK	FRAME 30	STRINGER 8L			OM727252/27253	
Repair	Description	• • • • • • •	• • • • • •		Repair Document SRM 53-21-11, SRM 53-00-11											
SDA ID#	SDR #		ATA	STA	Check	Defect Size	Defect Type	Part Name	-		-	Water Line From To	But Fron	t Line 1 To	LogPage	MON Status
8778		1/11/200	8 53-30	PIT	C11				STATIO	N FR	23 & FR24 S	KS 2.75" X 2.5" TRINGER 42 &	43r		JA-100-0051C-3	
Repair	Description			••••	• • • • • • •				ir Docume					• • • • • •		
							· · · · · · · · · · · · · · · · · · ·									· · · · · · · · · · · · · · · · · · ·

, en .	42 4			:										
	SDA ID #	SDR #	SDA AI Date	ta sta	Check	Defect Size	Defect Type	Part Name	Body Station From To	Stringer From To	Water Line From To	Butt Line From To	LogPage	MON Status
	2137	0522	4/5/2005 53	-40 PIT	S.				CORROSION FRAME 64 -	12" X 2" L/H FRAME C-70	1/B AFT FLOOR	BEAM Y765	JA-26053500001	
	Repair I	escription						Repa	ir Document ^S	RM 53-41-14			• • • • • • • • • • • • • • • • • • •	
		-	· .											
									·					
			-									·		
										·				
	•			-										
х 	•													
				,										
	х ¹						x							
	1.4													
. *														
. 1	,													
	i nursday, Ja	nuary 22, 2009											Page	2 of 2