



I hereby authorize the following repair work to be done on the aircraft and/or engine and hereby give you and your employees permission to operate and fly the aircraft herein described for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on this aircraft to secure the amount of repairs thereto. You will not be held responsible for loss or damage to the aircraft or articles left in case of fire. I will not be held responsible for any loss or damage to the aircraft or articles left in case of fire. I will not be held responsible for any loss or damage to the aircraft or articles left in case of fire. I will not be held responsible for any loss or damage to the aircraft or articles left in case of fire.

X

CUSTOMER #
TERMS
CASH ☐
CHARGE ☐
OK'D BY

NAME **Erik Nelson**

DATE **03/02/2009**

QUAN. PART NUMBER AND DESCRIPTION UNIT PRICE TOTAL AMOUNT

1	CH48109-1 Oil filter		
12	RHB32E Spark Plugs		
1	452-0130 ELT Battery (expires Dec 2010)		
3	649959 Intake Gasket		
3	652458 Exhaust Gasket		
2	655528 Cover Gasket		
8	534610 Seal-Push Rod tube		
1	649965 Gasket-oil filler		
1	M59970-117 O-Ring-Oil Filler		
2	641066 Seal-Cyl. Base		
4	652984 Rocker Shaft		
1	P13-7627 Air Filter		
4	A1638-5 Washer-Spinner		

ADDRESS CITY
MAKE & MODEL **4-36** SERIAL NO. **AIRCRAFT- E-3052 - 1237.1**
REGISTRATION NO. **N464TJ** ENGINE **R OR FWD.**
RECEIVED A.M. **L OR AFT**
P.M. **PHONE WHEN READY** WRITTEN BY
P.M. YES ☐ #
OPER. NO. **SERVICE DESCRIPTION**

QOR NO.	DESCRIPTION	SERVICE
	CHANGE OIL	
	CHANGE OIL FILTER CART.	
	INSPECTION 30 HOUR	
X	ANNUAL 100 HOUR PERIODIC INSP.	
	INCOMING INSPECTION	
	PRELIMINARY INSPECTION	
	HIDDEN DAMAGE INSPECTION	
	PROGRESSIVE INSPECTION	
	FINAL INSPECTION	

1. Cylinder compressions: 1-57/80 2-30/80 3-57/80 4-45/80 5-50/80 6-68/80
2. Oil and filter change. Service w/Aeroshell 15W50 & CH48109-1.
3. Replace all 12 spark plugs due to wear beyond limits. (RHB32E)
4. Clean fuel injector nozzles (next due at HOBBS 1537 or Feb 2012)
5. Replace induction air filter (P13-7627) (next due at HOBBS 1737)
6. Replace ELT battery (452-0130) Expires Dec 2010
7. Cylinder #2 and #4 low compression (30/80 and 45/80). Staked exhaust valve and tested again - no change. Remove both cylinders for repair by Kenmore Air - engine shop. Reinstall both cylinders following replacement of exhaust valves, guides and re-bushing of rocker arms and shafts.
8. Note: Metal found in oil filter (non-ferrous and brass/copper). Like cause: worn bushings in rocker arms and worn rocker shafts. Parts were replaced during cylinder work. No additional work authorized.
9. Repair aft cabin heat control by gaining access under co-pilot rudder pedals and replacing cable hardware that was missing. Reinstall floor panel under co-pilot rudder pedals.
10. Comply w/AD84-26-02 by replacement of paper induction air filter

6		
7		

ORDER NO. DATE / /

S.G.NED (SIGNATURE OF AUTHORIZED REPRESENTATIVE)

(CERTIFICATE NO.) (ADDRESS OF STATION)

1. ACCEPTANCE OF REPAIRED PLANE: At time of delivery of said aircraft, the undersigned has read and examined all notations in the "Remarks and Recommendations Section" and accepts the same as modifications of the repair and service work originally ordered as set forth herein above, hereby ratifying the original repair service except as modified.

OWNER'S SIGNATURE

"The limited warranties applying to the parts listed herein are those which may be offered by the manufacturer. We hereby expressly disclaim all warranties, either expressed or implied, including any implied warranties of the merchantability or fitness for a particular purpose and neither assume, nor authorize any other person to assume for the company any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the company any consequential damages, to property, damages for loss of use, loss of time, loss of profits or income, or any other incidental damages."

GAS, OIL & SOLVENT		TOTAL SERVICE
QTY.	\$ AMOUNT	TOTAL PARTS
12 GALLONS GAS		OUTSIDE REPAIRS
QUARTS OIL 15W50		GAS, OIL, SOLVENT, WASH, OIL
SOLVENT		SUB-TOTAL
		TAX
		TOTAL

If any of ABOVE NOT subject to state tax, enter on bottom line (above).

to approximately three (3) years of use. Repairs may be made on any aircraft. Applicable supply items are: cotter-pins, aero-spray, tape, solvers, solder, welding material, battery cleaner, window sealer, bearing grease, parts cleaning solvent, etc.

ORIGINAL

□ □ □ □ □



X

CUST ORD #	
TERMS	
CASH ☐	
☐ CHARGE	
OK'D	

ORDER NO. _____	DATE _____
SIGNED _____ (SIGNATURE OF AUTHORIZED REPRESENTATIVE)	
IDENTITY CARD NO. _____	ADDRESS OF STATION _____
REMARKS AND RECOMMENDATIONS FOR REPAIRS	
1. ACCEPTANCE OF REPAIRED PLANE: At time of delivery of said aircraft, the undersigned has read and examined all notations in the "Remarks and Recommendations" Section and accepts the same as modifications of the repair and service work originally ordered as set forth herein above, hereby ratifying the original repair service except as modified	
OWNER'S SIGNATURE _____	

ADDRESS		CITY	
MAKE & MODEL <i>Beech A36</i>		SERIAL NO.	TYPE HOURS <i>1237.1</i>
REGISTRATION NO. <i>N464TJ</i>		AIRCRAFT —	
		ENGINE <i>IO-550-B</i>	
		R OR FWD. <i>SN 682283</i> —	
RECEIVED	A.M.		
	P.M.	L OR AFT	—
PROMISED	A.M.	PHONE WHEN READY	WRITTEN BY
	P.M.	YES ☐ #	
OPER. NO.	SERVICE DESCRIPTION		

DATE	DESCRIPTION	SERVICE
	CHANGE OIL	
	CHANGE OIL FILTER CART.	
	INSPECTION 50 HOUR	
	ANNUAL/100 HOUR PERIODIC INSP.	
	INCOMING INSPECTION	
	PRELIMINARY INSPECTION	
	HIDDEN DAMAGE INSPECTION	
	PROGRESSIVE INSPECTION	
	FINAL INSPECTION	

McCauley Governor C290D3-K/T23 s/n 960351 Overhauled (AC WO# 28904)
McCauley Propeller D3A32C409-C s/n 961634 Overhauled with new Blades and De-ice boots (AC WO# 28884)
TCM Engine IO-550-B (29) s/n 882283 Teardown Inspection with Overhauled Starter Shaftgear, Repairs to #5 cylinder. New Hydraulic lifters (Premier WO# 11004).

5		
6		
7		

*The limited warranties applying to the parts listed herein are those which may be offered by the manufacturer. We hereby expressly disclaim all warranties, either expressed or implied, including any implied warranties of the merchantability or fitness for a particular purpose and neither assumes, nor authorize any other person to assume for the company, any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the company any consequential damages, to property, damages for loss of use, loss of time, loss of profits or income, or any other incidental damages.

GAS, OIL & SOLVENT				COMMENT	OUTSIDE REPAIRS
QTY	GALLONS GAS	OCTANE	\$ AMOUNT		GAS OIL SOLVENT ENVRO. CHG
12	QUARTS OIL 45/100	WGT.	DETERGENT NON-DETERGENT		SUB-TOTAL
SOLVENT				ENVIRONMENTAL CHARGES	9.5 TAX
If any of ABOVE NOT subject to state tax, enter on bottom line (above).				TOTAL	TOTAL

A Goulet design equivalent to approximately three percent of the labor charges may be included for supplies used on your aircraft. Applicable supply items are: center pins, aero-spray, rags, towels, solder, welding material, billy cleaner, window squeegee, bearing grease, parts cleaning solvent, etc....

ORIGINAL