PACIFIC GAS AND ELECTRIC COMPANY San Bruno Gas Transmission Line Incident Data Response

| PG&E Data Request No.: | NTSB_070-001 | | |
|------------------------|--|-------------------|------------------------------|
| PG&E File Name: | San Bruno GT Line Incident_DR_NTSB_070-001 | | |
| Request Date: | April 25, 2011 | Requesting Party: | NTSB |
| Date Sent: | April 26, 2011 | Requestor: | Operations (Chhatre/Hall) |

QUESTION 1

One of the pipe pieces from 881 Glenview Dr had a painted mark on the inside of the pipe (see the attached photograph). Is PG&E familiar with this mark and its meaning?

ANSWER 1

PG&E is not familiar with this painted mark. Original documentation identified painted joint marks and internal camera examination has confirmed internal joint marks in the 30" pipe. This mark is not similar to any of these other known marks.