

From: McAtee Nancy

Sent: Tuesday, August 13, 2013 2:22 PM

To: Yeager Leah

Cc: Budinski Michael

Subject: CEN13FA085 report

Leah,

The following components were submitted to the Materials Laboratory for examination.

1. Directional gyro
2. Pilot's attitude indicator
3. Co-pilot's indicator gyro
4. Turn and bank gyro
5. Annunciator panel

The indicators and gyros were submitted to determine if there was any rotational scoring/smearing present on the gyro and/or gyro case. All four gyros were examined and no scoring was found.

The annunciator panel was submitted to determine if any of the annunciator lights had hot coil filament stretching present. All the filaments for all the bulbs were intact and unstretched.

Let me know if you have any questions or need anything else done on these components.

Nancy McAtee