

Yeager Leah

From: McAtee Nancy
Sent: Monday, March 02, 2015 10:23 AM
To: Yeager Leah
Cc: Budinski Michael
Subject: CEN15FA003 Email report (Annunciator Panel)

Leah,

The annunciator panel from this accident aircraft was examined for the presence of any stretched light bulb filaments. Each annunciator light was x-rayed to determine the status of the two bulb inside. While there was some evidence of age-related sagging, no stretched filaments were found in any of the annunciator lights.

If you have any questions or need anything else, please let me know

Nancy McAtee
Chemist
RE-30