

To Mike Foker

I checked N-394110 main fuel tanks, Both tanks were empty, Checked all fuel lines to Fuel Filter, Lines were not Restricted, Removed Fuel Filter, Found a small amount of sanding dust in Filter, Removed Boost Pump, Hooked to a battery and Boost Pump, worked well. Checked all lines to Fuel Flow Divider on top of Eng, All lines were not Restricted, Removed flow divider and open it up to check diaphragm, Found small amount of sanding dust in flow divider, overall it looks pretty free of any fuel flow stoppage, If you have any ques from call me.

Thanks mike



Bob Korn

