



**Chart 4.5**  
**Seats Not Recovered**

 Seats not recovered (35)

Note:  
Seating positions shown assigned seats. Passengers may have  
changed seats during a low fuel go-around procedure.  
The 14 flight attendants were performing their duties throughout  
the flight. All are recovered.

Medical/Forensic 19 - Exhibit No. 19B - Chart 4.5 Seats Not Recovered