



The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
Aircraft Owner Information
Summary
CEN18LA157
Marathon Texas
May 2 2018

The airplane owner reported to the NTSB that the airplane had last flown about 6 months prior to the accident flight and that the airplane had about 3 hours of flight time since its most recent conditional airworthiness inspection which was performed on May 23, 2017.

Alexander Lemishko


Senior Air Safety Investigator
NTSB Central Region Aviation