



Metallurgical Group- Picture 17 Magnetic Particle Inspection (MPI) testing is performed by a qualified technician on (piece b) after grit blasting of the external surfaces at the NTSB Ashburn, Virginia facility.