

Figure 15. Partially recrystallized microstructure on the section through the sample from CW1004. (Keller's etchant, 200X)

Metallurgist's Factual Report No. 97-85