# METROLINK GENERAL TRACK BULLETIN

NO. 7780

TO: M102 24

February 24, 2015 AT: EAST VENTURA

A total of 14 items are included in this bulletin, consisting of:

3 Form A/B Bulletin Restriction(s)

11 Form C/TCM Bulletin(s)

OK 0303

Dispatcher: CEH

General Track Bulletin # 7780 addressed to M102 24 contains restrictions, if any are in effect, for the following locations:

Subdivision	From Milepost .	200	To Milepost	97#3
RIVER	0		3.67	
RIVER	140.05		144.4	
RIVER	480.9		485.2	•
VALLEY	3.67	•	76.63	
VENTURA '	426.4	¥ ¥	462.39	
MONTALVO	402.81		404.47	
MONTALVO	403.14		403.43	
	1		l , , ;	

<sup>\*\*</sup> Before your train operates on territory not listed, you must contact train dispatcher to determine if any additional restrictions are needed per timetable special instructions.

Timetable in Effect: 9

General Order in Effect: 9

5 E

ALBIO

<sup>\*\*</sup> If address is not shown correctly on General Track Bulletin address line, contact the train dispatcher and correct before operating on main track.



Void	Item No.	Bulletin Number	Form	Restu	rictions	s for RIV	ER Subdivi	siön (MP 0	TO MP 3.0	57)
7	1	157	A	MP	to	MP	HER	FRT	PSGR	Track
				3.4		3.5	d. <u>2,0 1</u> 2	10	15	ALL TRACKS
				CROS	Short Flag at MP 2.4 RESTRICTION IS FOR MOVEMENT AT CP TAYLOR THROUGH EAST CROSSOVER ONLY YELLOW FLAGS ARE DISPLAYED ON VALLEY SUBDIVISION AT MP 5.5					
Void	Item No.	Bulletin Number	Form						40.05 TO N	
	THER	E ARE NO	BULLETINS	S ASSI	GNED I	FOR RIVE	R Subdivisio	n (MP 140.0	5 TO MP 14	4.4)
Void	Item No.	Bulletin Number	Form	Restr	rictions	s for RIV	ER Subdivi	sion (MP 4	80.9 TO M	P 485.2)
_	1	372	С	MP	to	MP	:			Track
				SERV 6.32.2	IAIN ST ICE DI I(A) IS	UE TO CO	NSTRUCTIO	ON OF MAI	ATE IS OUT N ST. BRIDO UCTED BY	GE. RULE
Void	Item No.	Bulletin Number	Form	Restr	rictions	s for VAL	LEY Subd	ivision (MI	? 3.67 TO M	IP 76.63)
7	1	259	В	MP	to	MP				Track
				11.0 ON V	ENTU	13.6 RA SUBD	UNTIL:	FEBRUAR 97 (VELOZ	Y 24, 2015 06 Y 24, 2015 15 Z SALVADO LOW/RED F	500

461.0 AND RED FLAG AT MP462.4 FOR EASTWARD MOVEMENT



Void	Item No.	Bulletin Number		Restrictions for	Restrictions for VALLEY Subdivision (MP 3.67 TO MP 76.63)					
1	2	261	В	MP to M	IP Track					
				17.6 18	FROM FEBRUARY 24, 2015 0630 UNTIL FEBRUARY 24, 2015 1500 EIC ME103 (EWING R CHARLIE)					
Void	Item No.	Bulletin Number	Form	Restrictions for	VENTURA Subdivision (MP 426.4 TO MP 462.39)					
	THER	E ARE NO	BULLETIN	NS ASSIGNED FOR	VENTURA Subdivision (MP 426.4 TO MP 462.39)					
Void	Item No.	Bulletin Number	Form	Restrictions for	MONTALVO Subdivision (MP 402.81 TO MP 404.47)					
	THER	E ARE NO	BULLETIN	NS ASSIGNED FOR	MONTALVO Subdivision (MP 402.81 TO MP 404.47)					
Void	Item No.	Bulletin Number	Form	Restrictions for	MONTALVO Subdivision (MP 403.14 TO MP 403.43)					
	THER	E ARE NO	BULLETIN	NS ASSIGNED FOR	MONTALVO Subdivision (MP 403.14 TO MP 403.43)					
Void	Item No.	Bulletin Number	Form	Restrictions for	·RIVER					
1	1	348	С	SUBDIVISION, I	MEDIATELY, METROLINK TIMETABLE NO. 9, RIVER PAGE RV-4, THIRD ITEM, SAN GABRIEL TRACK, THE PASADENA JCT. MILEPOST IS REVISED / 1.08					
				r						
Void	Item No.	Bulletin Number	Form	Restrictions for	VALLEY					
I	1	388	С	FROM SIDING T ASSOCIATED P	1 FEBRUARY 15, 2015 THE WESTBOUND SIGNAL TO MAIN TRACK AT MP 12.67 IS RETIRED. OWER SWITCH AND TURNOUT ARE REMOVED FROM TRACK IS STRAIGHT-LINED.					



Void	Item	Bulletin	Form	n	
-	No.	Number		Restrictions for VENTURA	

THERE ARE NO GENERAL FORM C BULLETINS ASSIGNED FOR VENTURA SUBDIVISION.

Void	Item	Bulletin	Form	
	No.	Number		Restrictions for MONTALVO

THERE ARE NO GENERAL FORM C BULLETINS ASSIGNED FOR MONTALVO SUBDIVISION.

Void	Item No.	Bulletin Number	Form	Restrictions for ALL Subdivisions
_[	1	353	С	METROLINK TIMETABLE NO.9 OLIVE SUBDIVISION PAGE OL-1 IS REVISED AS FOLLOWS:
	2	354	с	MILEPOST FOR CP MAPLE IS CHANGED FROM 5.5 TO 5.42 METROLINK TIMETABLE NO.9 SYSTEM SPECIAL INSTRUCTIONS PAGE AS-22 RULE 9.12 STOP INDICATIONS
,				THE RULE IS DELETED IN ITS ENTIRETY
L	3	355	С	GENERAL ORDER No. 09, SECTION M "INSTRUCTIONS RELATING TO POSITIVE TRAIN CONTROL" IS NOT IN EFFECT UNTIL FURTHER NOTICE.
1	4	356	С	METROLINK TIMETABLE NO. 9 DATED 0001 JUNE 2 2013 IS IN EFFECT
				METROLINK GENERAL ORDER NO. 9
				DATED 0001 NOVEMBER 3 2014 IS IN EFFECT
				METROLINK GENERAL NOTICE 11-14 DATED 0001 NOVEMBER 3 2014 IS IN EFFECT
04				METROLINK MAINTENANCE OF WAY GENERAL ORDER NO. 21 DATED 0001 SEPTEMBER 22 2014 IS IN EFFECT
L	5	361	С	GENERAL ORDER No. 9, SECTION F, ITEM 8 IS DELETED IN ITS ENTIRETY
J	6	366	С	METROLINK TIMETABLE NO.9 AND SPECIAL INSTRUCTIONS, ALL SUBDIVISIONS: ALL REFERENCES TO THE TERM TRACK WARRANT ARE REPLACED WITH THE TERM GENERAL TRACK BULLETIN (GTB) EXCEPT WHEN TRACK

Void	Item	Bulletin	Form	
	No.	Number		Restrictions for ALL Subdivisions
				WARRANT GRANTS AUTHORITY AS PER GCOR 14.1 TWC LIMITS
_(	7	371	С	FOR TRAINS EQUIPPED AND OPERATING WITH POSITIVE TRAIN CONTROL CUT IN:
				BEFORE ATTEMPTING A DEPARTURE TEST OR INITIALIZATION, ENSURE BRAKE PIPE PRESSURE IS 110 LBS OR GREATER.
1	8	395	С	EFFECTIVE 0001 FEBRUARY 15, 2015 METROLINK TIMETABLE NO. 9 IS REVISED AS FOLLOWS:
				METROLINK TIMETABLE PAGE VL-4 OTHER MAXIMUM SPEEDS SUBSECTION TITLED CONTROLLED SIDING CP OLIVE - CP BRIGHTON IS CHANGED TO READ:
				CP OLIVE MP 11.1: THROUGH TURNOUT
				METROLINK TIMETABLE NO. 9, PAGE VL-12, RULE 6.28 MOVEMENT ON OTHER THAN MAIN TRACK THE FOLLOWING IS ADDED:
				RULE 6.28 IS IN EFFECT ON THE BRIGHTON SPUR
				METROLINK TIMETABLE PAGE VL-14, RULE 15,1 TRACK BULLETINS IS CHANGED TO READ:
				METROLINK CREWS MAY USE THE GENERAL TRACK BULLETIN (GTB) RECEIVED FOR SCHEDULED TRAINS FOR DEADHEAD MOVEMENT BETWEEN CP TAYLOR AND CP BURBANK JCT. IF DEADHEAD EQUIPMENT BEING HANDLED IS DIFFERENT FROM THAT ADDRESSED ON GTB, CHANGE OF ADDRESS IS NOT REQUIRED.

VERBALLY ISSUED FORM A RESTRICTIONS											
To:At:Date:											
RESTRN NUMBER	SUBDIV		LIMITS MP TO MP	SPEED MPH PSGR FRGT		TRACK(S)	FLA AT	AGS MP			
COMMENTS:OKDspr											
To:	At:Date:										
RESTRN NUMBER	SU	BDIV	LIMITS MP TO MP	SPEEI PSGR	MPH FRGT	TRACK(S)	AT FLA	MP			
COMMENTS	S:	S				OK	Dspr	-			
		VERB	ALLY ISSUED	FORM	C RESTR	ICTIONS					
To:	A	t:	Date:								
RESTRN NUMBER	SUBDIV			RESTRIC	TION TEXT						
				97.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
COMMENTS	S:				•	OK	Dspr	-			
To:	A	t:	Date:				ii 1.000 i				
RESTRN NUMBER	SUBDIV			RESTRIC	TION TEXT						
					9		3. 1.2.15.70.				
COMMENT	S:		-			OK	_Dspr	-			
		VERB	ALLY ISSUEI	D FORM	X RESTR	ICTIONS					
Eng:	At:	154 (241)	Copied by	/:		Date:		1			
620											
OKDS	PR										
Eng:	At:		Copied by	y:		Date:					
Observe Ru	le 6.32.2(A)	At									
OKDS	PR					57 TO 1 TO 1	2222				
WASTER CO.			Copied by	y:		Date:	**************************************				
	20. (2)										
OKDS	PR	200200000000	1870 - 184	-200							

## TUESDAY, FEBRUARY 24, 2015

#### G-COR

# 1.41 Engines Coupled to Occupied Passenger Cars

Engines coupled to equipment that includes occupied passenger cars must not be left without an authorized employee in charge.

## SAFETY TIP OF THE DAY - (AMT-5)

**5603** Before starting/energizing 480 volt H.E.P. or power supply on locomotives and/or cars, employees must be made aware that power will be energized and must stand clear of all electrical cables.



### Bags and Personal Belonging

In stations and on board trains, watch your bags and personal belongings at all times. Do not accept packages from strangers. Do not allow anyone to leave unattended items with you



#### 24 Travel Options

Remember, passengers chose to travel by train. Make it a great experience for them.