102

870/645 E

METROLINK GENERAL TRACK BULLETIN

NO. 7780

February 24, 2015

TO: M102 24

AT: EAST VENTURA

A total of 14 items are included in this bulletin, consisting of:

3 Form A/B Bulletin Restriction(s)

11 Form C /TCM Bulletin(s)

OK 0303

Dispatcher: CEH

General Track Bulletin # 7780 addressed to M102 24 contains restrictions, if any are in effect, for the following locations:

Subdivision	From Milepost	To Milepost
RIVER /	0	3.67
RIVER -	140.05	144.4
RIVER -	480.9	485.2
VALLEY 1	3.67	76.63
VENTURA /	426.4	462.39
MONTALVO,	402.81	404.47
MONTALVO	403.14	403.43
· '		į

^{**} Before your train operates on territory not listed, you must contact train dispatcher to determine if any additional restrictions are needed per timetable special instructions.

Timetable in Effect: 9

General Order in Effect: 9

SBA- 1860

^{**} If address is not shown correctly on General Track Bulletin address line, contact the train dispatcher and correct before operating on main track.

Void	Item No.	Bulletin Number	Form	Restr	riction	s for RIV	ER Subdivi	sion (MP (TO MP 3.6	57)	
_	1	157	A	MP	to	MP	HER	FRT	PSGR	Track	
				3.4		3.5		10	(15)	ALL TRACKS	
					Short Flag at MP 2.4						
		Porta	(*	RESTRICTION IS FOR MOVEMENT AT CP TAYLOR THROUGH EAST CROSSOVER ONLY							
	•	(20)		YELI 5.5	YELLOW FLAGS ARE DISPLAYED ON VALLEY SUBDIVISION AT MP						

Void Item Bulletin Form No. Number Restrictions for RIVER Subdivision (MP 140.05 TO MP 144.4)

THERE ARE NO BULLETINS ASSIGNED FOR RIVER Subdivision (MP 140.05 TO MP 144.4)

Void	Item No.	Bulletin Number	Form	Restrictions for RIVER Subdivision (MP 480	0.9 TO MP 485.2)
_	1	372	С	MP to MP	Track
				481.68 481.68 AT MAIN ST., MP 481.68 THE ALBION ST. GAT SERVICE DUE TO CONSTRUCTION OF MAIN 6.32.2(A) IS NOT REQUIRED UNLESS INSTRUCTRAIN DISPATCHER	ST. BRIDGE. RULE

Void	Item No.	Bulletin Number	Form	Restr	iction	s for VAL	LEY Subdivision (MP 3.67 TO MP 76.63)
_	1	259	(B)	MP	to	MP	Track
	7	259					ALL TRACKS FROM FEBRUARY 24, 2015 0600 UNTIL FEBRUARY 24, 2015 1500 EIC ME97 (VELOZ SALVADOR) IVISION SHORT YELLOW/RED FLAG AT MP S AT MP462.4 FOR EASTWARD MOVEMENT HIG 2. 4 MIC 107 SCAX 645E

General Track Bulletin No. 7780

Void	Item No.	Bulletin Number	Form	Restrictions for VALLEY Subdivision (MP 3.67 TO MP 76.63)						
_	2	261	В	MP to MP Track 17.6 18.4 FROM FEBRUARY 24, 2015 0630 UNTIL FEBRUARY 24, 2015 1500 EIC ME103 (EWING R CHARLIE)						
Void	Item No.	Bulletin Number	Form	Restrictions for VENTURA Subdivision (MP 426.4 TO MP 462.39)						
THERE ARE NO BULLETINS ASSIGNED FOR VENTURA Subdivision (MP 426.4 TO MP 462.39)										
Void	Item No.	Bulletin Number	Form	Restrictions for MONTALVO Subdivision (MP 402.81 TO MP 404.47)						
	THER	E ARE NO	BULLETIN	S ASSIGNED FOR MONTALVO Subdivision (MP 402.81 TO MP 404.47)						
Void	Item No.	Bulletin Number	Form	Restrictions for MONTALVO Subdivision (MP 403.14 TO MP 403.43)						
	THER	E ARE NO	BULLETIN	S ASSIGNED FOR MONTALVO Subdivision (MP 403.14 TO MP 403.43)						
Void	Item No.	Bulletin Number	Form	Restrictions for RIVER						
	1	348	c /	EFFECTIVE IMMEDIATELY, METROLINK TIMETABLE NO. 9, RIVER SUBDIVISION, PAGE RV-4, THIRD ITEM, SAN GABRIEL CONNECTING TRACK, THE PASADENA JCT. MILEPOST IS REVISED TO READ 482.3 / 1.08						
Void	Item No.	Bulletin Number	Form	Restrictions for VALLEY						
	1	388	c	EFFECTIVE 0001 FEBRUARY 15, 2015 THE WESTBOUND SIGNAL FROM SIDING TO MAIN TRACK AT MP 12.67 IS RETIRED. ASSOCIATED POWER SWITCH AND TURNOUT ARE REMOVED FROM SERVICE AND TRACK IS STRAIGHT-LINED.						

Void	Item	Bulletin	Form	TO A 1-41 S TONIDLID A
	No.	Number		Restrictions for VENTURA

THERE ARE NO GENERAL FORM C BULLETINS ASSIGNED FOR VENTURA SUBDIVISION.

Void	Item	Bulletin	Form	TO A LABOR OF THE PARTY OF THE
	No.	Number		Restrictions for MONTALVO

THERE ARE NO GENERAL FORM C BULLETINS ASSIGNED FOR MONTALVO SUBDIVISION.

Void	Item No.	Bulletin Number	Form	Restrictions for ALL Subdivisions
_	1	353	С	METROLINK TIMETABLE NO.9 OLIVE SUBDIVISION PAGE OL-1 IS REVISED AS FOLLOWS:
				MILEPOST FOR CP MAPLE IS CHANGED FROM 5.5 TO 5.42
	2	354	С	METROLINK TIMETABLE NO.9 SYSTEM SPECIAL INSTRUCTIONS PAGE AS-22 RULE 9.12 STOP INDICATIONS
				THE RULE IS DELETED IN ITS ENTIRETY
_	3	355	С	GENERAL ORDER No. 09, SECTION M "INSTRUCTIONS RELATING TO POSITIVE TRAIN CONTROL" IS NOT IN EFFECT UNTIL FURTHER NOTICE.
_	4	356	С	METROLINK TIMETABLE NO. 9 DATED 0001 JUNE 2 2013 IS IN EFFECT
				METROLINK GENERAL ORDER NO. 9 DATED 0001 NOVEMBER 3 2014 IS IN EFFECT
				METROLINK GENERAL NOTICE 11-14 DATED 0001 NOVEMBER 3 2014 IS IN EFFECT
				METROLINK MAINTENANCE OF WAY GENERAL ORDER NO. 21 DATED 0001 SEPTEMBER 22 2014 IS IN EFFECT
-	5	361	С	GENERAL ORDER No. 9, SECTION F, ITEM 8 IS DELETED IN ITS ENTIRETY
_	6	366	С	METROLINK TIMETABLE NO.9 AND SPECIAL INSTRUCTIONS, ALL SUBDIVISIONS: ALL REFERENCES TO THE TERM TRACK WARRANT ARE REPLACED WITH THE TERM GENERAL TRACK BULLETIN (GTB) EXCEPT WHEN TRACK

Void	Item	Bulletin	Form	
	No.	Number		Restrictions for ALL Subdivisions
				WARRANT GRANTS AUTHORITY AS PER GCOR 14.1 TWC LIMITS
_	7	371	С	FOR TRAINS EQUIPPED AND OPERATING WITH POSITIVE TRAIN CONTROL CUT IN:
				BEFORE ATTEMPTING A DEPARTURE TEST OR INITIALIZATION, ENSURE BRAKE PIPE PRESSURE IS 110 LBS OR GREATER.
	8	395	С	EFFECTIVE 0001 FEBRUARY 15, 2015 METROLINK TIMETABLE NO. 9 IS REVISED AS FOLLOWS:
				METROLINK TIMETABLE PAGE VL-4 OTHER MAXIMUM SPEEDS SUBSECTION TITLED CONTROLLED SIDING CP OLIVE - CP BRIGHTON IS CHANGED TO READ:
				CP OLIVE MP 11.1: THROUGH TURNOUT
				METROLINK TIMETABLE NO. 9, PAGE VL-12, RULE 6.28 MOVEMENT ON OTHER THAN MAIN TRACK THE FOLLOWING IS ADDED:
				RULE 6.28 IS IN EFFECT ON THE BRIGHTON SPUR
				METROLINK TIMETABLE PAGE VL-14, RULE 15.1 TRACK BULLETINS IS CHANGED TO READ:
				METROLINK CREWS MAY USE THE GENERAL TRACK BULLETIN (GTB) RECEIVED FOR SCHEDULED TRAINS FOR DEADHEAD MOVEMENT BETWEEN CP TAYLOR AND CP BURBANK JCT. IF DEADHEAD EQUIPMENT BEING HANDLED IS DIFFERENT FROM THAT ADDRESSED ON GTB, CHANGE OF ADDRESS IS NOT REQUIRED.

VERBALLY ISSUED FORM A RESTRICTIONS											
To:	A1	t:	Date:								
RESTRN NUMBER	SUI	BDIV	LIMITS MP TO MP	SPEED PSGR	MPH FRGT	TRACK(S)	AT AT	AGS MP			
COMMENTS	\$:					OK	Dspr				
To:	A	t:	Date:								
RESTRN NUMBER	SU	BDIV LIMITS SPEED MPH MP TO MP PSGR FRGT TRACK(S)					FL AT	AGS MP			
COMMENTS	COMMENTS:OK										
VERBALLY ISSUED FORM C RESTRICTIONS To: Date:											
RESTRN NUMBER	RESTRN SUBDIV RESTRICTION TEXT										
COMMENTS	S:					OK	Dspr				
To:	A1	t:	Date:								
RESTRN NUMBER	SUBDIV				TION TEXT	Г					
COMMENTS											
SIVIIVIEN 18	·					OK	Dspr				
		VERB	ALLY ISSUED	FORM >	(RESTR	ICTIONS					
Eng:	At:		Copied by:								
Observe Rule OKDSP	6.32.2(A)	At				~					
Eng: At: Copied by: Date:											
Observe Rule	6.32.2(A) A	At					-				
Observe Rule	6.32.2(A) A	\t	Copied by:			Date:					
DKDSPI	R			·							

TUESDAY, FEBRUARY 24, 2015

G-COR

1.41 Engines Coupled to Occupied Passenger Cars

Engines coupled to equipment that includes occupied passenger cars must not be left without an authorized employee in charge.

SAFETY TIP OF THE DAY - (AMT-5)

5603 Before starting/energizing 480 volt H.E.P. or power supply on locomotives and/or cars, employees must be made aware that power will be energized and must stand clear of all electrical cables.



Bags and Personal Belonging

In stations and on board trains, watch your bags and personal belongings at all times. Do not accept packages from strangers. Do not allow anyone to leave unattended items with you



24 Travel Options

Remember, passengers chose to travel by train. Make it a great experience for them.