



Hill Aircraft & Leasing Corp

Atlanta, Georgia 30336

Invoice: MAI-18-03741

Opened: 12/12/2018
Closed: 12/18/2018

Sold To: Chen Aircrafts, LLC (MAINT ONLY)
Memphis, TN 38133 United States

Ship To: Chen Aircrafts, LLC (MAINT ONLY)

Aircraft Number:		N188CW		Type:CITATION 560			S/N: 560-0148		
Total Time:		7,419.7	Hobbs Time:		Tach Time:		LG Cycles:		6,124
Eng#	Type	S/N	Time	Cycles	Prop	Type	Prop S/N	Prop Time	
1									
2									

Discrepancy: 1

Discrepancy Status: Completed

Problem:

SERVICE CONSUMABLES
MECHANIC: ZACHERY SCHEIDECKER
INSPECTOR: GERALD HALL

Action Taken:

SERVICED ALL CONSUMABLES AS REQUIRED. WORK DONE IN REF. TO CESSNA 560 M.M., CH 12-00-00.

Charges This Item:

Discrepancy: 2

Discrepancy Status: Completed

Problem:

R/H LANDING LIGHT INOP
MECHANIC: ZACHERY SCHEIDECKER
INSPECTOR: GERALD HALL

Action Taken:

TROUBLESHOT R/H LANDING LIGHT. CHECKED BULB. BULB WAS GOOD. CHECKED WIRING HARNESS FROM WHEEL WELL TO BULB. CHECKED GOOD. CHECKED FOR POWER AND BULKHED. NO POWER. FOUND C/B POPPED IN J-BOX. RESET C/B AND OPS CHECKED. OPS CHECK GOOD. WORK DONE IN REF. TO CESSNA 560 W.D.M CH 33-40-04.

Charges This Item:

Discrepancy: 3

Discrepancy Status: Completed

Problem:

LEFT TIRE CORD SHOWING
MECHANIC: ZACHERY SCHEIDECKER
INSPECTOR: GERALD HALL

Action Taken:

REMOVED L/H MAIN TIRE/WHEEL ASSY. DISASSEMBLED WHEEL. FLIPED TIRE ON WHEEL RE-INSTALLED BACK ON

Hill Aircraft & Leasing Corp

Atlanta, Georgia 30336

AIRCRAFT. WORK DONE IN REF. TO CESSNA 560 M.M., CH. 07-10-01, 32-41-010 AND BF GOODRICH C.M.M P/N:3-1490-1 CH. 32-45-43.

Charges This Item:

Discrepancy: 4

Discrepancy Status: Completed

Problem:

COFFEE DRAWER WILL NOT STAY SHUT
MECHANIC: ZACHERY SCHEIDECKER
INSPECTOR: GERALD HALL

Action Taken:

ADJUSTED DRAWER LATCH ON COFFEE DRAWER. OPS CHECK GOOD. WORK DONE IN REF. TO CESSNA 560 M.M., CH. 25-00-00.

Charges This Item:

Discrepancy: 5

Discrepancy Status: Completed

Problem:

TRIM OVER COCKPIT AND CABIN DIVIDER FALLING OFF
MECHANIC: ZACHERY SCHEIDECKER
INSPECTOR: GERALD HALL

Action Taken:

RE-INSTALLED TRIM OVER COCKPIT. FOUND SCREWS MISSING. INSTALLED NEW HARDWARE. WORK DONE IN REF. TO CESSNA 560 M.M., CH. 25-24-06.

Charges This Item:

Discrepancy: 6

Discrepancy Status: Completed

Problem:

CHECK BAGGAGE DOOR LATCHES
MECHANIC: ZACHERY SCHEIDECKER
INSPECTOR: GERALD HALL

Action Taken:

ADJUSTED AFT BAGGAGE DOOR LATCHES IN REF. TO CESSNA 560 M.M. CH. 52-30-01.

Charges This Item:

Discrepancy: 7

Discrepancy Status: Completed

Problem:

STICK SHAKER INOP
MECHANIC: ZACHERY SCHEIDECKER
INSPECTOR: GERALD HALL

Action Taken:

INSPECTED AND FOUND WIRES SEPERATED FROM CANNON PLUG. RE-SOLDIERED WIRES INTO CANNON PLUG. OPS CHECK GOOD. WORK DONE IN REF. TO CESSNA 560 M.M., CH. 27-32-01 AND AC 43-13-1B PAR 4-88.

Charges This Item:

Discrepancy: 999

Discrepancy Status: Completed

Hill Aircraft & Leasing Corp

Atlanta, Georgia 30336

Problem:

LOG BOOK SIGN OFF

Action Taken:

I certify that the above stated maintenance and/or inspection was performed in accordance with 14CFR91.409(f)(3) per Manual P/N ML-C-560 Rev# 6.1 and is Approved for Return to Service

Signed _____ FOR CRS# ESER686D Date _____

Total For This Discrepancy: \$

Miscellaneous Charges:

Misc Supplies: \$

Summary:

Misc Supplies: \$

Totals:

SubTotal: \$

Total Charges: \$

Did you receive exceptional service from one or more of our employees? Please let us know at _____

Please note that effective June 1, 2016 our shop rates for Piston will be \$110.00 and for Turbine will be \$110.00.