

Real Estate Ltd

7306 N

NAME		ST LOUIS MOBILE PHONE		DATE		8-26-92	
ADDRESS							
MAKE	TYPE OR MODEL	YEAR	RECEIVED	A.M.	P.M.		
BELL	206L	1976					
SERIAL NO	ENGINE NO	PHONE WITH HEADY	PROMISED	A.M.	P.M.		
45034	CAF830141	TERMS					
ORDER NUMBER HERE:	5475.8	YES ☐ NO ☐					
21121	ORDER WRITTEN BY	PHONE					
	W.A. Adams						
ORDER NO	INSTRUCTIONS						

1	Overhauled Tail Rotor Hub Assembly, S/N 206-011-819-05	5
2	Installed New Tail Rotor Yoke, S/N 206-011-819-05, S/N DFC 5484	4
3	Overhauled Main Driveshaft	
4	Installed New Outer Coupling, S/N 206-040-117-005, S/N A-5535	
5	Installed New Inner Coupling, S/N 206-040-117-005, S/N A-14630	
6	Balanced Tail Rotor Assembly To 1 IPS.	1
(See Page 2 of 2)		

	I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and / or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs therein.					TOTAL LABOR	
						TOTAL PARTS	
						ACCESSORIES	
						GAS, OIL & GREASE	
						OUTSIDE REPAIRS	
						TAX	
						TOTAL AMOUNT	

[illegible]

