



[Printer Friendly Page](#)

**Vessel Information**

Vessel	VIN	Hull Number	Flag	Call-Sign	Year Built
NORWAY	5119143		BAHAMAS, THE	C6CM7	1961

**Vessel Particulars**

Service	Length	Breadth	Depth	Alternate VINs	IMO Number
Passenger (6 or Fewer)	978.0 ft	0.0 ft	0.0 ft		5119143

**Service Information**

Service Status	Out of Service Date	Last removed from service by:
Out of Service	6/27/2003	SECTOR MIAMI

**Tonnage Information**

Deadweight	Gross Tonnage (GRT)	Net Tonnage (NRT)	Gross Tonnage (GT ITC)
13960	76049	45886	

**Cargo Authority:**

**Vessel Documents and Certifications**

Document	Agency	Date Issued	Expiration Date
Certificate of Compliance - Passenger Vessel	USCG	May 15, 2003	May 15, 2004
ISM - Document Of Compliance		February 6, 2003	July 6, 2003
SOLAS Passenger Ship Safety Certificate	BF	May 31, 2002	May 18, 2003
SOLAS Passenger Ship Safety Certificate	BF	May 23, 2001	May 19, 2002
International Oil Pollution Prevention Certificate	BF	October 31, 2000	May 23, 2005
Load Line Certificate (Coastwise)		May 22, 2000	May 23, 2005

- [Welcome](#)
- [Vessel Search](#)
- [VSP Status](#)
- [FSP Status](#)
- [Contact Us](#)
- [Links](#)
- [FAQ/Help](#)
- [No Historical Data](#)
- [Quick Jumps:](#)
- [Documentation](#)
- [Contacts](#)

Version 2.3



Classification Document  
 ISM - Safety Management Certificate  
 ISM - Document Of Compliance

BF  
 May 22, 2000  
 September 22, 1998  
 May 6, 1998  
 May 23, 2005  
 April 30, 2003  
 February 28, 2003

[Back to Top](#)

**Summary of Coast Guard Contacts**

Activity USCG Number Zone/Port	Date	Activity Type	Enforcement Incident Description
1816408 Miami Beach, FL	June 13, 2003	Vessel Operational Control	
1796498 STThomas, VI	May 15, 2003	Vessel Inspection/PSC	

**Deficiency Information**

**System**  
 Construction/Loadline

**SubSystem**  
 Penetrations

**Cause**

**Description of Deficiency**

Permanently seal hole in bulkhead near sanitary equipment storeroom fire door C.90

**Due Date**  
 6/15/2003

**Resolved**  
 No

**Resolved Date**

**Resolution Description**

**Deficiency Information**  
**System**  
 Fire Fighting

**SubSystem**  
 Fire Main

**Cause**

**Description of Deficiency**

Make repairs to 7 soft patch areas in Steering gear room

**Due Date** 6/15/2003 **Resolved** No **Resolved Date**

**Resolution Description**

**Deficiency Information System** Accommodation/Occupational Safety **SubSystem** Occupational Safety **Cause**

**Description of Deficiency**  
provide covers for lighting fixtures in gift shop store room.

**Due Date** 6/15/2003 **Resolved** No **Resolved Date**

**Resolution Description**

**Deficiency Information System** Electrical **SubSystem** Electric Generation Source (service) **Cause**

**Description of Deficiency**  
Provide Die-Electric Safety mat at aft utility control panel

**Due Date** 6/15/2003 **Resolved** No **Resolved Date**

**Resolution Description**

**Deficiency Information**

**System**  
Fire Fighting

**SubSystem**  
Portable CO2 Fire Extinguisher

**Cause**

**Description of Deficiency**

Provide evidence that all portable fire extinguishers are receiving the required Flag state/class servicing and companies safety management system reflects these requirements.

**Due Date**  
6/15/2003

**Resolved**  
No

**Resolved Date**

**Resolution Description**

**Deficiency Information**

**System**  
Fire Fighting

**SubSystem**  
Fixed Deck Foam System

**Cause**

**Description of Deficiency**

Provide evidence that fixed foam tanks are within 5-year foam renewal date.

**Due Date**  
6/15/2003

**Resolved**  
Yes

**Resolved Date**  
5/15/2003

**Resolution Description**

Proof of testing provided prior to departure of vessel.

**Activity USCG**  
**Number Zone/Port**  
1749116 STThomas, VI

**Date**  
February 20, 2003

**Activity Type**  
Vessel Inspection/PSC

**Enforcement Incident Description**

1716776 STThomas, VI November 28, 2002 Vessel Inspection/PSC  
 1709246 STThomas, VI November 21, 2002 Vessel Inspection/PSC

**Deficiency Information****System**

Accommodation/Occupational Safety

**SubSystem**

Other Accommodation Spaces

**Cause****Description of Deficiency**

WIRING IN THE DJ BOOTH IN THE CREW LOUNGE IS UNSAT DUE TO NUMEROUS EXTENSION CORDS, EXPOSED WIRES, AND GENERAL CONDITION. WIRES WERE ALL REMOVED AND BEIN ADDRESSED AT EXAMS CONCLUSION. BOOTH NOT TO BE USED UNTIL CORRECTED. LEGACY COMPONENT DESC: Recreation Space

**Due Date**

12/5/2002

**Resolved**

Yes

**Resolved Date**

11/28/2002

**Resolution Description**

Attended vessel and verified satisfactory wiring.

**Deficiency Information****System**

Personnel

**SubSystem**

Training

**Cause****Description of Deficiency**

LIFEBOATMEN UNFAMILIAR WITH LIFEBOAT EQUIPMENT, LOCATION, AND MANUALS. THIS INCL UDES PERSONNEL ASSIGNED TO THE RAFTS. VSL CONDUCTED ON THE SPOT TRAINING AND CREW WAS RE-EXAMINED PRIOR TO EXAM CONSLUSION. RE-EXAM SAT.

**Due Date**

11/21/2002

**Resolved**

Yes

**Resolved Date**

11/21/2002

**Resolution Description**

TRAINING ON THE SPOT.

Activity USCG Number Zone/Port	Date	Activity Type	Enforcement Description	Incident Description
1669996 STThomas, VI	September 3, 2002	Vessel Inspection/PSC		
1631992 Miami Beach, FL	June 9, 2002	Transfer Monitor		
1631804 Miami Beach, FL	June 9, 2002	Transfer Monitor		

**Deficiency Information**  
**System** Communications      **SubSystem** Visual Communication      **Cause**

**Description of Deficiency**  
 Mobile Facility did not have any warning signs posted. Operation suspended untill sign posted.

**Due Date** 6/9/2002      **Resolved** Yes      **Resolved Date** 6/9/2002

**Resolution Description**

Activity USCG Number Zone/Port	Date	Activity Type	Enforcement Description	Incident Description
1621646 STThomas, VI	May 30, 2002	Vessel Inspection/PSC		
1494801 STThomas, VI	March 21, 2002	Vessel Inspection/PSC		

**Deficiency Information**  
**System** Stability      **SubSystem** Watertight Integrity      **Cause** Unknown

**Description of Deficiency**  
 Repair hydraulic leak to manual control on watertight door #4 LEGACY COMPONENT DESC: Watertight do

<b>Due Date</b>	<b>Resolved</b>	<b>Resolved Date</b>
4/21/2002	Yes	5/30/2002

**Resolution Description**  
Leak repaired.

<b>Deficiency Information</b>	<b>SubSystem</b>	<b>Cause</b>
Lifesaving	Embarkation Appliances/Stations	Improper/Lack of Maintenance

**Description of Deficiency**  
Vessel to repair overheads above embarkation doors at lifeboat stations 19 & 20. LEGACY COMPONENT  
DESC: Accessibility

<b>Due Date</b>	<b>Resolved</b>	<b>Resolved Date</b>
4/21/2002	Yes	5/30/2002

**Resolution Description**  
Overheads repaired.

<b>Activity USCG</b>	<b>Date</b>	<b>Activity</b>	<b>Enforcement Incident</b>
<b>Number Zone/Port</b>		<b>Type</b>	<b>Description</b>
1488757 Miami Beach, FL	February 24, 2002	Vessel Inspection/PSC	
583867 Miami Beach, FL	December 13, 2001	Port Safety	
1468681 Miami Beach, FL	December 13, 2001	Vessel Inspection/PSC	

<b>Deficiency Information</b>		<b>Cause</b>
<b>System</b>	<b>SubSystem</b>	Damaged By Earlier Event
Fire Fighting	Automatic Sprinkler System	

**Description of Deficiency**

Make permanent repairs to damage sprinkler feeder next to starboard side shell door. Have class provide report as such. LEGACY COMPONENT DESC: Piping

<b>Due Date</b>	<b>Resolved</b>	<b>Resolved Date</b>
1/30/2002	Yes	1/8/2002

**Resolution Description**

<b>Activity USCG</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
151761	STATEN ISLAND, NY September 5, 2001	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
2024	Miami Beach, FL May 27, 2001	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
28379	STThomas, VI September 13, 2000	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**



Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
29940 Miami Beach, FL	December 23, 1998	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
168493 Miami Beach, FL	June 6, 1997	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
33601 SAN JUAN, PR	February 23, 1997	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
56532 Miami Beach, FL	October 8, 1995	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
83253 SAN JUAN, PR	August 28, 1995	Incident Investigation	Marine Casualty, Reporta

**Incident Information  
Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
149039 Miami Beach, FL	August 12, 1995	Incident Investigation	Marine Casualty, Reporta

**Incident Information  
Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
22742 Miami Beach, FL	July 21, 1995	Incident Investigation	Marine Casualty, Reporta

**Incident Information  
Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
104414 Miami Beach, FL	September 2, 1993	Incident Investigation	Marine Casualty, Reporta

**Incident Information  
Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
104414 Miami Beach, FL	September 2, 1993	Incident Investigation	Discharge of Oil

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
116059 STThomas, VI	April 16, 1992	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
116059 STThomas, VI	April 16, 1992	Incident Investigation	Discharge of Oil

**Incident Information**

**Role**

Involved in a Marine Casualty

<b>Activity USCG Number Zone/Port</b>	<b>Date</b>	<b>Activity Type</b>	<b>Enforcement Incident Description</b>
53481 SAN JUAN, PR	February 12, 1992	Incident Investigation	Marine Casualty, Reporta

**Incident Information**

**Role**

Involved in a Marine Casualty

Activity Number Zone/Port	USCG	Date	Activity Type	Enforcement Description	Incident Description
53481	SAN JUAN, PR	February 12, 1992	Incident Investigation		Discharge of Oil

**Incident Information**

**Role**

Involved in a Marine Casualty

[Back to Top](#)

*Page Created:* 30 August 2000  
*Last Modified:* 23 October 2003

*Disclaimer:* [www.uscg.mil/discclaim.html](http://www.uscg.mil/discclaim.html)  
*Questions?:* [psix@comdl.uscg.mil](mailto:psix@comdl.uscg.mil)  
*Phone:* (202) 267-6889

**Marine Safety Pages:**

[Port State Control \(Home Page\)](#)

[Office of Marine Safety](#)

**Rehabilitation Act (Section 508):**

[Web accessibility concerns?](#)  
[USCG Policy regarding web accessibility](#)  
*Phone:* (202) 366-4648