

Report ID: 24190

PIC: Chris Oldenburg

SIC:

Flight Number: 308

Route: ABY-ECP Flight Date: 12/15/2016

	Risk Value		Flight Value
Crew			
Capt. with less than 100 hrs. in type	3		0
Duty day greater than 10 hours	2		0
Flight time over 3 hours per leg	2		0
Pop up trip (less than 3 hours notice)	2		0
Crew rest less than 9 hours	3	Х	3
Training flight	10		0
Operating Env	ironment		•
Departure A	Airport		
VMC (1000/3)	3	Х	3
Surface winds greater than 20 kt cross	2		0
Mountain Airport	3		0
Wet runway/contaminated	3		0
Braking action less than fair	5		0
Night takeoff	3		0
Convective activity present	3		0
Icing predicted/present	3		0
Visibility less than 1 mile	4		0
Runway less than 5000 ft.	3		0
Arrival Ai	rport		
VMC (1000/3)	3	Χ	3
Surface winds greater than 20 kt cross	2		0
Mountain Airport	2		0
Wet runway/contaminated	3		0
Braking action less than fair	5		0
Night landing	3		0
Convective activity present	3		0
Icing predicted/present	3		0

IMC with precision approach	4		0					
IMC with non precision approach	5		0					
Visibility less than 1 mile	5		0					
Circling approach necessary	2		0					
Equipment								
Ferry Permit	3		0					
Open MEL	2		0					
Passenger Flight	3		0					
Subtotal:			9					
Mitigation								
Crew familiarity	-5	-5	-5					
SIC Aboard	-3		0					
Turbine powered	-3	Χ	-3					
TOTAL:			1					
GO								

Notes:			

Submitted By: Karbowski, Wayne Submit Date: 12/15/2016 03:12