8/15/16

Per research performed by Gordon Stabler, there have been no leaks on underground facilities in the defined incident area in the last 12 months.

Thanks, Katie Harkless

Director- Below Ground Field Operations

12 MONTHS - ABOVE GROUND LEAK CALLS IN THE VICINITY

	Address	City	EXP1	Field	CMPLDP	TIME STAMPS	ACCT	INST	RMK1
	8736 ARLISS ST	SIL SPR	812	2	321	Assigned 1/26/2016 20:54 EnRoute 1/26/2016 21:14 Arrived 1/26/2016 21:20		C#202-531-2143/CLEAR ACCESS /	CHECKED FOR LEAK IN FRONT DOOR AREA, METER BUILDUP, EXPOSED HOUSELINE, NO LEAKS OR ODORS FOUND, PERFORMED SAFETY CHECKS, ADVISED CUSTOMER, LEFT OK
	8541-A PINEY BR RD	SIL SPR	802	2	321	Taken 2/13/2016 12:38 Assigned 2/13/2016 12:39	ODOR AT FRONT ENTRANCE NEAR METERS/EDWIN /C-LUIS/	240.398.9191 C/CLEAR ACC/ CX WAITING AT FRONT	CALLED CUSTOMER AND ALSO HAD DISPATCH CALL,GOT IN UILDING,GOT NO GAS READINGS
	8545 PINEY BR RD	SIL SPR	802	2			ODOR IN HALLWAY/MIKE /C-CLAUDIA/	240-4132643 MAIN ENTRANCE	CKED AREA CUST SMELLING ODOR, APPLIANCES AND EXPOSED PIPES, NO ODOR OR READINGS, NO LEAK AT THIS TIME. NO ACCESS TOT HE MTR
			802	3				GO TO FRONT DESK	FOUND TOP PILOTS OUT ON RANGE HAD TO LET UNIT VENTILATE ALSO WAIT FOR ACESS CHECK ALL OTHER UNITS AND AROUND DOOR AND SERVICE AT BLDG WALL ASST FROM MAITENANCE
tarytand	8644 PINEY BRANCH RD	SILVER SPRING	802	1	321	Taken 8/11/2016 0:10 Assigned 8/11/2016 0:10 EnRoute 8/11/2016 0:10 Arrived 8/11/2016 0:10 Arrived 8/11/2016 0:32 Completed 8/11/2016 6:32		ODOR FIRE DEFT ON	ARRIVED TO FIND BUILDING 8701 TO BE ACTUAL ADDRESS NOT 8644,FOUND BUILDING ON FIRE UPON ARRIVAL,LOCATED VALVE BOX IN YARD,TURNED GAS OFF BY VALVE KEY WIASSISTANCE FROM F- J.RICH,CHECKED AMBIENT AIR IN

	LEGEND					
EXP1	Order type dispatched					
	802- Odor inside					
	812- Odor outside					
Field Priority	Assigned Priority: used to manage emergency response					
	1- Target response time 50 minutes					
	2- Target response time 60 minutes					
	3- Target response time 95 minutes					
CMPLD	Completion Code: used to summarize outcome of order					
	321- No leak found					
	441- Range Adjust / Left Off					
ACCT	Account Remarks: summary of description provided by caller					
NST	Access Instructions: relevant information to assist responder in accessing property					
RMK1	Completion Remarks: comments from responding technician describing findings and outcome					