

ODORANT MONITORING SAMPLE

Version: Effective 3/1/2015

JURISDICTION OF SAMPLE: ☐ DC ☐ VA ☐ MD								
TECHNICIAN'S STATION: ☐ S.E ☐ N.W ☐ S.O.C ☐ FREDERICK ☐ SHENANDOAH ☐ N/A - CONTRACTOR								
Reason for Sampling ☐ Fixed Point ☐ Random Sample ☐ Farm Tap	10400 TONG							
Ø Incident □ Low Odor □ Follow Up □ New Business	Contractor Podes No							
Odorator Serial Number: 2307 - 4 Name: TSN BIGHTMYFL Date of LAST Odorator Calibration: 4-8-16								
No. ODORANT SAMPLING POINT	Odor Recognition			Analysis				
Quad Map, Address or Intersection, City, State	Date	Inst. Read	%GIA	Comments				
1 Quad 8609 FINE & BEANCH RD. SILVER SPRING MD.	8-11-2016 3:45 Ain	-60	,50					
2 Quad								
3 Quad								
4 Quad								
5 Quad								
6 Quad			01					
**Notes:	<u> </u>							
Procedures: Contact Operations Dispatch (703) 750-4831 if the %GIA is greater than 1.0 for samples taken in VA or DC or greater than 0.5 for MD. All low odor conditions should be reported to Operations Dispatch. Procedure: Reference WG O&M Manual Standards Section 4114 for ALL CLARIFICATIONS								
Return these forms by company mail to the "Odorant Monitoring Program" or by fax to 703-750-7513								
Reviewed by:								



ODORANT MONITORING SAMPLE

Version: Effective 3/1/2015

JURISDICTION OF SAMPLE: ☐ DC ☐ VA								
TECHNICIAN'S STATION: S.E N.W S.O.C FREDERICK SHENANDOAH N/A - CONTRACTOR								
<u>R</u>	Reason for Sampling Sampled By							
	Fixed Point 🛘 Random Sample 🗇 Farm Tap	□ WG - Emp. No. <u>1405</u>						
1	Incident □ Low Odor □ Follow Up □ New Business		☐ Contractor - Badge No					
		Odorator S	Serial Numbe	er: 2	307-4			
Name: 150 \$164Fmys2 Date of LAST Odorator Calibration: 4-8-7016								
No			or Recognition	Analysis				
	Quad Map, Address or Intersection, City, State	Date	Inst. Read	%GIA	Comments			
1	Quad UNIVERSITY BUD.	8-11-2016 11:05 AM		.50	REY STATION 424			
2	Quad UNIVERSITY BLVD + SEEK IN.	8-11-2016 11:20 Am	.60	.50	BEG STATION 447			
3	DOTH IN							
4	Quad SILWEL SPRING MD.							
5	Quad							
6	Quad							
*Notes:								
Procedures: Contact Operations Dispatch (703) 750-4831 if the %GIA is greater than 1.0 for samples taken in VA or DC or greater than 0.5 for MD. All low odor conditions should be reported to Operations Dispatch. Procedure: Reference WG O&M Manual Standards Section 4114 for ALL CLARIFICATIONS								
Return these forms by company mail to the "Odorant Monitoring Program" or by fax to 703-750-7513								
Reviewed by Date: 8-11-16								