Attachment 22

Operational Factors Group Chairman's Factual Report

1


DCA00MA030

Warning Systems, Excessive Descent Rates (Mode-1)

-300/-500	Southwest Airlines	Warning Systems
<u>15.2.10</u>	Flight Reference Manual	_System Description

Excessive Descent Rates (Mode 1)

If the aircraft barometric descent rate is excessive, the "SINK RATE" aural alert sounds twice. If descent rate becomes severe, the "WHOOP WHOOP PULL UA" aural sounds. A red PULL UP alert is displayed on both attitude indicators.



1