

DOCKET NO. SA-510

EXHIBIT NO. 2A-2

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.**

**CHANGE TO
OPERATIONS GROUP CHAIRMAN'S FACTUAL REPORT
PAGE 16, PROFICIENCY CHECK RESULTS**



National Transportation Safety Board


Washington, D.C. 20594

January 19, 1995

EXHIBIT 2A-2
CHANGE TO OPERATIONS GROUP CHAIRMAN'S FACTUAL REPORT
PAGE 16, PROFICIENCY CHECK RESULTS

1. Change the sentence that reads: "This represents an unsatisfactory rate for proficiency checks of .0049%." The sentence should read: 0.49%.

2. Change the section that reads: ".76%" to 0.76%.


Charles F. Leonard
Operations Group Chairman