



Photograph # 10 - View of wire strike damage observed on forward skid