

HIGHWAY ACCIDENT BRIEF PHOTOS

Falls Church, Virginia HWY16SH012

(4 pages)



Photograph 1 – Showing the intersection of Leesburg Pike and Glen Carlyn Drive – facing northeast



Photograph 2 – The right southbound traffic lane at crash scene showing debris evidence – facing north



Photograph 3 – Front driver's side corner of Jeep Wrangler showing marks on the left front bumper