## Flight Crew Analyst Incident Report 4598



Event: 1
Baseline Risk Assessment
Likelihood:
Severity:
Risk Factor:
Description
Aircraft Configuration:
Nickname: N572RP
Tail Number: N572RP
Aircraft Type: ERJ
Flight Crew Employee Information:
Primary Duties During Time of Event: Pilot
Flight Information:
Departure Airport, Runway and Gate: CHS/KCHS
Flight Number: 6087
Scheduled Arrival Airport, Runway and Gate: JFK/KJFK
Landing Airport, Runway and Gate: JFK/KJFK
Narrative:
While holding short ( taxiway A, short of Q), Royal Jordanian flight 261 collided with the rear of our aircraft. The Jordanian flight was on
taxiway A moving clockwise on the taxiway. Our last ATC instruction was taxi on A and hold short of taxiway Q. Flight 261 was an Airbus 340
with a wingspan of at least 200ft. Taxiway A width is roughly 75ft
Phase of Flight:
Flight Phase at Start of Event: Taxi-In
Cause
Weather:
Other Weather: Night VMC
Detection
Reaction
Flight Crew:
Requested Emergency Equipment: Yes
Suggestions

WARNING: The information in this document may be protected from disclosure under 49 U.S.C., section 40123 and 14 CFR part 193.

Report generated Mon, 06 Oct 2014 20:59 Z