# TRANSPORTION SARETY BOARD

## NTSB RECORD OF CONVERSATION

Eric Swenson Aviation Accident Investigator Anchorage, AK (Alaska Region)

Date: 03/19/2019

Person Contacted: Flight Instructor (Carlisle Doria)

NTSB Accident Number: ANC19LA015

### **Narrative:**

The following is a summary of a conversation that occurred with the flight instructor

- First time student  $-1^{st}$  flight with her
- She has used the airplane for two private students in the past
- Weather was good
- She let the student taxi to the runway
- Briefed on safety abort procedures
- Lined up on the runway, she was to perform the takeoff and landings
  - Her plan was to do ground reference maneuvers since ceilings were about 2k ft, and fly to willow
- 1<sup>st</sup> takeoff attempt
  - o Added full power
  - o Had condensation appear on windscreen
  - Aborted the takeoff
  - Wiped with her hand verified it was water
- Student was making the calls
- Takeoff was from runway 01
- She had the student do another runup w/carb heat
  - Checked mags
- 2<sup>nd</sup> takeoff attempt
  - o Full power
  - o Her takeoff again
  - Small crosswind
  - She uses a "soft field" style takeoff
    - Yoke back once the airplane starts to fly, push the nose down
    - The nose came up quickly

# TRANSPORT

## NTSB RECORD OF CONVERSATION

- She pushed the nose down
- o Trimmed nose down
- o Rotated about 55-60
- o At about 70-80 the nose pitched up
- o Pushed full nose down the airplane still climbed
- o The student then helped to push the yoke all the way to the firewall
- Power to idle
- o Landed in the trees off the end of the runway
- When she went to turn the ELT off she noted nothing in the back/tail section
- Trim tab was "level/neutral" for takeoff on the elevator
- No snow on the airplane when they had preflighted
  - o The airplane had been hangered and only on the ramp for about two days
- She did not run the trim during preflight to test it
- She believes the airplane had sat all winter until she called in February and then they brought it in to go through before flying it
- They had about 20 lbs in the back seat/storage area
  - Engine cover
  - o Sleeping bag
  - o Stove
  - Winter gear
- There were no engine issues

END	)